
STRUCTURAL REPORT NOTES

REFERENCE SUPPLEMENTARY DOCUMENT - GENERAL BUILDING INSPECTION BY ROBERT WALZ ENGINEERING ON JANUARY 3, 2023

- 1. THE NORTH WALL FACES KERCHEVAL STREET. THE WINDOW SILL IS WOOD THAT HAS DETERIORATED FROM MOISTURE AND NO LONGER PROPERLY SUPPORTS THE SINGLE-PANE WINDWS. THE BRICK BELOW THE WOOD SILL IS BOWING OUT TOWARD KERCHEVAL STREET. THE BRICK CONDITION HAS BEEN REPAIRED ONCE SINCE 2014 AND IS REPEATING THE SEPARATION FROM SUPPORTING THE WINDOWS.
- 2. THE WINDOWS ARE ALL SINGLE PANE GLASS AND ARE THE ORIGINAL WINDOWS INSTALLED WHEN THE BUILDING WAS CONSTRUCTED IN 1925. ALL DOORS ARE THE ORIGINAL WOOD DOOR WITH SINGLE PANE GLASS.



EXIST. WD ENTRY DOOR W/ GLASS, TRANSOM, AND MTL. SECURITY GATE TO BE REMOVED

EXIST. ALUM. STOREFRONT TO BE REMOVED

STOREFRONT KNEEWALL TO BE REMOVED

CONC. BASE TO REMAIN, CLEAN AS REQ'D

EXISTING ENTRY DOOR



- SINGLE PANE ALUM WINDOWS W/ WOOD BLOCKING TO BE REMOVED
- STONE SILL TO REMAIN, CLEAN AS REQ'D
- CAST STONE BASE TO REMAIN, CLEAN AS REQ'D







EXISTING STOREFRONT SILL

EXISTING STOREFRONT SILL



EXISTING ENTRY DOOR



SINGLE PANE WOOD STOREFRONT TO BE REMOVED

- STONE SILL TO BE RESTORED TO MATCH EXIST.
- PRIOR BRICK REPAIR TO BE RESTORED TO MATCHING BRICK AS SPECIFIED

EXIST. WD ENTRY DOOR W/ GLASS, TRANSOM, AND MTL. SECURITY GATE TO BE REMOVED

- EXIST. 1 ' ALUM. STOREFRONT TO BE REMOVED


STOREFRONT KNEEWALL TO BE REMOVED

SINGLE PANE 1.5" ALUMINUM STOREFRONT WINDOWS TO BE REMOVED

1" ALUM STOREFRONT 2X WOOD TRIM TO BE REPLACED

STONE SILL TO BE RESTORED AS EXIST.

MASONRY TO BE RESTORED MATCHING EXIST.





1" = 1' - 0"

EXISTING STOREFRONT SILL





SISTER PIE RENOVATION

1811 Parker St. Detroit MI 48214 1908

OWNER: SISTER PIE LISA LUDWINSKI lisa@sisterpie.com

ARCHITECT: ET AL. COLLABORATIVE OF DETROIT LLC TADD HEIDGERKEN

CONSTRUCTION MANAGER:

th@etal-collaborative.com 313-804-1354

TBD

KITCHEN CONSULTANT: MILIIS AND ASSOCIATES JACQUELYN KEISER jackiek@danmillis 734-458-4775

STRUCTURAL ENGINEER: TBD

MECHANICAL / ELECTRICAL ENGINEER: TBD

SURVEYOR:

ISSUED DATE Historic Commission Review 09/21/2023

APPROVAL REFERENCE NUMBERS:

EXISTING CONDITIONS



- T.O. PARAPET ±16'-8"

T.O. ROOF EXIST. MASONRY TO REMAIN REPAIR AS REQ'D

B.O. SOLDIER COURSE

2x WD TRIM THROUGHOUT WINDOW FRAME. TO BE REPLACED

FIXED SINGLE PANE IN ALUM. FRAMING WOOD CLERESTORY WINDOWS TO BE REPLACED

B.O. CLERESTORY 8'-11"

2x WD TRIM THROUGHOUT WINDOW FRAME. TO BE REPLACED


- SINGLE PANE ALUM STOREFRONT TO BE REPLACED WITH INSUL. DOUBLE PANE GLAZING

SINGLE PANE ALUMINUM STOREFRONT TO BE REPLACED WITH INSUL. DOUBLE PANE GLAZING

2x WD TRIM THROUGHOUT WINDOW FRAME. TO BE REPLACED

EXIST. MASONRY TO REMAIN REPAIR AS REQ'D

INT. FLR 0'-0"



WINDOW TRIM 3" = 1' - 0"

© et al. 2023