2300 Cadillac Tower Detroit, Michigan 48226 Phone 313•224•6380 Fax 313•224•1639 www.detroitmi.gov

July 5, 2012

CERTIFICATE OF APPROPRIATENESS

Fatima Hirji 3280 47th Street, # 112B Boulder Colorado, 80301

RE: Application Number 12-133; 7840 Van Dyke Place; West Village Historic

District

Dear Ms. Hirji:

Pursuant to MCL 399.205(10); Section 25-2-57(b) of the 1984 Detroit City Code; Detroit Historic District Commission Resolution 97-01 (adopted August 13, 1997); Detroit Historic District Commission Resolution 97-02 (adopted October 8, 1997); and Detroit Historic District Commission Resolution 98-01 (adopted February 11, 1998), the staff of the Detroit Historic District Commission has reviewed the above-referenced application for building permit and hereby issues a Certificate of Appropriateness, which is effective as of July 5, 2012.

The staff finds the work appropriate for the following reasons:

The replacement of existing wood windows with new aluminum-clad Kelly windows as outlined in the attached cost estimate dated 5/9/2012 meets The Secretary of the Interior's Standards for Rehabilitation standard number 6) Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence. Please note that this certificate of appropriateness is contingent upon the change in design of the new aluminum-clad Kelly windows so that the muntins more closely match the those of the existing wood windows in profile and style.

Please retain this Certificate of Appropriateness for your files. You should now proceed to obtain a building permit from the City of Detroit Buildings and Safety Engineering Department. It is important to note that approval by the Detroit Historic District Commission does not waive the applicant's responsibility to comply with any other applicable ordinances or statutes. If you have any questions regarding the foregoing, please telephone the Detroit Historic District Commission at 224-6536.

For the Commission:

Jennifer Ross

Staff

Detroit Historic District Commission

copy: Daljit Benipal, B&SE

COLOR		STOCK	UMIL			_	DATE 5-9-12								DEALER				INVOICE		0.5
mb ex		0	Job Name HOUSE					KELLY WINDOW & DOOR MFG 15000 LINWOOD AVE.						ADD. 16870 WESTMORELAND DETROIT MI. 48219				AMOUNT	25,410.50		
		0	ADD. 7840 VAN DYKE PLACE						DETROIT, MI. 48238									TAX 1,493.88			
TRIM O GLASS HPLOW-E STAIN O MFG. KWD		PHONE						(313):861-6910 FAX (313) 861-6925					PHONE 313-535-4200 734-564-0115 PURCHASE ORDER				TOTAL 26,904.38				
																				Date Ship Grill Type > Alumi. Wood	
			QTY		Date Chip	WINDOW SIZES	GR-PAT.						UI	SDL-TOP	HPLOW E	GRILLS- TOP	ALÚM-BA				
RONT								0									NO				
	2	DH	38	X 64	2V1H	102	y 142	Y 115	y 58	y 166					y 25.00	764.00		1,270.00	2,540.00		
			0	X 0																	
-	4	DH	38	X 58	2V1H	96	y 142	v 108	y 58	y 156					y 25.00	672.00		1,161.00	4,644.00		
	-	- Uni	0	X 0	1 -	1															
_		5.1	36	x 48	2V1H	84	y 142	v 74	y 58	y 137					y 25.00	588,00		1,024.00	1,024.00		
	1	DH	0	X 0	20111	100	1 172	1	1 00	1										SUMMARY	
RIGHT	44	BU	38	x 64	2V1H	102	y 142	y 115	y 58	Y 166					y 25.00	764.00		1,270.00	13,970.00	\$25,410.50	Pg 1
_	11	DH	0	X 0	24111	102	1			-											
DEAD			U	^ 0	-	1															
REAR		32200	38	X 64	2V1H	102	y 142	y 115	y 58	y 166		-			y 25.00	764,00		1,270,00	12,700.00	\$25,410.50	Subtotal
	10	DH	0	X 0	20111	102	1 142	1 110	1 00	1,00										\$1,493.88	Tax
				^ 0		+				1										\$26,904.38	Total
LEFT				V 04	0) (411	400	y 142	v 44E	y 58	y 166	1=-				y 25.00	764.00		1,270.00	12,700,00		Deposit
	10	DH	38	X 64	2V1H	102	Y 142	1110	7 36	1 100					-						
			0	X 0		-	440	00	y 58	y 146	_				y 25.00	630.00		1,081.00	3,243.00		
	3	DH	34	X 56	2V1H	90	y 142	Y 80	Y 56	1 140	-			-	1 20.00						-
			0	X 0		-		-	_	-			_	_		-					
						-	-	-	_		-	-	-	_							
					_	+-	-	-	-	 	<u> </u>			_							
						+	-	-	-	-	-	-		-			-				
						-		├	-			\vdash		-	-						
						-		-	-	-	-	-	-+	+							
						-	-	-		-				_		-					_ ~
	_					-		-		-	-	-		-	-				. 1	121	35
						-		-	-	-	-			-	-			. 1	201	121	/
						+		-		-	 	-							10 C 11		
						-	-			_	-						-4	, ,		ACCT.	
				1		-		_	_						-	DIST	COMMI			ACC1.	
								-		-	-	-		-0	MRIC	0131.		CSION	-		
														-4475	10	-	COMMI	2210-	-	//	
						_		_									00.	1	11/		
																-	7	1/1/1/	1		
																	1 1 1 1 1	NINV	γ		
												\longrightarrow		_	-		MAM	1/	ě.	CODE#	
	41						5822	4541	2378	6677					1,025.00	30,378.00	000	00,821.00	50,821.00	TX#24898	
°	OMN.	ENTS:	SPACER LOOKS L	BETWEEN THE SC IKE THERE MIGHT	DL COULD BE A BOX	NOT OUT	SEE WINDO	HAT IF	ANY V	VINDO	WS LEF	TSIDE	CO,	EADST	CUP	AHOO.COM	и	1	5/20	12	

HISORIC COMMISSION SUBMISSION JULY 11th, 2012 Re:7840 Van Dyke Place

SCOPE OF WORK: WINDOW REPLACEMENT

EXISTING WINDOWS ON NORTH, WEST AND EAST SIDE OF RESIDENCE

- The windows do not appear to have maintained in many years and are in various states of disrepair. All of the upper sashes appear to have been painted in place. More importantly, the many layers of paint that have been applied through the years have peeled and exposed the wood to the elements. Refinishing the windows would require removing the sashes from the jambs and sanding off the remainder of the paint. The paint is almost certainly contains lead and will have to be handled appropriately.
- Some of the exterior jambs and sills appear to have been broken and will need to be replaced.
- A number of the existing panes of glass are broken and/or cracked and will need to be replaced.
- Individual sashes have sagged and no longer properly frame the glass panes. These sashes will need to be replaced.
- Glazing is absent from most, if not all, of the windows.
- Many of the sash cords are broken and/or missing. Replacing defective or missing sash cords will require the dismantling of the windows to permit access to the cavity spaces behind the window jambs. Some of the interior surfaces of the window sashes have been damaged.
- None of the windows have screens or storm windows.

*SEE ATTACHED LETTER FROM TREADSTONE LIMTED FOR FULL DETAILS.

PROPOSED WORK ON NORTH, WEST AND EAST SIDE OF RESIDENCE New windows shall conform to the original double hung, 6 over 1 lite architectural design.

The colour shall be white in compliance with the original colour of window trim. New windows are aluminum clad exterior and wood interior Storm windows are included in the replacement.

OPTION 1:Cost to refurbish existing wood windows: \$41,447.00

OPTION 2: Cost to replace existing windows with aluminum exterior and wood interior to match existing architectural style and new screens & storms: \$30,501.00

*SEE ATTACHED BIDS

The cost of replacing the existing windows with OPTION 1 exceeds our given budget of \$25,000 and hence our best option to proceed with the renovation would be to consider OPTION 2.