STAFF REPORT: APRIL 13, 2022 MEETING PREPARED BY: A. DYE

APPLICATION NUMBER: 22-7752

ADDRESS: 15004 WARWICK

HISTORIC DISTRICT: ROSEDALE PARK

APPLICANT: EDWARD PALMER

PROPERTY OWNER: EDWARD PALMER

DATE OF PROVISIONALLY COMPLETE APPLICATION: MARCH 21, 2022

DATE OF STAFF SITE VISIT: MARCH 23, 2022

SCOPE: REPLACE WOOD WINDOWS WITH VINYL WINDOWS

EXISTING CONDITIONS

Erected circa 1935, this two-story house was designed with minimal, yet prominently placed colonial revival details, including a symmetrical placement of window and door openings, keystones above the first-floor window openings, and a front entry flanked by pilasters and topped with a highly sculpted broken pediment. The windows on each elevation are double-hung units with a six-over-six glass pattern; the front elevation first floor window openings are larger than the others due to wood panels below (which are currently obscured by shrubs).



Staff photo, March 23, 2022

PROPOSAL

Remove 12 true divided-light wood double-hung windows (six-over-six pattern). Install 12 vinyl double-hung windows with between-the-glass grids (six-over-six pattern).

STAFF OBSERVATIONS AND RESEARCH

- The Rosedale Park Historic District was established in 2007.
- Vinyl windows on the north and south side elevations likely pre-date the Rosedale Park local historic

district designation as a 2009 Google street view image shows the south elevation vinyl windows in place. All four of the windows on the south elevation are vinyl double-hung units; two of the six double-hung units on the north elevation have been replaced. This application encapsulates the remaining wood windows on the four sides of the house at the first and second floor. The window excluded from the application is the small wood casement/fixed window in the attic on the north side elevation.

ISSUES

- The applicant states the original windows are suffering from condensation that is trapped between the storm and wood sash, and that he has attempted to maintain the windows. The windows do not appear to be highly deteriorated, likely in part to the owner's proactive care. The condensation may be caused by storm windows that do not have weep holes (or that the weep holes have been covered with caulk), whose purpose is to prevent/minimize moisture from being trapped against the window sash.
 - o It is possible the wood windows can be repaired by an experienced window repair company, and the installation of better fitting storms that offer weep holes may not only take care of the existing problems, but may offer greater thermal insulation than new plastic window framed units.
- The applicant expresses his wish for uniformity of window openings. There are 19 windows on the house, and only six are vinyl. The architectural integrity of the house is better served to retain the wood windows and eventually replace the vinyl windows with wood (true or simulated divided light) units once they inevitably deteriorate.
- Vinyl windows are not appropriate for historic houses, as the level of detail of a true-divided light window can not be matched by current vinyl production methods. Even though the storm window on the wood unit partially obscures the dimensionality of muntins when looking at the window from a distance, once up close, the dimensionality is noticeable and retains equal dominance with the profile of the wood brickmold. The vinyl window frame is boxy and flat, and makes the window sash look even more recessed. Additionally, the muntins of the vinyl unit are flat and in shadow, as they are recessed behind the glass. They add very little to the definition of the window unit and window opening.



Applicant photos



The Wallside window contract states each new window will cost \$1669. Staff believes the professional repair/restoration of a 34" x 53" double-hung window with wood muntins, and the installation of a new storm window would likely be less than the price of the vinyl window. The repaired units will offer a much longer lifespan through continued maintenance and repair. Repair is not an option for vinyl windows due to the totality of their fabrication, therefore they will need to be replaced, and then replaced again.

RECOMMENDATION

Section 21-2-78, Determination of Historic District Commission

It is staff's opinion the replacement of the existing wood windows with new vinyl windows will alter the features and spaces that characterize the property. Staff therefore recommends the Commission issue a denial for the work as proposed because it does not meet the Secretary of the Interior Standards for Rehabilitation and the Elements of Design for the district, specifically Standards:

- 2) The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 6) Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
- 9) New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.














To the Historic District Commission:

I am the homeowner of the aforementioned property. I have entered a purchase agreement with Wallside Windows for the replacement of 12 windows at my residence. At the time I entered the contract for purchase I was unaware of the process or requirements of the HDC nor detailed explanation needed for the much needed upgrade to my home. It is my will that this humble attempt at explanation is enough to convince the HDC that we may proceed with upgrading my home with energy efficient windows is a worthy cause.

As laid out by a phone conversation as well as email by Brendan Cagney, it comes to my understanding that the Historic District Commission always advocates for repair instead of replacement with regard to historic age windows. It is my intent to show that we have just cause to replace the rest of the existing wood windows with modern, energy efficient Vinyl windows that would match the windows already replaced to the north and south of the dwelling. The replacement of the proposed 12 windows will give the home a more consistent look since the windows to be replace have multiple different type of storms consisting of different material and do a poor job of insulating the home. As you will be able to see from the pictures I have attempted to keep up with maintaining the state of the wood windows with varying levels of success. This winter it has become apparent to us(the homeowners) that the amount of condensation that is trapped between the storms and windows as well as moisture that developes on the panes is the source for mold to accumulate. This is in contrast to the existing double pane with the grills in between the glass vinyl window that displayed no such condensation or mold growth. The proposed windows will have the same dimensions as the existing windows and as such we will be leaving all the original wood moldings on the interior of the home.

Photos - PDF or JPEG:

Photos











*Notice on the above elevation pictures the improved appearance of the updated vinyl windows that have the colonial grills.



6. Bathroom Window
Has major chipping of
paint. Caulking pulling
away from brick exterior.
single pane glass with bad
glazing. No glass storm for
lower 1/2. Condensation
that pools on interior as
seen in the detail picture to
the right.







Windows 9 and 10 I refinished the exterior During the Covid shutdown period in 2020. The grills glazing is chipping and lifting. The storm is a white aluminum. One of the many styles of storm mix matched across the



Interior view of 9 and 10 although may look ok in this photo they also suffer from moisture pooling on sills and has mold growth. Windows 8, 9, and 10 all have a screen insert as well as glass storm system which is the white aluminum and have faired the best in the existing wood windows because of it.



8. exterior view rusting frame and fasteners



8. interior view also pools moisture



8. interior detail view. notice cracked pane and moisture





11. Kitchen Sink window This is another window I have attempted to repair. This lower glass portion of this storm is missing and therefore deals with a lot of moisture pooling. The interior of this window was painted in 2021 with a high quality latex paint and it still has visible mold on the lower sill when you zoom into the photo. The sound of the wind is pronounced at this window and we fear is a major point of escaping heat and energy loss.







12. Kitchen half bath ext. detail



12. Kitchen half bath interior

These photos are a good demonstration of my best attempt at repairing the grills and properly repairing the window glazing. As you can see from the interior photo that the moisture that collects inside still damages and molds when left unchecked even for a short amount of time. Interior and exterior was painted at the same time. We do not lift up the blind on this window and was shocked to see this current state. Notice and make note of the bare aluminum storm window.







In this set of 2. Dining Area Window photos to the left you will notice the third style of storm window. There is only 2 of this style of storm in the home, here and found in the Living Room. These windows have shown very little moisture on the interior sills. I would attribute this in all most likely hood to have had caulked the storm shut when I repainted the exterior.

2. Dining Area Exterior, Dining Area Interior, and Dining Area Interior Detail (L to R)









1. Family Room Exterior, Exterior Detail, Interior and Interior Detail








4. Upstairs Bedroom 1 Exterior, Interior, and Interior Detail.


*Note Storm is missing completely from this window and lets in a massive draft. In the exterior photo you can notice fresh window glazing that is unpainted due to weather temp dropping last year before we could complete the restoration of the panes. Major mold growth this year discovered at time of taking these photos.





4. Bedroom 1 Exterior, Interior and Interior Detail







5. Upstairs bedroom 2 Exterior and Interior.





7. Upstairs bedroom 3 Exterior





5. Current Vinyl double pane, insulated, double hung with internal muntins

Scope of proposed work for approval

- *Replace 12 Windows
- *Material Used Vinyl
- *Double Hung
- *Window color and trim white
- *Muntin Count 3/2
- *Full Screen installed
- *Energy efficient Low-E glass
- *Double Pane
- *Colonial Style

7	SWallside ARS Windows	Customer#	Name(s): E Lu	1.00	D	CON	TR	(B) Job	Location			MADE IN MICHIGA	THE OUSCOME A	grees to pay the tot	tal sum of:	te License # 00	621
	IN DO THAT. WE ARE THE FACTORY:	Promotion 50%	Address: 1500	I WAL	ZWICK	34	-	Name:		_			As follows: Upon Signing	Z800		CK, CC, C	ash
2700 Taylo	00 W. Trolley Industrial Dr. or, MI 48180	Cidina #	old.		01, 0 - 0 1	Ζір. υ ε	25	Address		Ot.	7!	_	COD on measure	Or .		OV 00 0	nah
Phor		Appt# 626	Phone #2: 313-5					City: Jobsite #:		St:	Zip:		COD on windows			CK, CC, C	ASH
Fax:	313-292-4504 v.wallside.com	Proofed By:	/ Email: LUCING			1		-	ble For Measure: PL	KALA (All to	ch=Ode	-				
0	Total Windows/DW Removed Job nary Total Windows/DW Installed:	12	Window Color: In WHITE O	1011 WHHE	hitial &	Ride Siding Muntin	ers	Measure Ma	ure info n:		Condo In		Bank financing/ot				
_	Doorwall Handle Color:	Sill Size	Glass: Low 6 61	A55	mindi. M	lider Disclain	mer Casen	Measured By	Miscellaneous	Na Na	me:		Bank Name:	Sills /	inance Term:	1	7
Worl Orde	r /		5 - Year Glass Breakage Warranty	D.H. TIII (C/O)	window e down	1.10	Awmin	130 13	1001	(Both)	Glass (Munitin County	7	House Type House	1 2 1 1	Pan Remova;	After Opening Type of Removal	
TIM	Finished Size		Location	1-1-	+	18	1	13/18/		1		- 9		1 2 2	200		
1	2 * 9 1 d h L	27-47	Family Doon	X	4-846		4 × 2		F	Mw	3/2-3/2	X	ho		X	W	
2	-		DINING ROOM	X					F	1/3	1)	X			X	W :	2
3	1 4 4 4 4 4 A 4 A	FRENCH	4 Gollin O	X			964	1.184	E	и	U)	X			X	W 3	3
4			up BED Em	×					F	White	3/2-3/2	X	No		X	W	1
5		3 7 1 1	6 600 Rm(2)	×	3110			ENST	F	i)	V	×	2		X	W!	5
6			up Both Room	×					F	u	3 ⁴	(ex) X			X	W	ò
5 6 7		1650	up Bollen O up Bollen O up Boll Rune up Boll Roon up Boll Roon up Boll Roon	X) = y	33/14	F	ULITO	3/2.7/2	X	No		X	W	,
8			Kitchen Anen	×					F	u	Ŋ	×			X	W	В
9			KHOLOU ANGA	X		112	110	rite.	F	M	ų)†	X		THE P	X	w!	3
10			Kitchen Anea	x					F	WA HO	3/2 3/2	X	NO		X	W 1	0
0	Sales Comments	D63015	Measure/installer	Comments	Bo	Office Use Only		ic solicitation the third bus Additionally, 3-business-c All jobs MUS prior to the i	ERMS AND CONDITIONS: n at your residence, and iness day after the date the seller is prohibited lay period in which you T be measured 14 days	1. Purchased I if you sign to of this trans I from having can cancel to prior to the preer is responsi	r's Right to Can his agreement action. See the an independent ne transaction. comised installa	cel. Under Mich at your resider e notice of cam ent courier serv tion date, other g and reInstallin	igan Public Acts of 1971, N ce, then you, the purchas rellation form on the back ice or other third party p vise the installation date w g alarms and window treat	er, may cancel this trans of your copy of this agr lick up your payment at MORE TERMS ill be rescheduled, Furthe	saction at any time reement for an expla t your residence be IS AND CONDITIC er, changes must be	personal or telepher prior to midnigh lanation of this riefore the end of ONS ON BACK	ight.
_			Construction review required.	red 🗆 Yes	90	NAT 26824-2		Accepted By	7.07				Installation Date	tunsibali	July 14th	PAGE of _ REV. 0	Z . 5/19

			Date: / /	13/22 A	Customer Inf	iormati	ion F	PC []			CO	NI	R	A C	T				JAAA SUDE	K	4	*							S ^c	tate Lice	ense # 00	621
,	7		Customer#		ne(s): EDu	- M A		۵٫	j					0	Job	Locatio	п		7	5)-	MAN	E IN	(Fir	nancial	Terms	CC	כ					
	YEAR	Windows	Job#	Nam Nam	lean	3412		I K	1CW	EN	_		-	Nar					MA	44	MIC	HIGAN	The Cu As follo	stomer	agrees	to pay	the tot	al sum	of:			_
		DO THAT. WE ARE THE FACTORY:	Promotion 90%	1006 -1790 Add	Detro	1 11	JAN	WIC	16	51		130.10		-								_	Upon S			1		0	27	Ck	K, CC, Ca	ash
	27000 Taylor.	W. Trolley Industrial Dr. MI 48180	Siding #	City:	- Detro	726		Si	t: / V	1,	Zip:	116	43	-	dress:								000			51	68	PK	30	CO.		
	Phone:	MI 4818Ó 313-292-4400	Appt # 626		ne #1: 313・									City		-			St:	Zip:		_	COD or			1	-1			CK	CC, CC	ash
	Fax:	ee: 800-521-7800 313-292-4504	Proofed By:		ne #2: 313										site #:			~	e ^y	1			COD on		VS		->					=
	www.w	allside.com	Date		il luc									Tim	e Availa	ble For M	easure:(-المام	to S	hoou	5-		COD OI	Slullig								_
	① Jo	Total Windows/DW Removed:		Window Color: In	WHITE !	Out LL	141	6	Injtiei.	3/	O	Rider	S			ure Info			G) Condo In	ıfo										-	_
	Summa	Total Windows/DW Installed: Doorwall Handle Color:		Trim Color: Glass: Low	WH.76	#_	200	3	Initial:	X	出	Siding C /Juntin/S	J Alter Specialty er	Meas	sure Ma				-				Bank fir	_	other				_	_	_	_
	_	/ Stop Size /	Sill Size	I lass:	O DA	>>	1	1	II III I I I I	Stider		7	er Caser		sured By		Date: ellaneo	/ /	Nan	ne:Glas:		-	Bank N		Len	7	FI	inance			1	7
	(i) Work	J Stop Size	JIII SIZE	100	Year Glass	/	0	Dout.	1	1			Jasen	1	1	13	and I	Jus /	1	1		1	House		Sills	-	21	Instr	ruction:	-	ieno	/
	Order		/	Breakage	e Warranty	1	Picture (C/O)	1	End Vie	Center	Single (Hin.	Douth	all line	Picture Win	Specially/Garden	B.L.	Ben	2/2	2/3	Muntin Count	Temp. (Botha)	/3	Frame (Sided)	1 3	100	LOCK	Buck	10/	Outside 1	Alter Openion	of Remov	
				463		1	Ctime	Doub	End	ente	The Hall	00	Awnin	ure !	dieth	Dogwall R.	15/2	18	Muntin	min	No.C	Briss	Ime	Block	Woon	Extension ,	Wood Bu	Pasifi B	Outside 1	10%	100	
-		Finished Size		Location	on	10	10	/_		0	Sing			Pici	Sper	188			120	M	100		18/	1	In In	13/	2	100	100	14/	/ype	
	1	THE THE STATE OF		Kitchau	Siuk	X	En			4-16	13					135	F		white	3/2-3/2	3	×		No					X		w 1	ı
	2			Kitcher	Yz both	×								A.			F		White	3/23/2		×		NO					×	1	W :	2
el.	3	ALEGER AND		1 250	33 (3)	10		6	- 2					60 00	640	. = 3	x 0		- 2						1						3	3
by lev	4																															4
Please group windows by level.	5	274-134 80		WE KE	J = 863				13		Ta		1.7		11	111	73		1.4		()	1.6					570					5
niw dr	6										V											-					+	1		+	- 6	-
e grou	7	124 517 98	1777	35 60.	1158		7 6	17.1	14.37		130	- 7			y,	·												7	- 1			_
Pleas	8	11010111		97.32				W 193	12.93	N-8												-							0 A	- 1	-	_
	9		-300	W. 1857	W 100 m	The same	V-TI	1 1	(ray		,																-			+	3	-
	-			K and	8221-8	1		No. 1		2-3				3.3	7-1	123											-				9	-
ن	10			7 -																											10	_
	U Sa	25mas All	Dobais	_	sure/installer	Comm	ients		-	Office	O USE	AFE		ic so the t Addi 3-bu All ji prio clea	olicitatio third bus itionally, isiness-c obs MUS r to the i	n at your r iiness day the seller lay period IT be meas	esidence after the is prohil in which ured 14 d date. Cus I haul aw	e, and if y date of t bited from you can lays prior stomer is	rou sign the this transar method having cancel the rothe programments.	s Right to Can is agreement iction. See th an independe e transaction. mised installa le for removin	at your re e notice of ent courie tion date, g and reins	sidenc f cance r servio otherwi stalling	e, then you, ellation form se or other t se the install	the purch on the ba third part lation date window tre	aser, ma lick of you y pick up will be r eatments	y cancel ur copy of your pay MORE eschedule . New inte	this trans of this agree of the	saction a eement f your res S AND (er, change is not pai	at any tim for an ex sidence I CONDIT les must t	ne prior to planation before th FIONS O be receive	o midnigh n of this ri he end of DN BACK led 14 days	t on ight. the
					tion review required.	red 🗆 '	Yes	N ₀	10	CE	PTIFIET NAT 268	FIRM			nt Name: cepted By	LOH	Av	30	STIM	a	Purchas	er(s):(Sin		tallation	Thur	45	July	14	1h	PAGI	REV, O	5/19

DATE 1/13/22

27000 West Trolley Industrial Drive, Taylor, Michigan 48180 Phone: 313-292-4400 Toll Free: 800-521-7800

NAME LUCINDA PAL	MER EDMON	ADDRESS 15	ioog Warwid	c St Detr	ioit, m: 48223	4
TELEPHONE# 313-4			LEAD# <u>626</u>			
TYPE OF REMOVAL		MUNTIN SIZES MUS ED IN BELOW	EMAIL LUCIN	Dapalmen S	2 gmail. Com	-
ALUMINUM STEEL IN BLOCK			EXTERIOF	BRICK BLOCK	WOOD □ ALUMINUM □ STEEL □	
WINDOW COLOR	3			•	YEAR BUILT 1935	

TRIM	COLOR						YEAR BU	IILT <u>1935</u>
LOCATION	STYLE	SIZE	SILLS	LOW E REG OR PREM	MUNTINS	BUCKS OR EXT JAMBS	MISC	TOTAL
1 Diag	04	34×53	3/2-3/2				1669×12	20,028
2 h	Ŋ	3465	ν			TEM	" 115x 2	230
3 8 0	Ŋ	ν	11					20,258
48n0	1	H	N			. ,		-50%
5 8 2 2	ŀ	3403	r		(F	141 p	oths /	10,129
6 pton	tv.	27253	3/2-3/2	164		FILLE	sni nouth	- 18%
7 kitan	DN	34453	3/2-5/2				,	8305
8 11	И	M	ท					
9 v	N	٦	V			V3 DOWN		
10 KACh	1	28x 45	72-3/2			*2800		
11 Bot	М	ZYYUT	312-312			BALANCE O	· Constation	
12 p 5 to r	94	34×13	312-1/2					
13								
14								
15								
16				A Comment				
175m2	610 NO-	98263		4775				
18 Su A	PAID	36x63		2018				
19 🗸	PW	55×63		1861				
20 🕶	CAJE	36×63		2017				
21 Surp	pm	24x63		1361				
22				12,033				
23				-50%				
Sale				6016				
Siding				-18010				
Trim				84933)				
Gutters & Downs								

W107 12/17

GRAND TOTAL_



Energy Efficiency for **Your Home**.

Wallside Windows' Low-E Glass helps your home stay warm and cozy during the Midwest winters by blocking heat loss to the cold weather outside and reflecting heat back into your home. In the winter, the warm glass surfaces also means the relative humidity of the indoor air can be controlled and maintained properly, helping you better manage condensation on windows. And, in the summer the low U-Factor blocks heat gain from the hot weather outside and provides superior insulation. In short, our Low-E Glass can save energy year around and protect your home.

Window Energy Performance

Typically, 75% of the exposed surface of a window is glass, which makes the glass such an important part of a window's performance. All Wallside Windows meet the updated EnergyStar® Version 6.0 requirements in the Northern Climate Zone.

cfm/ft²

Coefficient



Southern



ar Heat Gain	U-Factor	Air Fill	Window
3	0.27	Argon	Casement
0	0.29	Argon	Double Hung
0	0.30	Argon	Double Slider
		Argon	Complete Control

Energy Star Version 6.0


Climate Zone	U- Factor ¹	SHGC ²	
Northern*	≤ 0.27	Any	Prescriptive
	= 0.28	≥ 0,32	-
	= 0.29	≥ 0.37	Equivalent Energy Performance
	= 0.30	≥ 0.42	Performance
North- Central	≤ 0.30	≤ 0.40	
South- Central	≤ 0.30	≤ 0,25	Air Leakage ≤ 0,3
Southern	≤ 0.40	≤ 0.25	1 Btu/h ft²-'F 2 Solar Heat Gain

Climate Zones



High Performance and Durability

Wallside Windows provides the most durable, longest lasting insulated glass available for your home. The spacer between the panes is designed with a corrugated shape that adds strength and bent corners – not notched or open joints – to create a continuous impermeable metal barrier around the entire perimeter, keeping moisture out and insulating argon gas in. Altogether, our insulated glass units achieve the window industry's lowest failure rate giving you peace of mind knowing your windows will not fail in your home.





For more information, please visit

www.wallsidewindows.com

800.521.7800

MI: 313.292.4400 OH: 419.292.4400

27000 W. Trolley Industrial Drive Taylor, MI 48180



A proud partner with





SINCE 1944

Wallside Windows

WE CAN DO THAT. WE ARE THE FACTORY."



1-800-521-7800 | wallside.com



to open. These windows open from both the top and bottom, and tilt inward for easy cleaning.

All Wallside windows and doorwalls are available in 4 interior and 5 exterior colors, with multiple glass options.

Easy To Clean From Inside Your Home





GLASS OPTIONS

- · Double or Triple Pane
- Tinted Bronze or Gray
- Obscure Glass
- Grids Contour, Flat or Etched (see next page)

"Excellent service. They did 19 windows in my house and it only took 5 hours. I thought that was awesome. Excellent salesman also."

- Suzanne C., Dearborn, MI

Wallside Windows **FEATURES & BENEFITS**

- · Foam Filled Frames
- · LowE Glass with Argon Gas Filling
- High Performance Stainless Steel Spacers
- Dual Weatherstripping
- . Double Wall Frame for less Roll
- Full and Half Screen Options
- · Reinforced Sashes as Needed
- Safety Latches
- Metal Cam Action Locks and Keepers

WARM-EDGE STAINLESS STEEL SPACER

1. Primary Seal (PIB) POLYSIOBUTYLENE

Minimizes moisture permeation, increases UV resistance and has one of the lowest argon


Secondary Seal
 Specially formulated silicone that provides long-term adhesion.

Spacer

Stainless steel spacer that features a roll form design that adds strength to create an impermeable barrier to keep moisture out.

4. Desicants

Molecular sieve creates a frost point below -85 degrees F. Provides optimal moisture adsorption.



WINDOW FRAME COLORS

*Colors are approximate. Please ask your sales rep for more details.

EXTERIOR









INTERIOR









25 Exterior Trim Colors Available


EXTERIOR TRIM **CHOOSE FROM 25 COLORS**

















FlexScreen installs in our Double Hung, Sliding and Casement style windows with nearly no effort.


- SIMPLE DESIGN
- EFFORTLESS INSTALLATION
- DAMAGE RESISTANT
- BEAUTIFULLY INVISIBLE

FlexScreen hides in the window screen pocket, drastically improving sight lines and eliminating the need for color matching. Your windows will never look better.

This revolutionary design utilizes a PVC coated, high-performance spring steel frame. However, innovation does not need to be complex, so you will not find unnecessary attachment hardware.

"Customer service is above and beyond."

Karen H., Grand Lodge, MI



Wallside Windows also offers a wide range of custom glass designs. Ask your Sales Representative for details.



Wallside Windows Are Guaranteed For 35 Years

Few companies take care of their customers year after year like Wallside Windows does. If there's ever a problem, just give us a call or send us a message. We'll help you resolve it over the phone, or we'll schedule a service visit to your home.

OUR GUARANTEE:

- STAYS IN EFFECT 35 YEARS, EVEN IF YOU SELL YOUR HOME, WHICH ADDS TO ITS RESALE VALUE
- COVERS YOUR WINDOWS AGAINST SEAL FAILURE
- FREE PARTS AND LABOR FOR ALL COVERED ITEMS