

4545

architecture

October 05, 2020

7949 E. Lafayette St.
Detroit, MI 48214

RE: 7949 E. Lafayette Residential Exterior Renovation, Historic District Commission Submission

Tree Removal

- a. Remove (3) trees along the rear property line.
 - Two trees are located at the Northeast and Northwest corners of the building, close to the foundations, between the building and the north property line. Since the building sits so close to the rear property line, these trees inhibit access to the rear of the building and to the exterior stairwells that provide access to the basement.
 - A third tree is a small Ohio Buckeye tree to the East of the building. This tree is behind, and dwarfed by the large, character defining Oak tree that is planted in the center of the yard to the East of the building.




Tree at Northeast Corner of Building (view from South)

4545

architecture



Tree at Northwest Corner of Building (view from Southwest)



(View from Northwest)

4545

architecture



Ohio Buckeye (view from South)