

## Description of Siding Repairs at 2489 Atkinson Street

Removed existing cedar shake siding at 2<sup>nd</sup> story wall above rear porch and replaced with new primed cedar lap siding, installing housewrap prior to siding install.

Replaced existing rotted window trim with new pine window trim.

Flashed and caulked per standard industry specs.