

# FIRE DAMAGE PHOTOS



FEBRUARY 21, 2018



FEBRUARY 21, 2018

# HISTORIC PHOTOS



Photograph from the *Inland Architect and News Record*, Volume 38, No. 3 (October 1901)

AUGUST 1971



APRIL 1980



OCTOBER 2010



# EXISTING CONDITIONS



EAST ELEVATION (SEMINOLE AVENUE)



NORTH ELEVATION (EAST LAFAYETTE BLVD)





WEST ELEVATION (ALLEY SIDE)



SOUTHWEST VIEW



SOUTH ELEVATION



STUCCO DETERIORATION AT SW CORNER OF BUILDING



STUCCO DETERIORATION AT WEST ELEVATION, FIRST FLOOR



STUCCO DETERIORATION AT SOUTH ELEVATION



STUCCO DETERIORATION AT EAST FACADE



STUCCO DETERIORATION AT NORTH FACCADE



STUCCO DETERIORATION AT NORTH FACADE





WINDOW #33, 34, & 35



WINDOW #39



WINDOW #6



GAPS IN STRUCTURE CAUSED BY STUCCO WEIGHT



GAPS IN STRUCTURE CAUSED BY LOADS PLACED ON WALL BY THICK STUCCO OVERCOAT. WINDOW #8.

