Porch Rebound in the 1990's

I received these pictures from the previous owner (Cheryl Huff). She rebuilt a large section of this porch in the 1990s. There are some scanned images of the rebuilding of the porch. As you can see – nothing is up to historical accuracy, or code.









Columns – Round vs Square

These the original columns to the house.



Locations of the rounds on the porch.





Square Columns:

Here is one of the square columns that is currently sitting in my font yard. You can see that is only made of 1x4 boards and is starting to rot at the base.








Rotting of the porch. As you can see that is actually part of the house so with out taking a significant part of the porch to begin with, I am not sure how we could fix this.



You can see from this picture the framing was done incorrectly in the (1990s). Instead of replacing they just added boards onto each other.



This was from earlier this year where I had to do temporary fix because the wood had gotten so rotted.



Not that I am that worried about the skirting at this point but as you can see the "decorative" Victorian that was added.

