

Existing Pictures

Foundation:

Original brick piers: you can see from this pic that they are angled and are off centered



Here the pier is missing.



Here you can how bad the right side of the porch is off from the rest of the porch. We have estimated that is it 8" lower than the other part of the porch



For the pillars:

In this picture you can see the pillars have no bases, are not connect to porch and are rotting at the base





Here you can see the columns are leaning and rotting. There are no base for the columns, so they are not attached to the porch. The center column on the south elevation is not connected to the roof .

Stairs:



You can see from the pictures the stairs are not to code missing handrails, risers at different heights, bricks use to level the stairs.



Skirting:



Rotting Wood:







