

City of Detroit Historic District Commission



Figure #01: Exterior, North elevation, Looking South. 06-08-22.



Figure #02: Exterior, West elevation, Looking East. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI

City of Detroit Historic District Commission



Figure #03: Exterior, South elevation, Looking North. 06-08-22.



Figure #04: Exterior, East elevation, Looking West. 01-17-22

Red Arrow Lofts
1567 Church, Detroit, MI

City of Detroit Historic District Commission



Figure #05: Exterior, North and East elevations, Looking southwest. 01-17-22.



Figure #06: Exterior, North and West elevations, Looking southeast. 01-17-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #07: Exterior, Typical Roof Condition, Looking East. 03-31-22.



Figure #08: Exterior, Typical Roof Condition, Looking East. 03-31-22.

Red Arrow Lofts
1567 Church, Detroit, MI

City of Detroit Historic District Commission



Figure #09: Exterior, Window Detail, Looking East. 01-17-22.



Figure #10: Exterior, Window Detail, Looking East. 01-17-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #11: Interior, Typical Window on North elevation, Looking North. 06-08-22.



Figure #12: Interior, Typical sash joinery detail on window, Looking North. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #13: Interior, Typical sill and sash condition on South elevation windows, Looking South. 06-08-22.



Figure #14: Interior, Typical sill and sash condition on South elevation windows, Looking South. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #15: Interior, Typical Window on West elevation, Looking West. 06-08-22.



Figure #16: Interior, Typical sash joinery condition on West elevation, Looking West. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #17: Interior, Typical Windows on West elevation, Looking West. 06-08-22.



Figure #18: Interior, Typical sash joinery condition on West elevation, Looking West. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #19: Interior, Typical sash and sill condition, Looking West. 06-08-22.



Figure #20: Interior, Roof Monitor Windows, Looking West and Up. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #21: Interior, Detail of Roof Monitor Window Condition, Looking West and Up. 06-08-22.



Figure #22: Interior, Roof Monitor Windows, Looking Southwest and Up. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #23: Interior, Typical Sawtooth Skylight Windows, Looking North and Up. 06-08-22.




Figure #24: Interior, Typical Sawtooth Skylight Windows, Looking North and Up. 06-08-22.

Red Arrow Lofts
1567 Church, Detroit, MI

City of Detroit Historic District Commission



Figure #25: Exterior, Historic Image, Looking southeast. 11-23-1942.



Figure #26: Exterior, Historic Image, Aerial Looking South. 1959.

Red Arrow Lofts
1567 Church, Detroit, MI



Figure #27: Exterior, Historic Image, Looking southeast. 1976.

Red Arrow Lofts
1567 Church, Detroit, MI