

#	FRAME SIZE		OPERATION	EXISTING CONDITIONS						NOTES
	WIDTH	HEIGHT		FRAME	SASH	SILL	GLAZING	PAINT	HARDWARE	
FIRST FLOOR (CAFE+BIKE STUDIO)										
1.1	2'-10"	6'-0"	DOUBLE-HUNG							MISSING RAIL STOPS, MISSING ROPE/WEIGHTS/PULEYS, FILM ON GLASS, INOPERABLE SASHES
1.2A	4'-3"	1'-11 1/2"	FIXED/TRANSOM						N/A	
1.2B	4'-3"	3'-11 1/2"	FIXED						N/A	FILM ON GLASS
1.3	2'-10"	6'-0"	DOUBLE-HUNG							MISSING ROPE/WEIGHTS/PULEYS
1.4	2'-2"	6'-0"	DOUBLE-HUNG							FRAME DISTORTED, SASH ROT, MISSING STOPS AND HARDWARE, MISSING ROPE/WEIGHTS/PULEYS
1.5A	2'-10"	1'-11 1/2"	FIXED/TRANSOM						N/A	REPLACEMENT/NOT ORIGINAL SASH, FRAME DISTORTED, MISSING RAIL STOPS, SASH ROT, BRICKMOLD ROT/SPLIT
1.5B	2'-10"	3'-11 1/2"	FIXED						N/A	MISSING ROPE/WEIGHTS/PULEYS
1.6	2'-2"	6'-0"	DOUBLE-HUNG							SASH STILES DETACHED AT JOINTS, MISSING STOPS, MISSING HARDWARE, BRICKMOLD SPLITTING
1.7	3'-10"	6'-0"	DOUBLE-HUNG							SILL AND FRAME ROT, MISSING STOPS, MISSING ROPE/WEIGHTS/PULEYS
1.8	2'-2"	4'-8"	DOUBLE-HUNG							TOP SASH STILES DETACHED AT JOINTS, MISSING ROPE/WEIGHTS/PULEYS
1.9	2'-6"	6'-0"	DOUBLE-HUNG							LARGE OPENING WHERE FRAME WAS CUT, GLAZING PUTTY DETERIORATED, GLASS FALLING OUT
1.10	2'-6"	6'-0"	DOUBLE-HUNG							FRAME WARPED, LARGE OPENING WHERE FRAME WAS CUT, MISSING STOPS, MISSING ROPE/WEIGHTS/PULEYS
1.12	2'-6"	6'-0"	DOUBLE-HUNG							MISSING RAIL STOPS, GLAZING PUTTY DETERIORATED, GLASS FALLING OUT
1.13	2'-6"	6'-0"	DOUBLE-HUNG							MISSING RAIL STOPS, SASH STILES DETACHED AT JOINTS, MISSING ROPE/WEIGHTS/PULEYS
2.1	1'-10"	3'-3"	DOUBLE-HUNG							SOME SILL ROT, REPAIRABLE CONDITION
2.2	2'-10"	6'-0"	DOUBLE-HUNG							BOTTOM SASH ROT, SASH STILES DETACHED AT JOINTS, METAL PLATE CONCEALING SILL CONDITION, INOPERABLE
2.3A	4'-3"	1'-11 1/2"	FIXED/TRANSOM							REPLACEMENT/NOT ORIGINAL SASH
2.3B	4'-3"	3'-11 1/2"	FIXED							MISSING GLAZING, METAL PLATE CONCEALING SILL CONDITION
2.4	2'-10"	6'-0"	DOUBLE-HUNG							BOTTOM SASH ROT, METAL PLATE CONCEALING SILL CONDITION, INOPERABLE
2.5	1'-10"	3'-3"	DOUBLE-HUNG							SOME SILL ROT BUT IN REPAIRABLE CONDITION
2.6	2'-2"	6'-0"	DOUBLE-HUNG							MISSING GLAZING, METAL PLATE CONCEALING SILL CONDITION
2.7A	2'-10"	1'-11 1/2"	FIXED/TRANSOM						N/A	REPLACEMENT/NOT ORIGINAL SASH
2.7B	2'-10"	3'-11 1/2"	FIXED						N/A	MISSING GLAZING (PLASTIC PANEL INFILL), BOTTOM SASH ROT, SILL ROT
2.8	2'-2"	6'-0"	DOUBLE-HUNG							METAL PLATE CONCEALING SILL CONDITION
2.9	3'-10"	6'-0"	DOUBLE-HUNG							MISSING RAIL STOPS, TOP SASH ROT, SASH STILES DETACHED AT JOINTS, MISSING ROPE/WEIGHTS/PULEYS
2.10	2'-2"	4'-8"	DOUBLE-HUNG							METAL PLATE CONCEALING SILL CONDITION, RAIL STOPS DETACHED
2.11	2'-6"	6'-0"	DOUBLE-HUNG							COMPLETE UNIT MISSING
2.12	2'-6"	6'-0"	DOUBLE-HUNG							COMPLETE UNIT MISSING
2.13	2'-6"	6'-0"	DOUBLE-HUNG							MISSING GLAZING, TOP SASH ROT, SASH STILES DETACHED AT JOINTS, MISSING ROPE/WEIGHTS/PULLEYS
2.14	2'-6"	6'-0"	DOUBLE-HUNG							SILL ROT, SASH STILES DETACHED AT JOINTS
2.15	2'-6"	6'-0"	DOUBLE-HUNG							MISSING BOTTOM GLAZING, MISSING ROPE/WEIGHTS/PULLEYS
2.16	2'-6"	5'-4"	DOUBLE-HUNG							SOME FRAME ROT, REPAIRABLE CONDITION
3.4	2'-6"	5'-5"	DOUBLE-HUNG							LARGE CUTS IN FRAME, MISSING GLAZING, SASH STILES DETACHED, MISSING HARDWARE

WINDOW CONDITION KEY:

POOR - MISSING, DETERIORATED, IRREPAIRABLE

FAIR - AREAS OF DETERIORATION, REPLACEMENT COMPONENTS REQUIRED

GOOD - SOME COSMETIC DEFECTS, REPAIRABLE

INTANDEM CAFE + BIKE STUDIO

8022 KERCHEVAL AVE. DETROIT, MI 48214

SUBJECT STUDIO

1577 ASH ST. DETROIT, MI 48208 USA

313.364.9859

hi@subject-studio.

PROJECT
2302
HDC REVIEW



DATE SET
07/12/23 HDC REVIEW

SEAL

SCHEDULES

A-600