
## EXISTING WOOD WINDOW DETAILS (DOUBLE-HUNG)

## HEAD INTERIOR HEAD TRIM, MOLDINGS, SILL AND APRON EXISTING ON 14 WINDOWS (MOSTLY SECOND LEVEL) AND MISSING ON 14 WINDOWS (MOSTLY FIRST LEVEL) RAIL STOPS MISSING ON MAJORITY OF WINDOWS EXISTING BRICKMOLD IS DETERIORATED ON MAJORITY OF WINDOWS RAIL PULLEY, ROPE, AND COUNTERWEIGHT BROKEN OR MISSING IN MAJORITY OF WINDOWS SILL 2" 2-3/8" **JAMB**

## PROPOSED REPLACEMENT WINDOW DETAILS (DOUBLE-HUNG)

- MARVIN ULTIMATE G2
- ALUMINUM-CLAD WOOD FRAME AND SASH
- NEW CUSTOM WOOD BRICKMOLD TO MATCH EXISTING PROFILE



## 8022 KERCHEVAL RENOVATION HDC PROPOSED BRICKMOULD