

1405 Chicago Blvd elevations with windows

North side, facing Chicago Blvd



Added a few more photos of the exterior north side, similar windows are also visible in street pictures dated 2011 or earlier, all the windows on this side are same style, material looks like PVC, we found a mark dated 2017 so we are assuming changes happened then for this section.



Master Bedroom windows facing North to Chicago Blvd, as all the ones facing North, they look all changed during same time and PVC type material, assuming 2017.



Family room on main floor facing North, same as previous, all same type and kind of PVC material, assuming 2017.



East side facing Byron St.



Main floor; family room, dining room and main entry.

Family room (right side taller window) is the same style as all the ones facing North, and installed clearly at same time, PVC material, assuming 2017.

Main entry, small window to the right of the door is original to the house (see detailed photos attached)



Dining room area on main floor (two windows)





On this section, windows facing Byron St are the same style, they also look like PVC material, and potentially changed around same time than the ones facing Chicago Blvd, assuming 2017.

Photos from 2011 show similar windows, but we are assuming changes were made in 2017.



See attached photos from Detroityes.com with comments about 2011, while the windows look like a similar style, we cannot tell they were the same ones.



And the only photo from 1974 that we were able to find in preservationdetroit.org showing what we think were the original windows.



On the second floor facing Byron St we have one bedroom, and the master bedroom and bath (right side). On this section, windows facing Byron St are the same style, they also look like PVC material, and potentially changed around same time than the ones facing Chicago Blvd, assuming 2017.

Master windows facing Byron St



Bathroom window with translucent glass



Second bedroom facing Byron with two double windows. Same material, PVC, and assuming 2017 updated.



Attic windows material is wood, while they are not original, they don't look as changed at same time than main and 1st floor. Assuming 2010 for a mark on the glass.



Back side (south) of house facing alley and Longfellow St

For this back side we have not been able to find any old photo, only one from 2011 shows originally a garage was attached to the house from where today's is the backyard/driveway door.

On this elevation only one window is original (top one on third floor staircase) that on below photo is the top center one.



Main floor ones (side of dining room) look like changed earlier than rest of dining room (potentially when garage was demolished) and material is wood, most of them damaged and with some “repairs” on the inside with screws to fix position of window. I was able to find a mark and windows look from 2010.





All this windows are from Andersen and built/installed in 2010. They are all the same on south façade (facing alley) ... on the picture is not easy to see the engraving.



1st floor bedroom

As the other ones facing south, wood material and mark dated 2010.



Foyer window seems from same time, but I cannot access to verify.



Attic staircase window is original, wood and still in good status



Third room in 1st floor window is one piece, material is wood with window dated 2010.



East side facing neighbors in Chicago Blvd.

(here I have multiple photos as I can't get far enough to cover all in one photo due to proximity to neighbors property)







Main floor, facing west we have the kitchen and part of family room.

Kitchen area, two windows, both are PVC material, and windows are dated 2017.



Basement access window, one window, PVC material dated 2017.



Family room, two windows around fireplace, left one is original, and quite damaged. Right one is wood and dated 2010.



Right window is wood, and dated 2010



Left window is original one



Family room window (old sun room), similar to the ones facing Chicago, material is PVC and dated 2017.



Staircase windows, material is wood and dated 2010



1st floor bathroom, translucent window, material is PVC and seems was changed in 2017




1st floor room, window is wood, dated 2010



1st floor (second bedroom)

One window is original and in quite a damaged status (right side of fire place)



Left side of fireplace is wood, dated 2010



Small window in center of the room, wood window dated 2010



Attic windows, all them are wood but I was not able to identify date on glass, assuming 2010 as the other wood ones.

Attic bathroom



Attic under roof windows, both wood and also assuming dated on 2010

