

Exterior Doors



Front Door



**Proposal Front Door
Fiberglass Craftsman**



**Proposal Front Security
Door**



Back Upper Porch Door



**Proposal Side and Back Doors
6 Panel Fiberglass**

South Wall Additional Information



Proposal JAMESHARDIE PRIMED
5 FIBER CEMENT CEDARMILL LAP SIDING
Cobblestone



Proposed replacement windows for back wall
Andersen 100 series 1st floor



Proposed replacement window for back
side 2nd floor. Andersen 100 series Gilding Window



Finished Example of proposal repairs
This photo was taken of the house next door
1659 Edison St

Front Porch Brick Repair



Replace missing bricks from the side.



Replace missing bricks from front steps additional install missing caps on top of the bricks.

Lastly, replace the 4x4 wooden post in the center with matching bricks like the other columns.

Gutters & Soffits



Amerimax 5-in aluminum gutter

Hardie® Soffit

Thickness 1/4 in

Vented and Non-Vented Select Cedarmill®

Width 12 in

Length 12 ft



Soffit


Windows



North Windows



West Windows






South Windows




East Windows

Window and Railing Cut Sheets

Single-Hung Window Details - New Construction
Scale 1 1/2" (38) = 1'-0" (205) - 1:8



Picture, Single Transom and Specialty Window Details - Replacement (continued)
Scale 1 1/2" (38) = 1'-0" (305) - 1:8





Missing concrete in driveway leading into the backyard.