

## Building 219: Noncommissioned Officer's Quarters

---



*Front (northwest) facade, April 2019*

**Construction Date:** 1939

**Current Use:** Vacant

**Historic Use:** Residential (Duplex Noncommissioned Officer's Quarters)

**Square Feet:** 2,550 (+1,208 SF basement)

**Condition:** Poor<sup>1</sup>

**Prior Cost Estimates:** \$510,000<sup>2</sup>; \$600,000–\$750,000<sup>3</sup>

**Building Typology:** “Type 3”, with 216, 217, and 218<sup>4</sup>

**Building Evolution:** This building appears to be largely unaltered since its original construction.

---

<sup>1</sup> Hamilton Anderson Associates, 2015.

<sup>2</sup> For rehabilitation; Hamilton Anderson Associates, 2015.

<sup>3</sup> For rehabilitation and conversion to office or rental residential use; SmithGroup, 2008.

<sup>4</sup> Nomenclature by SmithGroup, 2008.

**Interior Description:** This building is two stories with basement. Each unit's first floor consists of a living room, dining room, kitchen, enclosed side porch and a separate enclosed front entrance vestibule for each unit. The stair to the second floor is open to the living room. Second floors contain a stair hall, three bedrooms, and a three-piece bathroom. The two main floor levels have original fully plastered walls and ceilings. Except as noted, floors are wood. The kitchen floor is wood covered with linoleum. The bathroom has plastered walls and original ceramic tile wainscot and floor matching the 1935-39 remodeling of other buildings.

**General Condition:** This building is in poor condition, according to a 2015 report. A condition assessment conducted in 2008 identifies rusted lintels, mortar in good condition other than deteriorated chimney mortar, deteriorated rear porch masonry, rotted fascia, missing gutters and leaders, paint in poor condition, one half of roof in good condition due to recent replacement with the other half in poor condition, porch roofs in good condition, rear porches in fair condition. The building has suffered additional deterioration since 2008.


**Utilities:** None

**Character-defining Features:** Significant exterior features include: rectangular plan with hip roof, red brick walls, rectangular window openings, wood six-over-six windows, eaves with crown molding trim, brick chimneys, enclosed front entrances with wood panels, open rear porches, single-story sunrooms.

On the interior, all woodwork, including interior doors, along with colorful tile work in entrance vestibules and restrooms, are significant features. Fireplaces and surrounds are also significant. All wood features remain in place, including stairway rails and balustrades, though many have been damaged due to water infiltration. Some light fixtures and restroom fixtures remain but most are missing.

**References:** Additional background information, including both 2008 and 2015 conditions assessments referenced above, and National Register of Historic Places documentation, is available at [detroitmi.gov/historicfortwayne](http://detroitmi.gov/historicfortwayne).

See next page for floor plan.



Scale: 8" = 1'-0"  
JULY 1974

BUILDINGS 216, 217, 218 & 219  
FORT VLAYNE

