


**STAFF REPORT 07-24-2019 SPECIAL MEETING**  
**APPLICATION NUMBER: 19-6340**  
**ADDRESS: 1205 HUBBARD STREET**  
**HISTORIC DISTRICT: HUBBARD FARMS**  
**APPLICANT: TRACIE MCMILLAN**  
**STAFF SITE VISIT: 07-16-2019**

**PREPARED BY: A. PHILLIPS**

**PROPOSAL**

The building located at 1205 Hubbard Street is a 2½-story single-family residence constructed ca. 1900. The structure is clad in wide aluminum siding that is light yellow in color with white wood and aluminum trim. It appears that many of the original wood windows are intact. The asymmetrical façade includes a small porch at the entry which is topped with a gable roof. The multi-gable roof is covered in light gray asphalt shingles. Aluminum awnings exist over the two main windows on the front façade. Faux shutters flank the main window on the first floor.



With the current proposal, the applicant is seeking the Commission's approval **to repair the existing aluminum siding, paint the main body of the house a dark blue color that is not included in the assigned color charts B and C, and remove existing aluminum awnings per the attached application.**

### **STAFF OBSERVATIONS**

- Existing aluminum awnings are not considered historic nor are they character-defining features of the style of architecture in which the house is built.

### **ELEMENTS OF DESIGN**

- (1) **Height.** Commercial and institutional buildings range from one (1) story to four (4) stories in height; some have single stories with very high ceilings and balconies, such as Aijalon Church, the former bank building at 4138 W. Vernor, and Bowen Library. Buildings in Clark Park are generally one (1) or one and one-half (1½) stories tall, with additional height in a steep roof. Residential buildings range from one and one-half (1½) stories to five (5) stories, the smallest being the Workers Cottages seen primarily on Bagley and the tallest being the five-story Whitedel Apartment Building on Porter and Hubbard. The majority of residential buildings are either two (2) or two and one-half (2½) stories tall, meaning they have two (2) full stories with an attic or finished third floor within the roof. Where height specifications were included in the original subdivision restrictions, they should be complied with for new construction. Detached garages are generally one (1) to one-and-one-half (1½) stories tall. Additions to residential structures shall be related in height to the existing structure; new buildings shall meet the following standards:
- (A) The eight (8) adjoining structures on the same block face shall be used to determine an average height. The height of the two (2) adjoining houses shall be added into the total twice, with a divisor of ten (10) used to determine the average. Any new building must have a height of the main roof of at least eighty percent (80%) of the resulting average; in no case shall a new building be taller than the tallest roof height included in the computation. In determining the heights of existing structures and proposed structures, the highest point of the main roof shall be used, even where towers, cupolas, or other minor elements may be taller.
- (B) The level of the eaves of a proposed new residential structure having as much or more significance for compatibility as the roof height, an average eave or cornice height shall be determined by the same process as that described above. The proposed new structure shall have a height at the eaves, or cornice, of not less than ninety (percent) (90%) of the average determined from existing structures, and in no case shall the eaves or cornice of the proposed structure be lower than the lowest eave or cornice height used in the computation, nor higher than the highest.
- (2) **Proportion of building's front facades.** Proportion varies in the district, depending on type of building, age, style, and subdivision. Most single family houses are neutral to their eaves, although some are wider than tall and some taller than wide. Terrace buildings (rows) are wider than tall, although individual units are taller than wide or neutral. Apartment buildings are generally taller than wide or neutral. No proposed residential building or addition shall create a front facade narrower or wider than those existing on the same block. Commercial buildings on W. Vernor may be wider than tall, taller than wide, or neutral but when they abut other buildings they form a row that is wider than tall. Bowen Library is wider than tall, as is Western High School and Earhart Middle School on Scotten. The Clark Street facade of Maybury School is neutral. Aijalon Church is wider than tall when taken as a whole.
- (3) **Proportion of openings within the facade.** Proportion varies according to building type, age, and style. Generally, window openings in the district are predominantly taller than wide; several windows are frequently grouped into combinations wider than tall. Window openings are most often subdivided, the most common window type being double-hung sash, whose area is generally further subdivided by muntins. Queen Anne style buildings and special use buildings, such as Aijalon Church at 330 W. Grand Boulevard, display windows that may be wider than tall, arched, or square. In general, buildings have between fifteen (15) percent and thirty-five (35) percent of their area glazed.
- (4) **Rhythm of solids to voids in front facades.** Window openings are usually regularly arranged by floor, although there is most often variety between floor levels. In the Queen Anne and Richardsonian Romanesque style buildings, openings are often irregularly arranged. In buildings derived from classical precedents, voids are usually arranged in a symmetrical and evenly-spaced manner within the facade. In bungalows and arts and crafts influenced buildings, large areas of voids are filled with windows. Many of the residential buildings have dormers or gables that are fenestrated.
- (5) **Rhythm of spacing of buildings on streets.** The spacing of buildings is generally determined by the setback from the side lot line. There is a variance in the width of lots from subdivision to subdivision. In general, residential and commercial buildings are spaced close together as a result of their narrow lot width and/or maximized building size. Single/two family houses are centered between side lots or are sited very close to one (1) side lot line to provide additional space on the other side. Infrequently, two (2) lots are grouped together, creating a side lot. On Vernor and elsewhere where buildings have been demolished, the continuous line or rhythm of buildings is disrupted.
- (6) **Rhythm of entrance and/or porch projections.** Placement of entrance and porch projections vary from building to building,

usually depending on type, size and style. In general, a great variety of porches and entrances characterize Hubbard Farms. In those examples of classical inspiration, entrances and porches tend to be centered on the front facade or balance each other if there are more than one, as on terrace buildings and duplexes. Other examples, display more freedom in entrance and porch placement. Secondary entrances are common; Italianate houses and small Queen Anne cottages frequently have small side porches. Porches on houses built around the turn of the century tend to be large, sometimes stretching along most of the first story, while English and arts and crafts influenced buildings tend to have deemphasized entrances. Where similar houses line a block a rhythmic progression of porches is created. Most of the houses in the district have rear porches.

- (7) ***Relationship of materials.*** Brick and wood are the primary building materials originally used. Brick buildings may have pressed brick front facades with common brick sides and rears. Many wood frame buildings are clad in clapboard. While most buildings have brick foundations, some foundations are of stone. Buildings originally built on wood piers originally had wooden skirting. A few buildings were built of concrete block. Wood trim is most commonly used for window, porch, and functional elements as well as decorative trim; some lintels and sills also exist. Stucco with or without half-timbering is either the main building material or combined with brick on a few English revival and arts and crafts style houses. Front porch step materials are either wood or concrete. Brick of the more substantial buildings, such as Aijalon Church and Maybury and Western High Schools, is contrasted with stone foundations, trim and detail. Earhart Middle School is cast concrete. A small number of original slate roofs are present; the majority of original roofing materials have been replaced by asphalt shingles.
- (8) ***Relationship of textures.*** A variety of rich textural relationships exist in the district—those created by the juxtaposition of various materials, such as brick, stone, stucco, and/or wood, and those created by the repetition of the materials themselves, such as clapboard, wood fish scale shingles or decorative brick. Slate roofs create textural interest, whereas asphalt shingles generally do not. Textured concrete block houses built in the early twentieth century have a large degree of textural interest.
- (9) ***Relationship of colors.*** Natural brick colors (red, brown, orange, buff) predominate on brick wall surfaces. Stucco is usually cream, off white, or pale yellow in color. Wooden elements display a variety of colors, depending on what is appropriate for their style. In general, wooden elements of buildings derived from classical precedents, such as the Neo-Georgian or Colonial revival, are painted in the white-yellow-gray range, while wooden elements of Victorian buildings show more freedom, ranging from shades of rose to green, sometimes with a contrasting color highlighting the architectural detail. Wooden elements of bungalows and arts and crafts influenced buildings tend to be painted in earth tones. Asphalt shingle roofs display a range of colors, from natural slate colors and black to lighter shades of green, gray, brown and red. The original colors of any building, as determined by professional analysis, are always acceptable for that building, and may provide suggestions for similar buildings.
- (10) ***Relationship of architectural details.*** Architectural details generally relate to style. Colonial revival buildings display classical details, often in wood. Porches are commonly treated and usually have columns of a classical order. Buildings of Victorian substyles also tend to have details of wood located around the entrance, porch, windows, bays, towers, and dormers. Lathe-turned and jig-saw cut wooden elements and details are common. Prairie and arts and crafts style buildings tend to be simply stated, with architectural interest derived from the arrangement of elements and quality of design. In general, the Hubbard Farms District is extremely rich in architectural detail.
- (11) ***Relationship of roof shapes.*** Most every roof type is represented in the district, from flat roofs on terrace buildings and commercial buildings to hipped, pitched, and gambrel roofs on single-family residences. Roof shapes are generally related to style. Bungalows, arts and crafts influenced and Prairie style houses have shallow roofs; Queen Anne and other Victorian substyles exhibit greater heights, intersecting planes and steep slopes.
- (12) ***Walls of continuity.*** The major wall of continuity is created by the front facades of the buildings, where there are uniform setbacks within subdivisions. Trees planted between the sidewalk and the curb create a secondary wall of continuity.
- (13) ***Relationship of significant landscape features and surface treatments.*** The Hubbard Farms District is defined by the curbs; graded grass turf islands in the center of West Grand Boulevard on the east and Clark Park, a major public park, on the west. The northern half of Clark Park is landscaped and graded for passive recreational use. Its widening black asphalt paths are lined with modern black steel slighting standards. Picnic shelters, modest playground equipment and mature and more recently planted trees are located on the northern half. The southern half is occupied by more active recreational facilities, such as tennis courts, basketball courts, a playscape, and a large playfield enclosed by a chain-link fence. The typical treatment of individual properties is a flat or graded front lawn area in grass turf, often subdivided by a straight or curved concrete walk leading to the front entrance. Foundation plantings are of the evergreen and/or deciduous nature; a tree or two (2) are usually planted in the front yard as well. On those parts of streets with graded tree lawns, particularly on the southern ends of Vinewood and Hubbard, concrete steps lead up to the sidewalk from the curb. Tree lawns between the curb and public sidewalk are generally narrow throughout the district, and do not exist on Vernor. On Hubbard and Vinewood, the original flag-stone curbs still exist; elsewhere, curbs are concrete. Because of the narrow lot sizes, there are few side driveways in the neighborhood, and where they exist, they were added after the initial development of the neighborhood. Where there are no driveways or front yard fences, there is a continuous visual progression of front yards. On the western side of the southern end of Hubbard to the rear of Earhart School on Scotten, there is no alley; houses backing on the school have front-facing garages accessed by driveways off of Hubbard. The majority of fences are of the

chain link variety; four (4) foot chain-link fenced front yards are seen throughout the district but to a lesser degree at the south end of Hubbard and Vinewood. Rear yards are frequently enclosed by chain link, wood plank, or stockade fencing. A few houses have black wrought iron fences. Few houses have hedges along the lot lines. Chain-link fencing encloses the playfields to the south of Western High School and the Earhart School parcel. The parking lot to the north of Western High School is bermed and has tall steel lighting standards within. Street lights throughout the district are on wooden poles, with the exception of the tall steel light poles with modern lanterns on West Vernor and tall fluted standards with crane-neck pendants and old style lanterns on West Grand Boulevard. Some home owners have installed uniform outdoor lighting standards in their front yards in recent years. Alleys are either concrete or black asphalt; the north-south alley between West Grand Boulevard and Vinewood from Shady Lane to Porter is brick-paved.


- (14) Relationship of open space to structures.** The major open space is Clark Park, which has houses facing it across north-south streets, commercial buildings across Vernor, and Fisher Freeway to its south. The wide grassy islands in the center of West Grand Boulevard provide significant open space to those buildings facing it. The siting of most residential buildings on their lots create rear yards as well as front yards, the exceptions being those buildings situated on zero (0) lot lines, such as the commercial buildings on Vernor, YMCA on Clark, the Yorba Hotel on Lafayette, and Terrace Buildings, on side streets. Because of the minimal setback of some Terrace Buildings, apartment buildings, and houses on the east-west streets, some front yards are very shallow. Side lots are minimal if they exist, unless a vacant lot is joined with the house lot. While some vacant lots exist throughout the district, large vacant parcels are usually located on Vernor between commercial buildings to provide parking on Lafayette, where demolition occurred due to the construction of the Freeway, leaving irregularly shaped parcels, and on corners, where Terrace Buildings have been demolished. A planted area on the southwest corner of Lafayette at West Grand Boulevard makes an entrance into the district; a grass turf open space is located at the northeast corner of Scotten and Lafayette just south of Earhart Middle School.
- (15) Scale of facades and facade elements.** Houses are generally small to moderate in scale. Facade elements and details vary in scale and are generally dependent on style. Detail on arts and crafts, influenced buildings tends to be architectonic in nature; on Victorian Buildings decorative detail tends to be small in scale while facade elements, such as bays, dormers and towers, are large in scale. Classically influenced buildings tend to have large scale elements such as columns.
- (16) Directional expression of front elevations.** In general, directional expression is neutral, due to inform heights and narrow lots. On Vernor, where commercial buildings are contiguous, the overall directional expression is horizontal.
- (17) Rhythm of building setbacks.** Setbacks of front facades are uniform within subdivisions, with few exceptions, although porch projections vary. Houses on the first block of Clark south of W. Vernor and the first block of Clark north of Lafayette have irregular setbacks. Apartment buildings located on corner lots and within blocks on Hubbard are located closer to the front lot line than individual homes, creating inconsistency to the streetscape. On Vernor, facades are located directly on the front lot line. On the side streets, such as Bagley and Porter, setbacks are shallow but usually consistent.
- (18) Relationship of lot coverage.** Lot sizes vary within the district, but are generally consistent within subdivisions. Primary buildings on residential lots occupy twenty-five percent (25%) to ninety percent (90%) of their lots. The deep lots with single family houses on Hubbard are at the low end and lots occupied by large apartment buildings, Terrace Buildings (rows), and duplexes on side streets are at the high end of that range. Commercial buildings on West Vernor occupy most of their lots; lot coverages of institutional buildings vary due to the addition of adjoining lots to original parcels but they generally occupy a high percentage of their lots.
- (19) Degree of complexity within the facade.** The degree of complexity has been determined by what is typical and appropriated for a given style. The classically inspired buildings usually have simple, rectangular facades with varying amounts of ornamentation. The Victorian substyles tend to be more complex, complicated by towers, gables, and decorated porches. The arts and crafts and bungalow style houses are not complex.
- (20) Orientation, vistas, overviews.** The main streets in the district run north-south; Vernor Highway is the major commercial thoroughfare and runs east-west. The secondary streets: Bagley, Porter, Clark Court and Lafayette, run east-west. Fisher Freeway forms an emphatic southern boundary. Terrace Buildings (row) are frequently oriented towards the east-west streets but may have one (1) or more units facing the north-south street at the corner. Lafayette jogs to accommodate modifications made when the Fisher Freeway was constructed; Fisher Freeway forms an emphatic southern boundary to the district. From the Freeway, the Yorba Hotel sign provides a visual landmark in the neighborhood.
- (21) Symmetric or asymmetric appearance.** Classically inspired buildings are generally symmetrical; other styles are generally asymmetric but result in balanced compositions.
- (22) General environmental character.** The Hubbard Farms District appears as a late-nineteenth, early twentieth century neighborhood that grew as a street car, suburb off of a busy commercial thoroughfare (Vernor). Its mixed use and multidensity character survives to this day. The area was designed with visual and recreational amenities, such as the grassy treed and graded islands in the middle of West Grand Boulevard and Clark Park. The neighborhood is generally well maintained and intact today, although the commercial thoroughfare is showing signs of decline.

## **RECOMMENDATION**

It is staff's opinion that the work, as proposed, does not remove historic materials nor does it alter any features or

spaces that characterize the building, its site, or setting. Staff therefore recommends that the Commission find the removal of the aluminum awnings and painting the exterior of the house in the dark blue color as proposed to be appropriate as the scope of work meets the following Secretary of the Interior's Standards for Rehabilitation:

- *2) The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.*




Earhart Elementary  
Middle School

Yorba

1205 Hubbard Street

Google



Lupe Barber Shop

sars Pizza

Western International High School

Hubbard Farms Community Garden

Shaun's Party Store

Isowearelite

Deliverance Center

React Funding

A-1 Discount Restaurant Equipment

Clark Park

1205 Hubbard Street

Delray Senior Housing

Maybury Elementary School

Earhart Elementary Middle School

Yorba

The Church of Jesus Christ

Clark Park Coalition

Fisher Fwy

Marathon Gas

Detroit Engine Kit

MyDetroitAddress - Package Delivery Depot

Century Transportation

Google



STAFF SITE VISIT 07/16/2019



1201E

1205

STAFF SITE VISIT 07/16/2019





STAFF SITE VISIT 07/16/2019

# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

- Photographs of ALL sides of existing building or site** \_\_\_\_\_ **2**
- Front and side of house, East and South Facing \_\_\_\_\_ **3**
- Rear and side of house, West and south facing \_\_\_\_\_ **3**
- Rear of house, West facing \_\_\_\_\_ **4**
- Rear and side of house, West and north facing \_\_\_\_\_ **4**
- North side of house, accessed through neighbor's yard \_\_\_\_\_ **5**
- Neighborhood context: Rear of 1205 Hubbard and adjacent homes \_\_\_\_\_ **5**
- Detailed photographs of location of proposed work** \_\_\_\_\_ **7**
- FIRST PLEASE NOTE: See above. This is a proposal regarding exterior paint color.** \_\_\_\_\_ **7**
- Siding** \_\_\_\_\_ **7**
- Holes in siding \_\_\_\_\_ **7**
- Deteriorated caulking on south side, similar across exterior \_\_\_\_\_ **8**
- Deteriorated caulking, mold at building entry on east side \_\_\_\_\_ **9**
- Awnings** \_\_\_\_\_ **9**
- Stained glass (note blue details)** \_\_\_\_\_ **11**
- Description of existing conditions** \_\_\_\_\_ **12**
- Description of project** \_\_\_\_\_ **12**
- Detailed scope of work** \_\_\_\_\_ **13**
- Brochure/cut sheets for proposed replacement material(s) and/or product(s)** \_\_\_\_\_ **13**
- Paint card from Benjamin Moore (note that desired color is halfway between 2063-20 (middle) and 2063-10 (right)) \_\_\_\_\_ **13**
- Sample of desired color painted at 1205 Hubbard, adjacent to existing gutter \_\_\_\_\_ **13**

# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

Photographs of ALL sides of existing building or site  
Front of house, East Facing



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

Front and side of house, East and South Facing



Rear and side of house, West and south facing



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

Rear of house, West facing



Rear and side of house, West and north facing



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

North side of house, accessed through neighbor's yard



Neighborhood context: Rear of 1205 Hubbard and adjacent homes



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

## Detailed photographs of location of proposed work

FIRST PLEASE NOTE: See above. This is a proposal regarding exterior paint color.

Second, given that I am proposing to repaint the base color of the exterior of 1205 Hubbard, most of that is covered in the photos above. However, there are a **few detail photos that will help you understand the description of the project, below.**

### *Siding*

Holes in siding



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting



Deteriorated caulking on south side, similar across exterior



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

Deteriorated caulking, mold at building entry on east side



*Awnings*



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

*Stained glass (note blue details)*



# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

## Description of existing conditions

The existing exterior is wood aluminum siding with wood trime. As when I bought it, the trim is a clean, non-yellow white; the metal overlay on the brick understory is painted a dark gray; and the exterior aluminum siding is a faded light yellow.

Much of the building's caulk is brittle and cracked; there are many holes in the siding; and there are signs of mold. There are some issues with flashing having been installed poorly.

There are also two aluminum awnings—dirty, rusted, of aluminum, and likely added in the 1960s when they were in fashion—on the front of the house. They were painted poorly by previous painters, and this has opened the door for mold.

## Description of project

I purchased 1205 Hubbard in 2015 through the Detroit Land Bank, which had brokered the sale on behalf of the Michigan Land Bank. The home had been empty for two years prior, and had clearly not been maintained prior to that for some time. I have focused the first several years of ownership on making the home safe, inhabitable and stable: an entirely new roof, significant improvements to basement waterproofing and drainage, a new furnace, new flooring. Much work remains, but I am now at a point where I can afford to invest in the house's exterior.

**I am seeking approval to paint the body of the house a color that is not currently part of the default color schemes for the neighborhood.** I would leave trim the same clean white it was when I bought the house, and the understory the same dark gray, though I'm having both scraped and repainted. I had hoped to limit my repair work this year to the trim and gutters, but as my contractor has done his work, it's become clear that the siding is in very poor shape and this is causing slow, steady damage to the building by allowing weather to enter. I hope to paint my house a dark blue, which will highlight and contrast nicely with stained glass detail on the second story—currently hidden behind the awnings, and in need of repair (once I can afford to do so). That said, the neighborhood's color schemes offer only one real blue, and it is used twice on the block preceding mine. With this in mind, I've proposed an alternate color I believe is attractive, adds value to the home and block, and is in line with the neighborhood aesthetic.

I would also like to **remove the aluminum awnings**, which were likely added in the 1960s and have no historic value.

# REPORT

HDC Application: 1205 Hubbard  
Submitted July 3, 2019, for July 24 meeting

## Detailed scope of work

- Remove awnings and mounting hardware from front/east of building
- Patch all holes, and caulk all seams, of siding for exterior
- Power wash all siding for exterior
- Paint exterior with Benjamin Moore color, 2063-15 (between 2063-10 and 2063-20)
- 

## Brochure/cut sheets for proposed replacement material(s) and/or product(s)

Paint card from Benjamin Moore (note that desired color is halfway between 2063-20 (middle) and 2063-10 (right))



Sample of desired color painted at 1205 Hubbard, adjacent to existing gutter

