October 20, 2020

NOTICE OF DENIAL

James A. Franke Normandy Properties, Inc. 1991 Chicago Detroit, MI 48206

RE: Application Number 20-6894; 1991 Chicago; Boston Edison Historic District

Dear Mr. Franke:

At the regular meeting that was held on October 14, 2020, the Detroit Historic District ("Commission") reviewed the above-referenced application for building permit. Pursuant to Section 21-2-80 of the 2019 Detroit City Code, the Commission hereby issues a **Notice of Denial for the below outlined items** which is effective as of October 20, 2020. Specifically, the Commission reviewed the permit for the below**described work,** and determined that it *does not* qualify for a Certificate of Appropriateness because it does not meet the Secretary of the Interior Standards for Rehabilitation, Standards #2) The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided, #3) Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken. #5) Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a property shall be preserved, #6) Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence, and #9) New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment:

• The removal of porch wings, columns and railings and front elevation wall treatment without permit and/or approval of the Historic District Commission.

The Commission issues this *Notice of Denial, with the following Stipulations for Correcting the Violation:*

- 1. Rebuild porch to its original dimensions using matching materials, including wings with iron railings to match original, and including wood columns to match originals.
- 2. Correction work must receive a COA in order to receive a Building Permit, prior to beginning work.
- 3. Correction should be completed by June 2021

Please note that the above-described work associated with application #20-6894 represents a violation of Detroit City Code. The Historic District Commission will not take any further action until June 2021. If you have not corrected the violation in a matter that meets the above-outlined stipulations on or before June 2021, the Detroit Buildings, Safety Engineering and Environmental Department (BSEED) will resume enforcement action on the denied work items.

Please be advised that a permit applicant that is aggrieved by a decision of the Detroit Historic District Commission concerning a permit application may file an appeal with the Michigan Department of Attorney General. Within sixty (60) days of your receipt of this notice, an appeal may be filed with:

Jon Stuckey
Michigan Department of Attorney General
2nd Floor G. Mennen Williams Building
525 West Ottawa Street
P.O. Box 30754
Lansing, MI 48909
P: 517-335-0665

F: 517-335-3088

Email: stuckeyj@michigan.gov

If you have any questions regarding the foregoing, please contact Taylor Leonard, Counsel for the Commission at (313) 237-3006.

For the Commission:

Daniel Rieden

V. Kiese

Staff

Detroit Historic District Commission

2 WOODWARD, SUITE 808 DETROIT, MICHIGAN 48226 PHONE 313-224-6536 FAX 313-224-1310

October 20, 2020

CERTIFICATE OF APPROPRIATENESS

James A. Franke Normandy Properties, Inc. 1991 Chicago Detroit, MI 48206

RE: Application Number 20-6894; 1991 Chicago; Boston Edison Historic District

Dear Mr. Franke:

At the regular scheduled meeting that was held on October 14, 2020, the Detroit Historic District Commission ("Commission") reviewed the above-referenced application for building permit. Pursuant to Section 5(10) of the Michigan Local Historic District Act, as amended, being MCL 399.205, MSA 5-3407(5)(10) and Section 21-2-73 of the 2019 Detroit City Code; the Commission has reviewed the above-referenced application for building permit and hereby issues a Certificate of Appropriateness, which is effective as October 20, 2020.

The Commission issued a Certificate of Appropriateness for the following work items because they meet the Secretary of Interior's Standards for Rehabilitation.

Exterior Work

- All windows were restored throughout the home. Each window was taken apart, resized, new historic chain and hardware installed and glass replaced where needed.
- Shutters restored back to the original color that existed under the painted-over white color.
- Upper railing repairs included removing rust and repainting the railings from white to black, their original color.
- Light fixture on underside of porch roof was repaired and reinstalled.
- Limestone edge of front porch slab was salvaged and reset in place
- Replaced damaged concrete in front porch surface

Please retain this COA for your files. You should now proceed to obtain a building permit from the City of Detroit Buildings, Safety, Engineering and Environmental Department. It is important to note that approval by the Detroit Historic District Commission does not waive the applicant's responsibility to comply with any other applicable ordinances or statutes.

For the Commission:

V. Kiesa

Daniel Rieden

Staff

Detroit Historic District Commission

THIS IS A 3-PAGE FORM - ALL INFORMATION IS REQUIRED FOR PROJECT REVIEW

HISTORIC DISTRICT COMMISSION PROJECT REVIEW REQUEST

Date: 9/8/2020

City of Detroit - Planning & Development Department 2 Woodward Avenue, Suite 808 Detroit, Michigan 48226

Detroit, Mongan 19229	
PROPERTY INFORMATION	
ADDRESS: 1991 Chicago Blvd AKA:	
HISTORIC DISTRICT: Boston-Edison District	
SCOPE OF WORK: Windows/Doors Roof/Gutters/Chimney Porce Deck (Check ALL that apply) New Construction Demolition Addition	Rehab
APPLICANT IDENTIFICATION	
Property Owner/ Homeowner Contractor Tenant or Business O NAME: David Darkowski COMPANY NAME:	Occupant Architect/Engineer/ Consultant Normandy Properties, LLC
ADDRESS: 1991 Chicago Blvd CITY: Ann Arbor	STATE: MI ZIP: 48103
PHONE: 734-545-8546 MOBILE: 734-368-8663	EMAIL: ddarkowski@norfolk-home
PROJECT REVIEW REQUEST CHECKLIST Please attach the following documentation to your request: *PLEASE KEEP FILE SIZE OF ENTIRE SUBMISSION UNDER 30MB* X Completed Building Permit Application (highlighted portion of the permit Number (only applicable if you've already a for permits through ePLANS) X Photographs of ALL sides of existing building or site	additional documentation may
Detailed photographs of location of proposed work (photographs to show existing condition(s), design, color, & ma	
Description of existing conditions (including materials and	design)
Description of project (if replacing any existing material(s), replacementrather than repairof existing and/or constructions.	
✓ Detailed scope of work (formatted as bulleted list)	
Brochure/cut sheets for proposed replacement material(s)	and/or product(s), as applicable
Upon receipt of this documentation, staff will review and inform you of the next ste	eps toward obtaining your building permit from the

SUBMIT COMPLETED REQUESTS TO HDC@DETROITMI.GOV

Buildings, Safety Engineering and Environmental Department (BSEED) to perform the work.

P2 - BUILDING PERMIT APPLICATION

				Date: 9/8/2020
PROPERTY INFORM	ATION			
Address: 1991 Chicago		Floor:	Suite	e#:Stories:
AKA:		Lot(s):	Subdi	vision:
Parcel ID#(s):	Tota	al Acres:	Lot Width:	Lot Depth:
Current Legal Use of Prop				
Are there any existing bui				
PROJECT INFORMA	TION			
Permit Type:		Addition	Demolition	Correct Violation
Foundation Only	the state of the s			
Revision to Original Pe				
Description of Work				
Remove deteriorating mass				
reduce columns from 4 to 2	. Two interior column	s are rotted and bey	ond repair.	
		MBC us	se change	No MBC use change
Included Improvements	(Check all applicable;	these trade areas req	uire separate per	mit applications)
HVAC/Mechanical	Electrical	Plumbing F	ire Sprinkler S	ystem Fire Alarn
Structure Type		1 1 1 1		
New Building	xisting Structure	Tenant Space	Garage	/Accessory Building
Other:				
Construction involves cha				
(e.g. interior demolition or con				
Use Group:		ction (per current MI)	Bldg Code Table	601)
Estimated Cost of Const			\$	
Structure Use	· ·	By Contractor		By Department
Residential-Number of Uni	ts: Office-C	iross Floor Area	Industr	ial-Gross Floor Area
Commercial-Gross Floor A				
Proposed No. of Employees:				
PLOT PLAN SHALL BE sub				
(must be correct and in de-	tail). SHOW ALL stree	ets abutting lot, inc	dicate front of	ot, show all buildings,
existing and proposed dist				s on Next Page)
		Department Use		
Intake By:		Date:	Fees Due:	DngBld? No
Permit Description:				
Current Legal Land Use:		Propos	ed Use.	
Permit#:				
				st. \$
Lots Combined?				
Revised Cost (revised perm				\$
Structural:				
Zoning:				
Other:		Date:	Notes:	

P2 - BUILDING PERMIT

Permit #:

Page 1 of 2

IDENTIFICATION (All Fields Property Owner/Homeowner	The same of the sa	ty Owner/Hom	neowner is Permit	Applicant		
Name: David Darkowski			me: Normandy F			
Address: 8178 Jackson Rd, Ste						
				Zip. 40100		
		Mobile: 734-368-8663 Email: ddarkowski@norfolk-homes.com				
			SW3KI@HOHOIK-H	omeo.com		
Contractor Contractor i			In the D.C.	onstruction		
Representative Name: Brent Virk						
Address: 2465 LaSalle Garden	5 50UIII	203	State: IVI	athed com		
Phone: 586-854-9203 Mo	bile: 360-634-8	Em	iall: Dient@restore	stried.com		
City of Detroit License #: LIC202	10-00674					
TENANT OR BUSINESS OC	CUPANT	Tenant is P	ermit Applicant			
Name: Ph						
ARCHITECT/ENGINEER/CO						
Name:						
Address:		City:	State:	Zip:		
Phone: Mo	bile:	E	mail:			
HOMEOWNER AFFIDA	VIT (Only require	ed for residential	permits obtained by he	omeowner.)		
inspections related to the installation other person, firm or corporation a Print Name: (Homeowner)	ny portion of the	e work covered	by this building p	ermit.		
Subscribed and sworn to before me t						
Signature:(Notar	y Public)					
F	PERMIT APPLIC	ANT SIGNAT	URE			
I hereby certify that the information restrictions that may apply to this certify that the proposed work is at to make this application as the proposed all applicable laws and ordinances inspections are requested and contemporarily provided provi	construction and authorized by the operty owner(s) is of jurisdiction. onducted within expired permi	d am aware of e owner of the authorized age I am aware th n 180 days of its cannot be	my responsibility to record and I have ent. Further I agree at a permit will ex	hereunder. I been authorized to conform to spire when no nce or the date of		
Print Name: David Darkowski (Permit Applicant)	Signat	ure:		Date: 9/8/2020		
Driver's License #: D 622 135 67			1/17/2024			
Subscribed and sworn to before me t	his 8 day of	Sept 20 2	20 A.D. Oaklein	County, Michigan		
Signature: Ilalatura	Dus 1	My Commission		126		
(Notary Pub)	c)	acting	in Washt	enaw Coun		
Section 23a of the state prohibits a person fro state relating to per residential stru	m conspiring to	code act of 19 o circumvent to o perform wo	772, 1972PA230, I the licensing requi	MCL 125.1523A, rements of this building or a		

This application can also be completed online. Visit detroitmi.gov/bseed/elaps for more information.



1991 West Chicago Blvd Detroit, MI

The following details didn't change:

- 1. Porch roof. Nothing changed to the porch roof. Hence, no work was done to the porch roof.
- 2. Upper railing. Just restored as noted below.
- 3. Limestone "rim" of the porch slab was salvaged and used in place.
- Outer pair of columns supporting porch roof. The outer columns at the front corners of the porch were saved and restored/repaired. The columns on the rear corners of the porch are also original.
- Shutters. Shutters are original to the home and were restored back to the original color that existed under the current white color.
- Windows. All windows were restored throughout the home. Each window was taken apart, resized, new historic chain and hardware installed and glass replaced where needed.
- Roof Color. The front facing surface of the roof had been replaced sometime prior to our purchase of the home.
- 8. Light on underside of porch roof. The original underside light was repaired and re-installed.

The following items were changes made to front elevation:

- 1) Wings of porch removed. The wings were collapsing due to failing footings (See attached photo). The wings could not have been repaired. They would have had to be completely re-built. In order for us to do so we would have had to dig out the old footings and pour new ones and re-build from that point. Rebuilding the wings would have added \$20,000 to the cost of the porch rebuild. This would not have made financial sense considering the value of the home. The main porch's footings were in good shape so we were able to just rebuild the brick work etc. for the center porch. In respect to the old footings, we dug them out and removed to accommodate installation of the new landscaping and grading from the exterior walls of the house. We also used as much of the original porch materials as possible in the re-build which is evident in the photos.
- 2) Railings on wings of porch removed. The railing was corroded and damaged, but intact, on the left wing but none attached to the right. The vintage of the railing was undetermined.
- 3) Columns reduced from 4 to 2. The two interior columns were rotted out and could not be salvaged. The exterior columns were able to be salvaged and re-built/repaired.
- 4) The shutter color was changed from white to green. The shutters were returned to their original color (or at least the last color they were prior to being painted white) We color matched the green to what color was under the white so we're not sure what the exact color is.
- 5) The railing above the roof over the porch changed from white to black. The same thought process was applied as was to the shutters. The original color of the railing was black. We returned it to its original color. We also restored them to the extent possible as there was a lot of rust, etc.

A list of specific materials used:

Front porch brick manufacturer and color. We used re-claimed brick from I believe Belding Masonry. We took one of the original bricks and matched it to the best extent possible.

Mortar manufacturer and color. We color matched the current mortar of the house.

Porch paint manufacturer and color. I believe it was Behr Premium. It was color matched to the existing white.

Shutter paint manufacturer and color. I believe it was Behr Premium. It was color matched to the original green color.

The area exposed on front of house where porch wings used to be was painted with an effort to color match to the existing brick.

From: David Darkowski [mailto:DDarkowski@norfolk-homes.com]

Sent: Tuesday, September 8, 2020 7:48 PM

To: Jennifer Ross < rossi@detroitmi.gov >; Brendan Cagney < cagneyb@detroitmi.gov >

Cc: Daniel Garan < garand@detroitmi.gov > Subject: [EXTERNAL] RE: 1991 W Chicago

Good Evening Jennifer,

Attached you will find our completed application for approval from the HDC, as it relates to 1991 W Chicago. Based on the poor condition of the front porch, we were forced to demolish portions of it, to make it safe, as required by the Detroit Land Bank. We do understand that we did not received HDC approval, prior to the demo, however, it is our intention to work with the HDC to resolve any concerns that they may have. The Building Department has currently ticketed us for removal of the porch without HDC and the Building Department approval, if possible, we would like to receive approval from the HDC for the demolition work (since it's completed), so that we can clear up that item, while we work to a resolution on the balance of the approval by the HDC.

I would welcome the opportunity to meet with you to discuss the work that's been completed thus far, and where we go from here.

Please let me know your availability. I'd also like to bring my contractor with me as well.

Thank you so much for the help.

David Darkowski Normandy Properties 734.368.8663 Mobile 734.545.8546 Direct 734.408.0780 Fax

1991 West Chicago Boulevard

Detroit, Michigan

Index

A1.0 INDEX, SITE PLAN


A1.1 PARTIAL PLANS, SECTION, ELEVATIONS

• •

Building Data


USE GROUP: SINGLE FAMILY HOME
CONSTRUCTION TYPE: V

Location




02/20/2020

OWNER
NORMANDY PROPERTIES LTD



1991 West Chicago Boulevard 02-20-2020

A10 INDEX, SITE PLAN



Too I Woot Officago Dulle Valu 02-20-2020

A1.1 PARTIAL PLANS, SECTION, ELEVATIONS



North/ Front Elevation



South/ Rear Elevation



West/ Right Elevation



East/ Left Elevation



North/Front Elevation (BEFORE) 1974



North/Front Elevation (AFTER) 2020





North/Front Elevation (BEFORE) 2017



Front Porch Detail (BEFORE) 2017




Front Porch Detail (AFTER) 2020

1991 CHICAGO BLVD NOW



Front Porch Details (AFTER) 2020




Rear Elevation 2020

STAFF SITE VISIT PHOTOS: 1991 Chicago, Detroit, MI OCTOBER 1, 2020



North/ Front Elevation

STAFF SITE VISIT PHOTOS: 1991 Chicago, Detroit, MI OCTOBER 1, 2020




Northwest/ Front-Right Elevation

STAFF SITE VISIT PHOTOS: 1991 Chicago, Detroit, MI OCTOBER 1, 2020



Northeast/ Front-Left Elevation
Rear Elevation 2020






Since 1984, Digger Specialties, Inc. (DSI) has manufactured the highest quality building materials in the industry.


DSI is constantly improving and innovating to bring better products to the marketplace, including Composite and Fiberglass Columns.

Composite and Fiberglass Columns are available in three different finishes to meet your installation and design needs. The Standard, ready to paint column, comes in a mill finish ready for finishing and painting. The Caulk-N-Walk column is ready to install just caulk and walk away. The Pre-Finished Column provides both beauty and durability. Our innovative state of the art coating process provides a ready to install column, including coated capital and base, which eliminates the need for onsite prep and painting.

All Composite and Fiberglass Column products feature heavy duty packaging to resist transit and jobsite damage and are backed by a Lifetime Limited Warranty. DSI offers the first Pre-Finished Architectural Coated Column Warranty in the industry.



COMPOSITE UND COLUMNS



ROUND SMOOTH TAPERED

Tuscan Columns are one of the most recognizable architectural elements in the world. From the historical cities of Europe to the cities and towns of the United States, these columns and their elegant style are celebrated by architects the world over.

Round Columns are available in smooth tapered and nontapered and fluted tapered.

[A	c
1		
L	В	

- A Top Outside Diameter
- **B** Bottom Outside Diameter
- C Neck Ring Height

Column Size	Outside Diameter Top (A)	Inside Diameter Top	Outside Diameter Bottom (B)	Inside Diameter Bottom	Taper from Bottom	Material Thickness	Neck Ring Height (C)
6"x8'	5 1/8"	4 3/8"	6"	5 1/4"	45"	3/8"	4"
8" x 5'	6 1/8"	5 3/8"	7 5/8"	6 7/8"	15"	3/8"	5"
8"x6'	6 1/8"	5 3/8"	7 5/8"	67/8"	27"	3/8"	5"
8"x8'	6 1/8"	5 3/8"	7 5/8"	67/8"	31"	3/8"	5"
8"x9'	6 1/8"	5 3/8"	7 5/8"	67/8"	26"	3/8"	5"
8"x 10'	6 1/8"	5 3/8"	7 5/8"	6 7/8"	38"	3/8"	5"
10"x 6'	8"	7 1/4"	9 5/8"	8 7/8"	6"	3/8"	5 7/8"
10"x 8'	8"	7 1/4"	9 5/8"	8 7/8"	30"	3/8"	5 7/8"
10"x 9'	8"	7 1/4"	9 5/8"	8 7/8"	24"	3/8"	5 7/8"
10"x 10'	8"	7 1/4"	9 5/8"	8 7/8"	36"	3/8"	5 7/8"
10"x 12'	8"	7 1/4"	9 5/8"	8 7/8"	62"	3/8"	5 7/8"
12" x 6'	9 3/8"	8 5/8"	11 1/2"	10 3/4"	8"	3/8"	7 3/4"
12"x 8'	9 3/8"	8 5/8"	11 1/2"	103/4"	32"	3/8"	7 3/4"
12"x 9'	9 1/2"	8 3/4"	11 1/2"	10 3/4"	29"	3/8"	7 3/4"
12"x 10'	9 1/2"	8 3/4"	11 1/2"	103/4"	41"	3/8"	7 3/4"
12"x 12'	9 5/8"	8 7/8"	11 5/8"	10 7/8"	40"	3/8"	7 3/4"
12"x 14'	9 5/8"	8 7/8"	11 5/8"	10 7/8"	48"	3/8"	7 3/4"
12"x 16'	9 5/8"	8 7/8"	11 5/8"	107/8"	72"	3/8"	7 3/4"
14" x 8'	12"	11 1/4"	13 7/8"	13 1/8"	22"	3/8"	8 1/8"
14" x 9'	12"	11 1/4"	13 7/8"	13 1/8"	34"	3/8"	8 1/8"
14" x 10'	12"	11 1/4"	13 7/8"	13 1/8"	46"	3/8"	8 1/8"
14" x 12'	12"	11 1/4"	14"	13 1/4"	26"	3/8"	8 1/8"
14" x 14'	12"	11 1/4"	14"	13 1/4"	50"	3/8"	8 1/8"
14" x 16'	12"	11 1/4"	14"	13 1/4"	74"	3/8"	8 1/8"
14" x 18'	12"	11 1/4"	14"	13 1/4"	98"	3/8"	8 1/8"
16" x 8'.	13 3/4"	12 3/4"	15 3/4"	14 3/4"	31"	1/2"	8 1/2"
16"x 9'	13 3/4"	12 3/4"	15 3/4"	143/4"	43"	1/2"	8 1/2"
16" x 10'	13 3/4"	12 3/4"	15 3/4"	14 3/4"	55"	1/2"	8 1/2"
16" x 12'	13 3/4"	12 3/4"	15 3/4"	143/4"	36"	1/2"	9"
16" x 14'	13 3/4"	12 3/4"	15 3/4"	14 3/4"	60"	1/2"	9"
16"x 16'	13 3/4"	12 3/4"	15 3/4"	14 3/4"	84"	1/2"	9"
16" x 18'	13 3/4"	12 3/4"	15 3/4"	14 3/4"	108"	1/2"	9"
18"x 8'	15 3/8"	14 3/8"	17 1/4"	16 1/4"	12"	1/2"	11 5/8"
18"x 9'	15 3/8"	14 3/8"	17 1/4"	16 1/4"	24"	1/2"	11 5/8"
18" x 10'	15 3/8"	14 3/8"	17 1/4"	16 1/4"	36"	1/2"	11 5/8"
18"x 12'	15 3/8"	14 3/8"	17 1/4"	16 1/4"	60"	1/2"	11 5/8"
18"x 14'	15 1/4"	14 3/8"	17 5/8"	16 3/8"	28"	1/2"	11 1/2"
18" x 16'	15 1/4"	14 1/4"	17 5/8"	16 3/8"	60"	1/2"	11 1/2"
18"x 18'	15 1/4"	14 1/4"	17 5/8"	16 3/8"	84"	1/2"	11 1/2"
18" x 20'	15 1/4"	14 1/4"	17 5/8"	16 3/8"	108"	1/2"	11 1/2"
20"x 12'	16 3/8"	15 3/8"	19 3/4"	18 3/4"	0"	1/2"	10 1/8"
20" x 14"	16 3/8"	15 3/8"	19 3/4"	18 3/4"	17"	1/2"	10 1/8"
20"x 16'	16 3/8"	15 3/8"	19 3/4"	18 3/4"	41"	1/2"	10 1/8"
20"x 18"	16 3/8"	15 3/8"	19 3/4"	18 3/4"	65"	1/2"	10 1/8"
20" x 20'	16 3/8"	15 3/8"	19 3/4"	18 3/4"	89"	1/2"	10 1/8"
20" x 22'	16 3/8"	15 3/8"	19 3/4"	18 3/4"	113"	1/2"	10 1/8"
20" x 24'	16 3/8"	15 3/8"	19 3/4"	18 3/4"	137"	1/2"	10 1/8"
20 x 24 24" x 14'	19 3/4"	18 3/4"	23 3/4"	22 3/4"	10"	1/2"	12 1/8"
24 x 14 24"x 16'	19 3/4"	18 3/4"	23 3/4"				
24" x 18"	19 3/4"	18 3/4"	23 3/4"	22 3/4" 22 3/4"	34" 58"	1/2" 1/2"	12 1/8"
	19 3/4"	18 3/4"	23 3/4"	22 3/4"	82"	1/2"	12 1/8" 12 1/8"
			/ 3 3/4	// 3/4	0/	1//	17 1/8"
24" x 20' 24" x 22'	19 3/4"	18 3/4"	23 3/4"	22 3/4"	106"	1/2"	12 1/8"

AVAILABLE IN Caulk-N-Walk® Plumb Perfect® (kit included) Plumb Perfect® (kit sold separately) Split-Fit® Pilaster Pre-Finished Standard Column, Capital and Base all in one box Seamless Column, except for Split-Fit®

LOAD BEARING: Visit dsicolumns.com for testing information

ROUND CAPITALS

Our standard Tuscan capitals are cast from the same rock hard composite material as our column shaft assuring maximum durability. Although casting capitals from this material requires extra attention to detail, we think you will agree it is worth the effort.

Most sizes of the Tuscan Tapered Capitals are made from Polyurethane. And some sizes are made utilizing a patented process to create a **Snug-Fit** capital. The Polyurethane capital is created with a foam ring for a snug-fit. This capital eliminates the need to purchase a backer rod to close the gap that can occur between the column shaft and the capital. Snug-Fit capitals do not require pilot holes.




NON-TAPERED TUSCAN CAPITALS

Column Size	Width	Height	Inside Diameter	Diagonal
8"	9 1/8"	2 1/2"	7 11/16"	13"
10"	12 1/4"	3 1/8"	9 7/8"	17 5/16"
12"	14"	3 1/2"	11 3/4"	20"
14"	16 3/4"	3 1/2"	14 1/8"	23 3/4"
16"	19 1/16"	5 1/8"	16 1/4"	27"

TAPERED TUSCAN CAPITALS



Column Size	Width	Height	Inside Diameter	Diagonal
Polyurethan	ne .			
6"	8"	2 1/4"	5 1/4"	11"
8"	9 1/8"	2 1/2"	6 1/4"	13"
10"	12 1/4"	3 1/2"	8 1/8"	17-5/16"
12"	14"	4 1/2"	9 5/8"	20"
14"	16 3/4"	4 1/2"	12 1/8"	23 3/4"
16"	19 1/16"	5 1/8"	14"	27"
Composite				
18"	21 1/4"	5 3/4"	15 3/4"	30"
20"	24 3/8"	5 5/8"	16 3/4"	34 1/2"
24"	27 3/4"	7 5/8"	20 1/2"	39 1/4"



ROUND BASES

Standard Doric bases and optional Attic bases are made from the same material as our column shafts assuring maximum durability. This material provides superior performance withstanding punishment from snow shovels, weed eaters, pressure washers and general wear and tear.



DORIC BASES*


Column Size	Width	Height	Inside Diameter	Diagonal
6"	8"	3"	6 1/4"	11 1/4"
8"	10"	4 1/8"	7 11/16"	14"
10"	13 1/8"	5 5/8"	9 7/8"	18 15/16"
12"	15 3/8"	6 5/16"	11 3/4"	21 3/4"
14"	18 5/8"	7 1/4"	14 1/8"	26 5/16"
16"	21 1/4"	8 1/8"	16 1/4"	30 1/16"
18"	24"	9 1/4"	18"	33 7/8"
20"	26 1/2"	11"	20 1/8"	37 5/8"
24"	32 1/4"	13 1/2"	24"	45 5/8"



ATTIC BASES

Column Size	Width	Height	Inside Diameter	Diagonal
8"	10 3/8"	4 5/8"	7 3/4"	14 5/8"
10"	13"	5 5/8"	9 7/8"	18 3/8"
12"	15 7/8"	6 3/8"	12"	22 1/2"
14"	19 1/4"	8 3/8"	14 3/8"	27 1/4"
16"	21"	8 3/4"	16"	29 1/2"
18"	24"	10 1/4"	17 3/4"	34"





*Use Doric Base as the Capital for Non-Tapered 18", 20", and 24" Columns.

PACKAGING

Nothing increases the cost of a project more than delays. Delays can occur when the column arrives damaged, or the capital and base sets are separated from the order.

DSI takes great care in packaging our Columns. Most sizes are packaged with the complete shaft, capital, and base in one box. The column shaft is "cradled" in the box with foam rings to resist damage.





INSTALLATION KITS AND HARDWARE

OPTIONAL BRACKET KITS

Optional bracket kits contain 6 round brackets or 4 square brackets and screws.

The Round and Square Bracket Kits assist in the prevention of column kick-out.





OPTIONAL SPLIT-FIT® REASSEMBLY KITS

Optional Split-Fit® Reassembly kits include Adhesive Cartridge with Adapter and (1) Roll of 3M/Scotch Bonding Tape.



TECHNICAL PRODUCT DATA

LOAD-BEARING SPECIFICATIONS

Load-Bearing specifications are listed on the DSI Website, *dsicolumns.com*.

Load limits are specific to a product's diameter or profile and predicated on 100% coverage at the top and bottom of a column.

FIRE RATED PRODUCT

DSI has fire rated products available upon request. Our fire rated products have received Class A Certification through testing for flame spread and smoke developed standards set forth in the ASTM E84 Test.





Composite & Fiberglass Column Load Ratings

Model	Size	Length	Tested Height	Ultimate Load					
Square Smooth Composite Columns were tested using Concentric Loading									
Square Smooth	6"	8' & 9'	9'	40,000 lbf					
Square Smooth	8"	8', 9', & 10'	10'	44,000 lbf					
Square Smooth	10"	8', 9', & 10'	10'	40,000 lbf					
Square Smooth	12"	8', 9', 10', & 12'	12'	61,000 lbf					
Round Smooth Taper	ed Composite	Columns were tested	using Concentri	c Loading					
Round Smooth Tapered	6"	6', 7', & 8'	8'	41,000 lbf					
Herculite Square Smooth	Herculite Square Smooth Pultruded Fiberglass Columns were tested using Eccentric Loading								
Hercultie Square Smooth	8"	8', 9', & 10'	10'	28,829 lfb					
Herculite Square Smooth	10"	8', 9', & 10'	10'	28,160 lbf					
Herculite Square Smooth	12"	8', 9', 10', & 12'	12'	39,303 lbf					
Round Smooth Tapered larg	ger than 6" Coi	mposite Columns were	e tested using E	ccentric Loading					
Round Smooth Tapered	8"	8'	8'	27,000 lbf					
Round Smooth Tapered	8"	9'	9'	27,000 lbf					
Round Smooth Tapered	8"	10'	10'	22,000 lbf					
Round Smooth Tapered	10"	8'	8'	25,000 lbf					
Round Smooth Tapered	10"	9'	9'	43,000 lbf					
Round Smooth Tapered	10"	10'	10'	38,000 lbf					
Round Smooth Tapered	12"	8'	8'	32,000 lbf					
Round Smooth Tapered	12"	9'	9'	36,000 lbf					
Round Smooth Tapered	12"	10'	10'	50,000 lbf					

Weight values are ultimate load - Saftey factors have not been applied to this value.



800-446-7659

