## Wrap Wood Fascia and Soffits with Dark Brown Aluminum - Facade



Above: "Before". Areas of soffit and fascia at front entry. 🗙

Notice profile of front porch gable trim at left. Wood components were not deteriorated beyond repair.

Below: "After".

Highly profiled fascia is gone; sheen of aluminum material is highly visible. New soffit has a repeating horizontal pattern, which was not part of the original wood soffit.




## Wrap Wood Fascia and Soffits, with Dark Brown Aluminum – Gable wall Similar "before" and "after" comment from the front elevation. Note also the small, yet important detail of the rakeboard that has been lost.







**Rear Railings**Raised patio, rear entry and second floor rear porch railings were replaced. Applicant photos.



Removal of Front French door railings.
"Before" photo, Google street view, August 2015. Remaining photos were provided by the applicant.









Replacement of steel windows with vinyl windows - Facade

## East side wall – Window replacement






# West side wall – Window Replacement

## Rear Wall – Window Replacement indalihanilalahan kalentari

## **New exterior doors - Rear**

Applicant claims the white doors were in place at time of house purchase. Staff didn't find any previous HDC review for the white steel doors.



## East side wall

