

## **HDC STAFF-SUMMARY OF WORK**

**ADDRESS:** 1676 CHICAGO BOULEVARD

**MEETING DATE:** 2/11/2026

**APPLICATION NUMBER:** HDC2026-00021

**HISTORIC DISTRICT:** BOSTON EDISON

**APPLICANT/ARCHITECT:** ALISSA JACOBS/4545 ARCHITECTURE

**OWNER:** GCG CLB 28 LLC

**DATE OF PROVISIONALLY COMPLETE APPLICATION:** 01/20/2026

**SCOPE PHRASE FOR AGENDA:** REHABILITATE EXTERIOR

**PUBLIC HEARING PER 21-2-77:** NO

### **STAFF SUMMARY OF SCOPE OF WORK:**

Based on staff review of the submitted documents, the following work is proposed:

- **SITE**

- Remove two trees at front yard
- Erect wood fence at rear yard (work completed)
- At front yard, install foundation plantings/shrubs to replace landscaping that was removed without HDC approval

- **HOUSE**

Roof

- At dormer roof, replace asphalt shingles with rubber membrane
- At dormers where windows are missing, install single hung, aluminum-clad wood units with simulated divided lites (SDL), Andersen E- series
- Install aluminum half-round gutters and downspouts
- Replace dentilated wood soffit (work completed)
- 

Front Façade

- Retain and repair existing wood windows and trim/brickmould
- Replace front brick, concrete, and tile porch with concrete and brick porch (work completed)
- Install new 3'-0" tall, wood guardrail at porch to replace wrought iron railing that was removed without HDC approval
- Replace wood pilasters which flank the front door with new wood pilasters (work completed)
- Install a new aluminum-clad wood arched transom with SDL (Andersen E- series) over the front door to replace missing transom. Fanlight pattern (work initiated)

- Replace two columns at front porch with aluminum clad columns (work completed)
- Repair flashing at bay roof

East/Side

- Retain and repair all but one existing wood windows and trim/brickmould
- Replace one existing wood window with aluminum-clad wood window (6/1. SDLs)
- Install a new aluminum-clad wood arched transom with SDLs at the second story bay to replace missing transom. Fanlight pattern. At third story, install two aluminum-clad wood casement units with SDLs
- At first story, install a new aluminum door with vision panel
- Install glass block at basement windows

Rear

- Install a 3'-0" tall, wood guardrail at roof of enclosed porch.
- Install glass block at basement windows
- At first story of enclosed porch, install an aluminum door with vision pane

West/Side

- Install glass block at basement windows
- At dormer, install a fixed aluminum-clad window with SDL to replace missing window

Front/Sides/Rear

- Tuckpoint where necessary
- Paint wood trim and windows per submission

• **GARAGE**

- Tuckpoint where necessary
- Retain and repair existing windows
- Install new aluminum gutters and downspouts
- Replace original fascia and soffit with new wood (work initiated)

**MISSING INFORMATION, CLARIFICATION, OR OTHER ISSUES RELATING TO A COMPLETE SCOPE OF WORK:**

None