

Figure #1: Exterior, Looking West. 5/31/19



Exterior #2: Exterior, Looking Southwest. 10/15/2019



Figure #3: Exterior, Looking Northwest. 10/15/19





Figure #4: Exterior, Looking up. 7/17/19



Figure #5: Exterior, Looking West. 7/17/19



Figure #6: Exterior, Looking West. 10/15/19



Figure #7: Exterior, Looking Up. 10/15/19



Figure #8: Exterior, Looking West. 10/15/19



Figure #9: Exterior, Looking West.. 10/15/19



Figure #10: Exterior, Detail, Looking Up. 10/15/19



Figure #11: Exterior, Looking Up. 10/15/19



Figure #12: Exterior, Detail, Looking West. 10/15/19



Figure #13: Exterior, Detail, Looking West. 10/15/19



Figure #14: Exterior, Detail, Looking West. 10/15/19



Figure #15: Exterior, Detail, Looking West. 10/15/19



Figure #16: Exterior, Looking Southwest. 7/17/19



Figure #17: Exterior, Looking Southwest. 7/17/19



Figure #18: Exterior, Looking Up. 7/17/19



Figure #19: Exterior, Looking Northwest. 7/17/19



Figure #20: Exterior, Detail, Looking West. 10/15/19



Figure #21: Exterior, Canopy, Looking up. 10/15/19



Figure #22: Exterior, Canopy, Looking Up. 10/15/19



Figure #23: Exterior, Canopy Detail, Looking North. 10/15/19



Figure #24: Exterior, Canopy Detail, Looking North. 10/15/19



Figure #25: Exterior, Canopy, Looking North. 10/15/19



Figure #26: Exterior, Canopy, Looking Northwest. 7/17/19



Figure #27: Exterior, Canopy Detail of Plaster Underside, Looking Up. 7/17/19




Figure #28: Exterior, Mezzanine Glass Block, Looking West. 10/15/19



Figure #29: Exterior, Storefront and Canopy Detail, Looking Northwest. 10/15/19



Figure #30: Exterior, Looking Northwest. 10/15/19




Figure #31: Exterior, Alley, Looking North. 10/15/19



Figure #32: Exterior, Alley and West Façade, Looking Southeast. 10/15/19



Figure #33: Exterior, Alley, Looking Up. 5/31/19



Figure #34: Exterior, Alley, Looking Northeast. 5/31/19



Figure #35: Exterior, Alley Façade, Looking Northeast. 10/15/19



Figure #36: Exterior, Alley Façade Window, Looking East. 10/15/19



Figure #37: Exterior, Alley Façade Knee Wall, Looking Down. 10/15/19




Figure #38: Exterior, Alley Façade, Looking Up. 10/15/19



Figure #39: Exterior, Alley Façade Door. 10/15/19



Figure #40: Exterior, Alley façade windows, Looking East. 10/15/19



Figure #41: Exterior, Alley Façade, Looking Up. 10/15/19



Figure #42: Exterior, Alley Façade, Looking Southeast. 10/15/19



Figure #43: Exterior, Alley Façade, Looking East. 10/15/19



Figure #44: Exterior, Fire Escape, Looking Up. 10/15/19



Figure #45: Exterior, Fire Escape, Looking Up. 10/15/19




Figure #46: Exterior, Alley Façade, Looking Up. 10/15/19




Figure #47: Exterior, Alley Façade and Fire Escape, Looking Up. 10/15/19



Figure #48: Interior, 1st Floor Storefront, Looking Northeast. 10/15/19



Figure #49: Interior, 1st Floor Storefront, Looking Up. 10/15/19



Figure #50: Interior, 1st Floor Storefront Window into Vestibule, Looking South. 10/15/19




Figure #51: Interior, Mezzanine Windows, Looking Northeast. 5/31/19



Figure #52: Interior, Mezzanine Glass Block, Looking Northeast. 10/15/19



Figure #53: Interior, Mezzanine Glass Block, Looking 10/15/19



Figure #54: Interior, 2nd floor, Looking East. 10/15/19



Figure #55: Interior, 2nd floor, Looking East. 7/17/19



Figure #56: Interior, 2nd floor, Looking East. 10/15/19



Figure #57: Interior, 2nd floor, Window Detail. 10/15/19



Figure #58: Interior, 2nd floor, Looking West. 7/17/19



Figure #59: Interior, 2nd floor, Window Detail. 10/15/19




Figure #60: Interior, 3rd floor, Window Detail, Looking Northeast. 5/31/19



Figure #61: Interior, 3rd Floor, Looking East. 10/15/19



Figure #62: Interior, 3rd Floor, Window Detail. 10/15/19



Figure #63: Interior, 3rd Floor, Window Detail. 10/15/19



Figure #64: Interior, 3rd Floor, Window Detail. 10/15/19



Figure #65: Interior, 3rd floor, Window Detail. 10/15/19



Figure #66: Interior, 3rd floor, Window Detail. 7/17/19




Figure #67: Interior, 3rd floor, Window Detail. 5/31/19



Figure #68: Interior, 4th floor, Looking Northeast. 5/31/19



Figure #69: Interior, 4th floor, Window Detail. 10/15/19



Figure #70: Interior, 4th floor, Looking East. 10/15/19



Figure #71: Interior, 4th floor, Window Detail. 10/15/19



Figure #72: Interior, 4th floor, Window Detail. 10/15/19



Figure #73: Interior, 5th floor, Window Detail, Looking East. 10/15/19



Figure #74: Interior, 5th floor, Looking southeast. 7/17/19



Figure #75: Interior, 5th floor, Window Detail, Looking Down. 10/15/19



Figure #76: Interior, 6th floor, Looking Northeast. 7/17/19



Figure #77: Interior, 6th floor, Window Detail, Looking Down. 10/15/19



Figure #78: Interior, 7th floor, Window Detail. 10/15/19



Figure #79: Interior, 7th floor, Looking Down. 10/15/19



Figure #80: Interior, 8th floor, Looking Southeast. 10/15/19



Figure #81: Interior, 8th floor, Window Detail. 10/15/19



Figure #82: Interior, 8th floor, Looking West. 10/15/19



Figure #83: Interior, 8th floor, Window Detail. 10/15/19



Figure #84: Exterior, Roof, Looking North.7/17/19



Figure #85: Exterior, Roof, Looking East. 7/17/19



Figure #86: Exterior, Roof, Looking East. 7/17/19



Figure #87: Exterior, Rooftop with Penthouses. 2013



Figure #88: Exterior, Water tower, Looking up. 6/12/20



Figure #89: Exterior, Roof and Penthouse, Looking Northwest. 6/12/20



Figure #90: Exterior, Penthouse and Roof, Looking West. 6/12/20



Figure #91: Exterior – 1920s



Figure #92: Exterior – lightened for detail - 1920s



Figure #93: Cornice detail zoomed in from previous photo #92 – 1920s



Figure #94: Old storefront zoom from previous photo #92 - 1920s



Figure #95: Exterior – Date Unknown



THE NEW STREAMLINED ENTRANCE AND DISPLAY WINDOWS UNDER A GLEAMING NEW MARQUEE AT KLINES

Figure #96: Exterior photograph - Loewy Design - 1940



Figure #97: Exterior rendering - Loewy Design - 1940



Figure #98: Exterior – Loewy Storefront - 1954



Figure #99: Exterior zoom of prior photograph #98 - 1954



Figure #100: Canopy detail – 1950s



EXTERIOR OF KLINE'S WOMEN'S FASHIONS, 1958. Kline's was founded by Eugene B. Kline in 1911 at 1225 Woodward Avenue. With a streamlined entrance and display windows under a gleaming marquee, it was called the most modern store in the country in 1940. Merchandise was housed on eight floors. In 1958, Kline's was acquired by City Specialty Stores, operators of Franklin Simon Stores. Many shoppers found outstanding bargains during Downtown Detroit Days in the famous Franklin Simon Attic on the sixth floor. The store closed in 1977 and was succeeded by Pam's Fashions and later a beauty supply store. (Courtesy Central Business District Foundation.)

Figure #101: Exterior - 1958