THIS IS A 3-PAGE FORM - ALL INFORMATION IS REQUIRED FOR PROJECT REVIEW

HISTORIC DISTRICT COMMISSION PROJECT REVIEW REQUEST

Date: 9/8/2020

City of Detroit - Planning & Development Department 2 Woodward Avenue, Suite 808 Detroit, Michigan 48226

Detroit, mongan 1922	
PROPERTY INFORMATION	
ADDRESS: 1991 Chicago Blvd AK	A:
HISTORIC DISTRICT: Boston-Edison District	
(Check ALL that apply) New Chimney Doors	orch/ Landscape/Fence/ General Rehab
APPLICANT IDENTIFICATION	
	or Architect/Engineer/ Ss Occupant Consultant E: Normandy Properties, LLC
ADDRESS: 1991 Chicago Blvd CITY: Ann Arbor	STATE: MI ZIP: 48103
PHONE: 734-545-8546 MOBILE: 734-368-8663	EMAIL: ddarkowski@norfolk-home
PROJECT REVIEW REQUEST CHECKLIST Please attach the following documentation to your request: *PLEASE KEEP FILE SIZE OF ENTIRE SUBMISSION UNDER 30MB X Completed Building Permit Application (highlighted portion of the permit Number (only applicable if you've already for permits through ePLANS) X Photographs of ALL sides of existing building or site	tions only) Based on the scope of work, additional documentation may
Detailed photographs of location of proposed work (photographs to show existing condition(s), design, color, & n	
Description of existing conditions (including materials a	nd design)
Description of project (if replacing any existing material(s replacementrather than repairof existing and/or constru	
✓ Detailed scope of work (formatted as bulleted list)	
Brochure/cut sheets for proposed replacement material(s) and/or product(s), as applicable
Upon receipt of this documentation, staff will review and inform you of the next	steps toward obtaining your building permit from the

SUBMIT COMPLETED REQUESTS TO HDC@DETROITMI.GOV

Buildings, Safety Engineering and Environmental Department (BSEED) to perform the work.

P2 - BUILDING PERMIT APPLICATION

				Date: 9/8/2020
PROPERTY INFORM	ATION			
Address: 1991 Chicago		Floor	: Suite	e#:Stories:
AKA:		Lot(s):	Subdi	vision:
Parcel ID#(s):	Tota	Acres:	Lot Width:	Lot Depth:
Current Legal Use of Prop				
Are there any existing bui				
PROJECT INFORMA	TION			
Permit Type:		Addition	Demolition	Correct Violation
Foundation Only				
Revision to Original Pe				
Description of Work				
Remove deteriorating mass				
reduce columns from 4 to 2	. Two interior columns	are rotted and be	yond repair.	
		☐ MBC u	se change	No MBC use change
Included Improvements	(Check all applicable; t	hese trade areas rec	quire separate per	mit applications)
HVAC/Mechanical	Electrical	Plumbing	Fire Sprinkler S	ystem Fire Alarn
Structure Type				
New Building	xisting Structure	Tenant Space	Garage	/Accessory Building
Other:				
Construction involves cha				
(e.g. interior demolition or con				
Use Group:		tion (per current MI	Bldg Code Table	601)
Estimated Cost of Const			\$	
Structure Use		By Contractor		By Department
Residential-Number of Uni	ts: Office-G	ross Floor Area	Industr	ial-Gross Floor Area
Commercial-Gross Floor A				
Proposed No. of Employees:				
PLOT PLAN SHALL BE sub	The second second second			
(must be correct and in de-	tail). SHOW ALL stree	ts abutting lot, in	dicate front of	ot, show all buildings,
existing and proposed dist	The second secon	A		s on Next Page)
		Department Use		
Intake By:		Date:	Fees Due:	DngBld? No
Permit Description:				
Current Legal Land Use:		Propos	ed Use:	
Permit#:				
				st. \$
Lots Combined?				
Revised Cost (revised perm				\$
Structural:				
Zoning:				
Other:		Date:	Notes:	

P2 - BUILDING PERMIT

Permit #:

Page 1 of 2

IDENTIFICATION (All Fields Property Owner/Homeowner	The same of the sa	arty Owne	r/Homeow	mer is Permit	Applicant	
Name: David Darkowski					Properties, LLC	
Address: 8178 Jackson Rd, S						
Phone: 734-545-8546					Zip. 40100	
		Email: ddarkowski@norfolk-homes.com				
			darkows	Ki@HoHoik*H	omes.com	
Contractor Contractor			NI O	In the D.C	onstruction	
Representative Name: Brent Vii						
Address: 2465 LaSalle Garde	15 SOULT	O203	To all l	State: IVI	athed com	
Phone: 586-854-9203 M	obile: 000-004-	-9203	Email:	or entition estore	stiled.com	
City of Detroit License #: LIC20	120-00674					
TENANT OR BUSINESS O	CCUPANT	Ten	ant is Permi	t Applicant		
Name:						
ARCHITECT/ENGINEER/C						
Name:						
Address:		City:		State:	Zip:	
Phone: M	obile:		Email			
HOMEOWNER AFFID	AVIT (Only requi	ired for resi	dential permi	its obtained by h	omeowner.)	
inspections related to the installar other person, firm or corporation Print Name: (Homeowner)	any portion of t	he work o	overed by	this building p	permit.	
Subscribed and sworn to before me						
Signature:(Not	ary Public)		_ iviy comi	mosion Expire.		
	PERMIT APPLI	ICANT SI	GNATURE			
I hereby certify that the informative restrictions that may apply to this certify that the proposed work is to make this application as the pall applicable laws and ordinance inspections are requested and the previous inspection and that	s construction at authorized by the roperty owner(sees of jurisdiction conducted with at expired pern	nd am aw the owner a authoriz I am aw nin 180 d nits canno	are of my recorded agent. It are that a ays of the	esponsibility to ord and I have Further I agree permit will ex	hereunder. I been authorized to conform to spire when no nce or the date of	
Print Name: David Darkowski (Permit Applicar		ature:		-	Date: 9/8/2020	
Driver's License #: D 622 135 6		_	ration: 1/			
Subscribed and sworn to before me	this 8 day	of Sept	20 ZOA	.D. Oaklein	County, Michigan	
Signature: I Calalin /c	ms		mission Exp		126	
(Notary Pub	i)(c)	act	ma in	Washt	enaw Coun	
Section 23a of the sta prohibits a person fr state relating to pe	te construction	to circum to perfo	t of 1972, went the li m work o	1972PA230, licensing requi	MCL 125.1523A, rements of this building or a	

This application can also be completed online. Visit detroitmi.gov/bseed/elaps for more information.








1991 CHICAGO BLUD 2017









1991 CHICAGO BLVD NOW











1991 West Chicago Blvd Detroit, MI

The following details didn't change:

- 1. Porch roof. Nothing changed to the porch roof. Hence, no work was done to the porch roof.
- 2. Upper railing. Just restored as noted below.
- 3. Limestone "rim" of the porch slab was salvaged and used in place.
- Outer pair of columns supporting porch roof. The outer columns at the front corners of the porch were saved and restored/repaired. The columns on the rear corners of the porch are also original.
- Shutters. Shutters are original to the home and were restored back to the original color that existed under the current white color.
- Windows. All windows were restored throughout the home. Each window was taken apart, resized, new historic chain and hardware installed and glass replaced where needed.
- Roof Color. The front facing surface of the roof had been replaced sometime prior to our purchase of the home.
- 8. Light on underside of porch roof. The original underside light was repaired and re-installed.

The following items were changes made to front elevation:

- 1) Wings of porch removed. The wings were collapsing due to failing footings (See attached photo). The wings could not have been repaired. They would have had to be completely re-built. In order for us to do so we would have had to dig out the old footings and pour new ones and re-build from that point. Rebuilding the wings would have added \$20,000 to the cost of the porch rebuild. This would not have made financial sense considering the value of the home. The main porch's footings were in good shape so we were able to just rebuild the brick work etc. for the center porch. In respect to the old footings, we dug them out and removed to accommodate installation of the new landscaping and grading from the exterior walls of the house. We also used as much of the original porch materials as possible in the re-build which is evident in the photos.
- 2) Railings on wings of porch removed. The railing was corroded and damaged, but intact, on the left wing but none attached to the right. The vintage of the railing was undetermined.
- 3) Columns reduced from 4 to 2. The two interior columns were rotted out and could not be salvaged. The exterior columns were able to be salvaged and re-built/repaired.
- 4) The shutter color was changed from white to green. The shutters were returned to their original color (or at least the last color they were prior to being painted white) We color matched the green to what color was under the white so we're not sure what the exact color is.
- 5) The railing above the roof over the porch changed from white to black. The same thought process was applied as was to the shutters. The original color of the railing was black. We returned it to its original color. We also restored them to the extent possible as there was a lot of rust, etc.

A list of specific materials used:

Front porch brick manufacturer and color. We used re-claimed brick from I believe Belding Masonry. We took one of the original bricks and matched it to the best extent possible.

Mortar manufacturer and color. We color matched the current mortar of the house.

Porch paint manufacturer and color. I believe it was Behr Premium. It was color matched to the existing white.

Shutter paint manufacturer and color. I believe it was Behr Premium. It was color matched to the original green color.

The area exposed on front of house where porch wings used to be was painted with an effort to color match to the existing brick.

1991 West Chicago Boulevard

Detroit, Michigan

Index

A1.0 INDEX, SITE PLAN

A1.1 PARTIAL PLANS, SECTION, ELEVATIONS

• •

Building Data


USE GROUP: SINGLE FAMILY HOME
CONSTRUCTION TYPE: V

Location




02/20/2020

OWNER
NORMANDY PROPERTIES LTD



1991 West Chicago Boulevard 02-20-2020

A10 INDEX, SITE PLAN



991 West Unicago Boulevard 02-20-2020

A1.1 PARTIAL PLANS, SECTION, ELEVATIONS