# Overall Site Context

**Cass Henry Historic District** 



Figure #01: Exterior, 2467 and 2447 Cass, Looking West. 10/28/20.



Figure #02: Exterior, Henry Street streetscape, Looking West. 10/28/20.



Figure #03: Exterior, Henry Street streetscape, Looking East. 10/28/20.



Figure #04: Exterior, View from W Fisher Service Drive, Looking Northeast. 10/28/20.



Figure #05: Exterior, Grassy area flanked by 439 Henry, 427 Henry, 2467 Cass, and 2447 Cass, Looking North. 10/28/20.




Figure #06: Exterior, Alley behind Henry Street buildings, Looking East. 10/28/20.




Figure #07: Exterior, Alley between 427 and 439 Henry, Looking South. 10/28/20.



Figure #08: Exterior, Alley between 427 and 439 Henry, Looking South. 10/28/20.

# 2467 Cass

# **Cass Henry Historic District**






Figure #01: Exterior, Overall context, Looking Southwest. 08/23/20.



Figure #02: Exterior, Overall Context, Looking Southwest. 07/28/20.



City of Detroit – Historic District Commission

Figure #03: Exterior, East façade, Looking West. 10/28/20.



Figure #04: Exterior, North facade, Looking South. 10/28/20.



Figure #05: Exterior, South façade, Looking Northwest. 10/28/20.



Figure #06: Exterior, South façade, Looking Northwest. 10/28/20.




Figure #07: Exterior, Western edge of South façade and West façade, Looking Northeast. 10/28/20.



Figure #08: Exterior, East façade first floor main entrance detail, Looking West. 10/28/20.



Figure #09: Exterior, East façade first floor entablature detail, Looking Up. 10/28/20.



Figure #10: Exterior, East façade first floor masonry pier detail , Looking West, 10/28/20.



Figure #11: Exterior, East façade first floor masonry wall, Looking North, 10/28/20.



Figure #12: Exterior, East façade first floor bay window detail, Looking Up, 10/28/20.



Figure #13: Exterior, East façade first floor bay window cornice detail, Looking Up, 10/28/20.




Figure #14: Exterior, East façade stacked porch detail, Looking Southeast, 10/28/20.




Figure #15: Exterior, North façade detail, Looking Up. 08/25/20.



Figure #16: Exterior, North façade first floor masonry infilled opening detail, Looking South. 10/28/20.



Figure #17: Exterior, North façade bay window detail, Looking South. 10/28/20.



Figure #18: Exterior, North façade first floor masonry detail, Looking South. 10/28/20.



Figure #19: Exterior, North façade cornice detail, Looking Up. 10/28/20.



Figure #20: Exterior, South façade, Looking Northeast. 10/28/20.



Figure #21: Exterior, Western edge of North façade and West façade, Looking Southeast. 10/28/20.




Figure #22: Exterior, Historic Newspaper Advertisement, Looking Southwest. Circa 1914.



Figure #23: Exterior, Historic Photograph, Looking Southwest. Undated.