

Property: 1062 Vinewood St Detroit MI 48216

Before: Back wall bathroom window and room window.



After: Back wall bathroom window replaced, and room window removed.



Status: Both windows were falling apart; We want to patch those windows with Masonry work.

Property: 1062 Vinewood St Detroit MI 48216

Before: South wall on the side of the house top two windows. They were cover from the inside by drywall and falling apart.



After: Both top windows removed.



Status: Both windows were falling apart; We want to patch those windows with Masonry work.

Property: 1062 Vinewood St Detroit MI 48216

Before: first floor back left window.



After: First floor back left window removed.



Status: Windows were rotten and falling a part; We want to patch those windows with Masonry work.

Description of existing condition and project.

- All the windows are 100+ year old and are rotten and falling apart. We want to patch those windows with masonry work.
- Materials: Neusd face brick (see pictures below for match)



Detail scope of work

- General Contractor removed old windows and added weather insulation.
- Masonry contractor has been hired to do the work.
- Bricks were picked in a local store (neusd face brick) and matches current and existing brick.