

# 14894 Greenview Rd

## Window Replacement

### Existing condition

-Metal with grid pattern, single pane, wooden framing, partially casement windows (only middle is functional as casement window).

-Almost all painted shut, many have cracked panels, and have rotting wooden framing around the window.

### Description of Project

-Replacement of all windows on first floor, and second floor bathroom window

-Replacement with vinyl double hung windows, with dark grid pattern to preserve grid appearance of current windows

-Replacement is necessary as they increase cost of energy due to lack to insulation. They do not allow for airflow because they do not open. This could also pose a safety concern if there is a fire and escape is not possible through a door.

### Scope of project

- 1) Removal of current first floor and upstairs bathroom windows and wood trim around windows.
- 2) Installation of insulation and vinyl windows
- 3) Clean Up





Inside second story bathroom window

Rotting of trim around second story bathroom window



Window one of three on east side of house



Window two of three on east side of house



Window three of three on east side of house





Window one of two on  
north side of house



Window two of two on  
north side of house





Window one of three on  
south side of house



Window two of three on  
south side of house



Window three of three on  
south side of house



Window on west side of  
house. Right of front door



Window on west side of  
house. Left of front door