

COMMERCIAL

RESIDENTIAL

MAINTENANCE & REPAIR

INSPECTIONS

09/27/22


City of Detroit Historic Project Commission 2 Woodward Ave, Ste 808 Detroit MI 48226

Regarding:

Building Permit Application: **913 Chicago Blvd – Boston Edison District. ePLANS Permit number BLD2022-02869** Removal of Slate roof, installation of CertainTeed PRO Asphalt shingle roofing system.

Request: The planning division requires photos of the existing roof and specifications/details (color, material) of new roofing material to better understand the project scope and what additional applications (if any) may be required from the planning division.

Existing Conditions: Built in 1913, 2.5-story colonial home. The Gable roof featured dark-grey slate with open valleys, slate also featured on the sides of the two dormers. 5" k-style aluminum gutter system in place. The house roof replacement is the subject of this application.








House Roof Replacement: Remove all slate roofing from the house. Install CertainTeed Pro dimensional asphalt shingle, Driftwood in color.

Rationale: The slate size was 12x12", age approximated at 108 years with a typical life expectancy of 80 years. The roof was not well maintained over time having been vacant for many years. The slate was cracked and uneven throughout the roof field with many signs of age and wear apparent including missing and broken tiles, staining, accelerated fade and overall penetration failure. Inside of the home there were damages throughout with some leakage making its way down to the first floor. Damages include but not limited to exterior stucco, window trim, wood floor, walls, and ceilings.









The photos were taken from the ground, the roof was considered too unsafe to climb. I requested close-up photographs from the project managers twice and was denied due to the slate condition and our inability to see the damage to the deck beneath. We could not see where the deck was missing or failed and this also posed huge safety concerns.

Please see below photo of existing garage slate as reference.



Supplemental photos of the garage slate are attached. I am not able to climb as I am not properly insured, but I was able to get a few clearer and more close-up photos from the ground.

This work was completed prior to securing the building permit to do so. This was a decision made by the homeowner to an empathetic project manager who understood the urgency of her situation but is strictly against protocol. This has been addressed with the manager involved and will not happen in the future. Homeowner statement as follows:


- "1. We needed to restore the roof and change from slate to shingles because the roof was leaking in every room (attic, 2nd floor bedrooms, sunrooms, 1st floor, etc). We had water damage everywhere and had to file an insurance claim to restore the home. I would have LOVED to have kept the slate because this is what I fell in love with when I purchased the home back in April, yes April. But, it would have cost us over \$200k to rebuild the entire roof. That is what was needed to save this roof and home.
- 2. As I just stated above, the cost to repair the slate roof is out of my budget and I believe out of everyone's budget. We tried to repair sections. We had a repairman come over that has worked on the home for decades. He worked on a small section of the back on the home all day but said if we truly wanted to repair the damage of years we would need a lot more in-depth and expensive repairs. We waited for a rainfall after our first repair and the roof still leaked In the same places he had worked on. We made the executive decision to not waste our money to continue to have this gentleman come out when it was clear the problems wouldn't be solved by piecemeal patching as we go."

Please see below photos of interior damages provided by the homeowner:













Please see below an estimate for cost to repair one area of the roof. This estimate includes 34' of copper valley with copper drip and the removal of saddle with new slate tie-ins. The area of repair is only one front section of the home and would not address the remaining roofing field, any other penetrations, underlying wood deck damages, or any other failures in the remaining roof. There are also no guarantees with repairs.

Bruttell Roofing, Inc. 2000 10821 CAPITAL . OAK PARK, MI 48237

CONTRACT

(248) 543-3040 • fax (248) 543-5810 Roofing That Works!

PROPOSAL SUBMITTED TO	PHONE DATE		
Lauren Thiel	248-943-3225 May 2, 202		
STREET	EMAN BCC		
913 Chicago Blvd.	Roof Repairs		
CITY, ETATE, ZIP	JOB ADDRESS		
Detroit, MI 48202	Same		

EXAMPLE -

idence 10 Blvd. 148202

ROOF REPAIRS: (See attached roof plan)

34' CORRER VALLET CAL'T WI CORRER DRIP REMOVE CHAMNEL SARRLE

As requested, please find a proposal that outlines repairs at the above referenced residence. A roof plan is attached highlighting the areas noted during our investigation.


We propose the following:

- Remove 36" of slate and existing steel valleys (Approx.34 L.F.) and 1 saddle highlighted on the attached roof plan.
- Install 36" of a high temperature ice and water shield at the exposed valley and saddle area.
- Fabricate and install a new 24" wide 16oz copper valley over the new ice and water shield. Reinstall slate over the newly installed copper valley to provide a watertight system.
- Resecure 1 loose steel hip cap highlighted on the attached roof plan.
- Remove the bottom course of slate at the eave to allow access to install a new drip edge. This area is highlighted in red on the attached roof plan.
- Fabricate and install a new 16-ounce copper drip edge at the eave (Approx. 84 L.F.). Re-install all necessary state to provide a watertight system.
- Clean all debris created form this work,

Please note the new state may not match in color due to age and weathering of the existing state roof.

Thank you for the opportunity to bid this work.

We will perform the above SCOPE OF WORK for the lump sum of: Twenty-Nine Thousand Five Hundred Eighty-Four Dollars.....\$29,584.00 Payment to be made as follow Terms - 1/3 Initial payment - Balance net 10 days Scott Kania Signature ist materials in guaranteed to be as appointed. Amen's on a companion in a working risk amenies appointing to standard practices. Any attention or develop from allached specifications involving extra costs will be executed upon Owner's approval and will become an extra charge over and above the contrast amount. All agreements contingent upon strikes, accidents or Scott Kanis lave beyond our control. Owner to carry fire, tomado, and other



Please Note: An estimate to repair the entire roof really could not be written. The damages were so extensive, the estimates to piecemeal and repair would be close to the cost of replacement considering the additional time each section removal and tie-in would require. This option would not offer any guarantees, the additional time required would drive up already high costs, and technician safety would be of concern. The partial repair estimate was written with no information on the condition of the underlying roof deck and would have easily turned into much more extensive repairs that covered much larger areas of the roof once the deck condition was discovered. This roof was considered unrepairable with the safety issues it presented, the age of the roof, and the degree of failure present.

Please see below the estimate to replace the slate roof. This estimate includes full removal and replacement with Vermont Slate and copper details. There is also an option included for a synthetic slate system on page two and includes material and workmanship warranty.

10821 CAPITAL • OAK PARK, MI 48237 (248) 543-3040 • fax (248) 543-5810 Roofing That Works!



Page 1 of 4

Bruttell Roofing, Inc.

10821 CAPITAL • OAK PARK, MI 48237 (248) 543-3040 • fax (248) 543-5810 Roofing That Works!

SPECIFICATIONS

Page 2 of 4

Lauren Thiel	PHONE 248-943-3225	August 5, 2022	Thiel Residence	August 5, 2022
913 Chicago Blvd, are state ap	Same		SLATE ROOF REPLACEMENT- Roof C C	Only
Detroit, MI 48202	Same		See Allactied Sile & Root Flatt	
			PREPARATION: Remove the existing slate, drip edge and a	ccessories to the wood deck or suitable surface and dispose off-site
ROOF REPLACEMENT – Vermont State Company State Roof – Roof A Only – Approx. 2,200 S.F. (See Attached Site & Roof Plan) As requested, please find a proposal that outlines the installation of a new Vermont State Company state roof system for Roof A only at the above-mentioned residence. A Roof Plan is attached for your reference.			ICE & WATER SHIELD PROTECTION: Install 40 mil (.040") Tamko® Metal and Ti protect against ice damning and water infill	lle high temperature ice and water shield over entire roof to trains.
			DRIP/RAKE EDGE: Install new 16-ounce copper drip edge and rake edge where necessary.	
Our proposal includes the removal of the existing slate roof system followed by the installation of a new Vermont Slate Company unfading gray/green or unfading gray slate roof to match the existing slate as close as possible. We will be installing all new 16oz copper flashings, drip edge, ridge cap, and valleys. In lieu of the Vermont slate and copper flashings, an alternate price to install a new DaVinci synthetic slate® roof system with aluminum flashings has been provided at the bottom of this proposal.			SLATE. Furnish and install new Vermont Unfading Gray/Green or unfading gray 10" x 16" x 1/4"- 3/8" manufactured by the Vermont Slate Company LLC. Owner to choose from the 2 standard colors provided.	
			COUNTERFLASHINGS: Custom fabricate and install new 16-ounce copper flashings at all roof to wall area, ridges, and chimney. Se all necessary areas with a high-grade polyurethane sealant.	
Thank you for the opportunity to be of service.		VALLEY/SADDLE: Install new 16-ounce copper valley or saddle where necessary. All joints will be soldered to industry standards.		
			CLEAN-UP: All debris from our work will be cleaned up	daily.
We will perform the work outlined below in the sum of:	accordance with the attached Specifi	cations including the for	Warranty: Two-year Bruttell Roofing, Inc. contractors'	warranty on slate work.
One Hundred Seventeen Thousand Eight I	Hundred Twenty-Four Dollars	\$117.824.00		
Payment to be made as follows: TERNIS – 1/3 Initial Payment with signed contract – Balance due Net 10 Days.		OPTION:		
All material is guaranteed to be as specified. All work to be compiled with marrish marrier according its standard practices. Any attention to according to the control from wateries specifications increased as the control desired and the control demands. All agreements continged upon stillade, sections as design about our control. Other to every the control demands and other moreasery meanance. Our workers demands in July control by Workman as Cereptionistics in Nuisina.	Scott Kan		single width synthetic slate® roof syste	C SLATE SYSTEM ROOF A; shings, and price noted above, a price to install a new DaVinci m with aluminum flashings for Roof A only.
ACCEPPTANCE: The above prices are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will	Signature	Date	ACCEPTANCE: Specifications and Conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified.	Signature Date
be made as outlined above. This sheet is considered part of the attached specifications.	Signatura	Date	This page becomes part of and in conformance with the attached contract.	Signature Date

Please see below photos from the roofing installation showing the holes and general damage to the roofing deck. This was a concern when considering roof repairs as these issues would not have been properly addressed without full section removal and replacement, and could cause injury to workers who could not tell if they were stepping on a failed area in the deck:











To Conclude: The existing roofing was in a failed state in its entirety. The cost to repair, the underlying deck failures and the safety issues involved defined this a non-repairable roofing system. The cost for slate repairs or a full slate replacement or a synthetic slate option was far out of the homeowner budget on cost to cure for the roof, and the interior damages were widespread and possibly causing health and safety issues with the property overall. It would also be very unpleasing to the eye to have sections here and there replaced while the rest of the field was falling into disrepair.

This roof was replaced prior to securing the building permit, which is an internal issue and has been addressed. This will not happen in the future under any circumstances. We feel that the lifetime PRO system chosen by the homeowner does match or surpass other homes on this street with appropriateness. Although an asphalt shingle removes the historic character, distinctive features and does not match the old character-defining features, the homeowner has preserved the slate on the dormers and has chosen a beautiful system to protect this home for generations to come.

Please see below arial photo showing the block between Hamilton and 3rd, where 913 Chicago is located along with photos of neighboring homes and those directly across the street. In this block there are 11 homes with asphalt shingle installed, and only 1 home with slate/tile/specialty roofing installed on the North side. On the South side there are 10 other homes with asphalt shingle installed, only 3 featuring slate/tile/specialty roofing.



Neighboring Homes on the South side of Chicago between Hamilton and 3rd: West side of 913



Neighboring homes on the South side of Chicago between Hamilton and $3^{\rm rd}$: East side of 913



Homes on the North side of Chicago, directly across the street from 913:



In total, there are 21 other homes on this block with an asphalt shingle application, many of which are a basic 3-tab 25 year shingle. 913 Chicago has chosen a full CertainTeed PRO lifetime dimensional roofing system that matches the home and remaining slate character beautifully. There are only 4 other homes on this block of Chicago that still feature a slate/tile or specialty roofing system today.

SCOPE OF WORK:


- -Tear off existing one layer of slate tiles down to wood decking.
- -Dispose of debris using vinyl tarps and rubber wheel dumpster.
- *Telehandler may be required on this project
- -Install new 1.5" painted aluminum drip edge at all eaves and rakes of roofs.
- -Install 2 new courses (6') of CertainTeed Winterguard $^{\textcircled{R}}$ Ice & Water shield at all eaves and valleys. Full Ice & Water shield on upper rear room.
- -Install 1 layer of CertainTeed Roof Runner® Synthetic Felt remaining roof deck.
- -Install CertainTeed Swift Start® metric starter shingle at all eaves and rakes of the roofs.
- -Install CertainTeed Landmark® PRO limited lifetime dimensional shingles using 1 ¼" galvanized roofing nails.
- -Install CertainTeed Shadow Ridge® Hip & Ridge Cap shingles at peaks and hips.
- -Install new counter surface mounted flashings.
- -Install new aluminum plumbing base flange flashing on all plumbing vent pipes.
- -Install new aluminum step cards at all side walls as necessary.
- -Install new aluminum flashings around the base of all chimneys/penetrations.
- -Install new CertainTeed Restoration® millwork 1x6 with aluminum Z-Flashing on 3 upper dormers, (cut back slate siding at dormers, wrap vertical wall with ice shield and step flashings)
- -Install 8 slant back-style vents in knee wall attic spaces to improve exhaust ventilation at 50" NFA each.
- -Install approx. 78' CertainTeed Shingle Vent II® to improve exhaust ventilation at 18"NFA per foot.
- -Flat Roof Sections: Install CertainTeed Flintlastic SA® base sheet. Install CertainTeed Flintlastic SA cap sheet, color to match shingle. Install all appropriate edging and flashing metals.

Please see below a few photos from the installation along with a photo featuring the completed roof:










Please contact us at 248-543-3040 with any questions or any further requirements. We greatly appreciate your time, patience, and continued help with this application.

Thank You,

Chalyn A. Edwards Bruttell Roofing Co, Inc.

Brochure, data sheets and supplemental photos of the garage slate to follow:



Introducing

More Value

Landmark® PRO is designed specifically for the professional roofing contractor that takes pride in providing more to their customer.

Landmark PRO improves upon the reliable CertainTeed Landmark shingle.

We started by adding more weathering asphalt to the industry's toughest fiberglass mat to provide more protection. Then we incorporated our Maximum Definition color blend technology to give the product more vibrancy on the roof. Included is the proven performance of our **Nail**Trak* feature, enabling faster installation.

Landmark PRO offers the industry's strongest warranty. Protecting your reputation and safeguarding homeowners from manufacturing and aesthetic defects.

LANDMARK PRO STANDARD WARRANTY

- · Lifetime Limited Warranty
- · 10-years of SureStart™ protection
- 15-year 110 MPH wind warranty (Upgrade to 130 MPH available. CertainTeed starter and CertainTeed hip and ridge required.)
- 15-year Streak Fighter algae resistance warranty

Add it all up and what you get is the opportunity to offer a lot of additional value for the money... and today that means more than ever.

LANDMARK® PRO



Landmark PRO specifications:

- · Premium Max Def color palette
- NailTrak for faster installation
- · Lifetime limited warranty
- 15-year ** Fighter algae resistance
- 10-year SureStart protection includes:
 - Materials, labor, tear off and disposal cost
- 15-year 110 MPH wind warranty with upgrade to 130 MPH available

LANDMARK[®]



Landmark specifications:

- . Traditional color palette
- * Nad Trail: for faster installation
- · Lifetime limited warranty
- 10-year Smein Fighter algae resistance
- 10-year SureStart protection includes:
 - Materials and labor costs
- 15-year IIO MPH wind warranty with upgrade to I30 MPH available

StreakFighter*

Algae Resistance

The ultimate in stain protection.

Those streaks you see on other roofs in your neighborhood? That's algae, and it's a common eyesore on roofing throughout North America. CertainTeed's **Streak**Fighter technology uses the power of science to repel algae before it can take hold and spread.

Streak Fighter's granular blend includes naturally algae-resistant copper, helping your roof maintain its curb appeal and look beautiful for years to come.




Nail Trak®

Fast, Accurate, Visible

The new and improved NailTrak nailing line, a feature on CertainTeed designer shingles.

Now NailTrak is brighter than ever before, with high-visibility lines that stand out whether it's daybreak or dusk.

NailTrak removes the guesswork with three separately defined lines, creating a large area to guide your nailing and a smaller area for extreme steep-slope applications.




.

QuadraBond[®]

Advanced Lavering

CertainTeed's specially formulated adhesive adheres shingle layers at four points, more than any other manufacturer. This superior bond provides greater protection against shingle delamination to maximize performance over the life of the shingle in any climate.



CertaSeal"

Uplift Protection

CertaSeal™ is a fast-activating modified asphalt sealant with a 20-year record of proven performance.
Designed to seal shingles together upon installation, it protects roofs from wind uplift and shingle blow-off so that homes stay safe and dry. It's also engineered to remain flexible after installation, unlike harder sealants that can dry out and crack over time.



Integrity Roof System"

Insist upon the Integrity Roof System™ and get the ultimate in roof performance.

learn more at.

certainteed.com/roofing





CertainTeed

CEILINGS - DECKING - FENCE - GYPSUM - INSULATION - RAILING - ROOPING - SIDING - FRIM 22 Magnet Raise Parkers Parasis - Professional 800-223-8390 - Consumer 800-782-8771 - Centended Com-




Technical Data Sheet

Landmark®, Landmark® Premium, Landmark® Pro Shingles, Landmark® Pro/Architect 80 (NW Region Only) Shingles

PRODUCT INFORMATION

Landmark shingles reflect the same high manufacturing standards and superior warranty protection as the rest of CertainTeed's line of roofing products. Landmark Premium (and Algae Resistant-AR), Landmark PRO (and AR) and Landmark (and AR) are built with the industry's toughest fiber glass mat base, and their strict dimensional tolerance assures consistency. Complex granule color blends and



subtle shadow lines produce a distinctive color selection. Landmark is produced with the unique NailTrak^a nailing feature. Please see the installation instruction section below for important information regarding NailTrak.

In the Northwest Region Landmark PRO (AR) is double-branded as Landmark PRO/Architect 80 (AR).

Landmark algae-resistant (AR) shingles are algae-resistant and help protect against dark or black discoloration, sometimes called staining or streaking, caused by blue-green algae. AR shingles are not available in all regions.

Colors. Please refer to the product brochure or CertainTeed website for the colors available in your region.

Limitations: Use on roofs with slopes greater than 2" per foot. Low-slope applications (2:12 to < 4:12) require additional underlayment. In areas where icing along eaves can cause the back-up of water, apply CertainTeed WinterGuard® Waterproofing Shingle Underlayment, or its equivalent, according to application instructions provided with the product and on the shingle package.

Product Composition: Landmark Series shingles are composed of a fiber glass mat base. Ceramic-coated mineral granules are tightly embedded in carefully refined, water-resistant asphalt. Two pieces of the shingle are firmly laminated together in a special, tough asphaltic cement. All Landmark shingles have self-sealing adhesive strips.

Applicable Standards

ASTM D3018 Type I ASTM D3462 ASTM E108 Class A Fire Resistance ASTM D3161 Class F Wind Resistance ASTM D7158 Class H Wind Resistance UL 790 Class A Fire Resistance ICC-ES ESR-1389 and ESR-3537 CSA Standard A123.5 (Regional) Miami-Dade Product Control Approved Florida Product Approval # FL5444 Meets TDI Windstorm Requirements

Technical Data:

	(and AR)	(and AR)	Landmark Premium (and AR)
Weight/Square (approx.)	219 to 238 lb **	240 to 267 lb **	300 lb
Dimensions (overall)	13 1/4" x 38 3/4"	13 1/4" x 38 3/4"	13 1/4" x 38 3/4"
Shingles/Square (approx.)	66	66	66 <mark>.</mark>
Weather Exposure	5 5/8°	5 5/8"	5 5/8*

^{*}Includes Landmark PRO AR/Architect 80

^{**}Dependent on manufacturing location

INSTALLATION

Detailed installation instructions are supplied on each bundle of Landmark shingles and must be followed. Separate application sheets may also be obtained from CertainTeed.

Hips and Ridges: For capping hip and ridge apply CertainTeed Shadow Ridge*, Cedar Crest* or Mountain Ridge* shingles of a like color.

MAINTENANCE

These shingles do not require maintenance when installed according to manufacturer's application instructions. However, to protect the investment, any roof should be routinely inspected at least once a year. Older roofs should be looked at more frequently.

WARRANTY

Landmark Premium (and AR). Landmark PRO/Architect 80 AR, Landmark PRO (and AR), and Landmark (and AR) shingles carry a lifetime limited, transferable warranty to the consumer against manufacturing defects when applied to stated CertainTeed application instructions for this product. In addition, Landmark Premium (and AR), Landmark PRO (and AR), Landmark PRO/Architect 80 AR, and Landmark (and AR) carry 10-years of SureStart™ Protection. Landmark AR shingles carry a 10-year algae resistance warranty. Landmark Premium AR, Landmark PRO AR, and Landmark PRO/Architect 80 AR shingles carry a 15-year algae resistance warranty. For specific warranty details and limitations, refer to the warranty itself (available from the local supplier, roofing contractor or on-line at www.certainteed.com).

FOR MORE INFORMATION

Sales Support Group: 800-233-8990 Web site: www.certainteed.com

See us at our on-line specification writing tool, CertaSpec®, at www.certainteed.com/certaspec.

CertainTeed 20 Moores Road Malvern, PA 19355



