THIS IS A 3-PAGE FORM - ALL INFORMATION IS REQUIRED FOR PROJECT REVIEW

HISTORIC DISTRICT COMMISSION PROJECT REVIEW REQUEST

Date: 12.07.2020

City of Detroit - Planning & Development Department 2 Woodward Avenue, Suite 808 Detroit, Michigan 48226

2 0 11 0 11, 111 0 111, 111 11 11 11 11 11 11 11 11 11 11	
PROPERTY INFORMATION	
ADDRESS: 701 West Canfield	AKA:
HISTORIC DISTRICT: West Canfield	
SCOPE OF WORK: Windows/ Check ALL that apply) Windows/ Check ALL that apply)	ters/ Porch/ Landscape/Fence/ General Rehab
New Construction Demolition	n Addition Other:
APPLICANT IDENTIFICATION	
Property Owner/ Homeowner NAME: Contractor CON	Tenant or Architect/Engineer/ Business Occupant Consultant MPANY NAME: Tenant or Architect/Engineer/ Consultant
PHONE: MOBILE: 313-610-	
PROJECT REVIEW REQUEST CHECKLIS	
Please attach the following documentation to your	
PLEASE KEEP FILE SIZE OF ENTIRE SUBMISSION	UNDER 30MB ! NOTE:
X Completed Building Permit Application (high	ghlighted portions only) Based on the scope of work,
ePLANS Permit Number (only applicable if y for permits through ePLANS)	ou've already applied additional documentation may be required.
X Photographs of ALL sides of existing building	See www.detroitmi.gov/hdc for scope-specific requirements.
Detailed photographs of location of propose (photographs to show existing condition(s), des	
Description of existing conditions (including	g materials and design)
Description of project (if replacing any existing a replacementrather than repairof existing a	ing material(s), include an explanation as to why and/or construction of new is required)
Detailed scope of work (formatted as bullete	ed list)
✔ Brochure/cut sheets for proposed replacem	ent material(s) and/or product(s), as applicable


Upon receipt of this documentation, staff will review and inform you of the next steps toward obtaining your building permit from the Buildings, Safety Engineering and Environmental Department (BSEED) to perform the work.

SUBMIT COMPLETED REQUESTS TO HDC@DETROITMI.GOV

AKA:	Lot(s):	Subdivision:	
Parcel ID#(s): 04000902	Total Acres: 0.171	Subdivision: Lot Width: 50' Lot Depth: residential	150'
Current Legal Use of Property	residential	Proposed Use: residential	
Are there any existing building	gs or structures on this parcel?	Yes No	
PROJECT INFORMATIO	N		
Permit Type: New	Alteration Addition	Demolition Correct Vi	olations
Foundation Only Ch	ange of Use Temporary	Use Other:	
Revision to Original Permit	t #:	Original permit has been issued and	is active)
	oe in detail proposed work and use of the control o		
	MB	C use change No MBC use	 change
Included Improvements (Ch	neck all applicable; these trade areas	require separate permit applications)	
HVAC/Mechanical	Electrical Plumbing	Fire Sprinkler System Fir	e Alarm
Structure Type			
New Building Existing	ng Structure 🔲 Tenant Spa	ce Garage/Accessory Buil	ding
Other: Si	ze of Structure to be Demolish	ned (LxWxH) c	cubic ft.
Construction involves changes	s to the floor plan?	Yes No	
(e.g. interior demolition or construction			
Use Group: R-2	Type of Construction (per current	t MI Bldg Code Table 601) III-B	
Estimated Cost of Construct	By Contractor	By Department	
Structure Use	,		
Residential-Number of Units:		Industrial-Gross Floor Are	
Commercial-Gross Floor Area:	 _ _		
Proposed No. of Employees:			
(must be correct and in detail).	SHOW ALL streets abutting lot	show all easements and measurem r, indicate front of lot, show all buil pplication Continues on Next Page)	
	For Building Department (Jse Only	
Intake By:	Date:	Fees Due: DngBld?	No
Permit Description:			
Current Legal Land Use:	Pro	posed Use:	
Permit#:		Permit Cost: \$	
Zoning District:	Zoning (Grant(s):	
Lots Combined?	es No (attach zoning	clearance)	
Revised Cost (revised permit ap	plications only) Old \$	New \$	

Permit #:

Phone:	Mobile: 313-610-8086					
Driver's License #:	Email: scott@trafficjam.com					
Contractor	actor is Permit	Applicant				
Representative Name:	Company Name:					
Address:		City:		Stat		
Phone:	Mobile:		Ema	ail:		
TENANT OR BUSINES	S OCCUPAN	NT	enant is Pe	rmit Applicar	nt	
Name:	Phone:		En	nail:		
ARCHITECT/ENGINEE Name: Nicole Rittenour Address: 2255 Wabash Phone: 313-757-5006	R/CONSULT State	te Registratio	<mark>Architect/E</mark> n#: Detroit	ngineer/Cons 062110 Ex	oultant is Perpiration Description	ermit Applicant 10/2021 ate: 0: 48216
Phone: 313-757-5006	Mobile: 310	3-580-8178	En	nail: nikki@p	ushdetroit	com
HOMEOWNER A						
on this permit application sh requirements of the City of I inspections related to the insother person, firm or corpora Print Name:	Detroit and take stallation/work ation any portic	e full responsi herein descri	bility for a bed. I sha k covered	Ill code comp Il neither hire by this build	oliance, fe e nor sub-c ling permit	es and contract to any t.
(Home Subscribed and sworn to befo	,	day of	20	ΔD	Cc	ounty, Michigan
		aay or		——————————————————————————————————————		runty, Michigan
Signature:	(Notary Public)			JIIIIII1331011 L	λριιεз	
	PERMIT	APPLICANT	SIGNATU	JRE		
I hereby certify that the inforestrictions that may apply to certify that the proposed we to make this application as all applicable laws and ordininspections are requested the previous inspection and Nicole Rittenor	o this constructork is authorize the property or nances of juriscend conducted that expired	etion and amed by the own wner(s) authoriction. I amed diction. I amed d within 180 d permits car	aware of r ner of the n rized agen aware tha days of t	ny responsik record and I nt. Further I a t a permit v	oility there have been agree to consider will expire issuance consider.	under. I n authorized conform to e when no or the date of
Print Name: Nicole Aliterio (Permit A) Driver's License #:	pplicant)	Signature: _	xpiration:	2-03-2022		ite:
Subscribed and sworn to befo			20			ounty, Michigan
Signature:				 Expires:		arry, michigan
(Nota	ary Public)			'		





701 W Canfield

PROJECT INFORMATION

Description of Existing Conditions

This project site is located in the West Canfield Historic District listed on the U.S. National Register of Historic Places. It is a 3-story structure plus basement. The original building was a residential duplex. The roof is a cross-gable structure with a rear hip-framed structure. The plan incorporates window bays on the east and west elevations. The front facade features a covered porch.

The exterior of the building is masonry bearing wall construction at the basement through second stories. The third floor (attic) is framed primarily in wood and clad with a combination of wood trim, and stucco. The masonry repairs and roof trim are part of a previous submission (a COA was issued on 5/21/2020 under application number 20-6624).

Description of Work

Renovation of existing historic 3-story duplex building plus basement. Building improvements include new windows.

NORTH ELEVATION (FRONT):

A. REPLACE (8) EXISTING VINYL DOUBLE-HUNG WINDOWS WITH CLAD WOOD DOUBLE-HUNG INSERT WINDOWS.

B. REPLACE (8) EXISTING WOOD DOUBLE-HUNG WINDOWS WITH CLAD WOOD DOUBLE-HUNG INSERT WINDOWS.

C. REPLACE (2) VINYL CASEMENT WINDOWS WITH (1) FRENCH INSWING CASEMENT CLAD WOOD WINDOW.

D. REPLACE (I) WOOD FRENCH INSWING CASEMENT WINDOW WITH A CLAD WOOD FRENCH INSWING CASEMENT WINDOW.

E. REPLACE (I) VINYL SLIDING WINDOW WITH (I) CLAD WOOD CASEMENT WINDOW AT BASEMENT.

PUSH Design

F. REPLACE (2) WOOD CASEMENT WINDOWS WITH CLAD WOOD CASEMENT WINDOWS AT BASEMENT.

EAST ELEVATION:

A. REPLACE (7) VINYL SLIDING WINDOWS WITH (7) CLAD WOOD CASEMENT WINDOWS AT BASEMENT, REMOVE METAL GRILLS AT EACH WINDOW.

B. REPLACE (12) EXISTING VINYL DOUBLE-HUNG WINDOWS WITH CLAD WOOD DOUBLE-HUNG INSERT WINDOWS.

C. REPLACE (2) EXISTING VINYL CASEMENT WINDOWS WITH (2) CLAD WOOD DOUBLE-HUNG INSERT WINDOWS.

D. REPLACE (I) EXISTING VINYL CASEMENT WINDOW WITH (I) CLAD WOOD CASEMENT INSERT WINDOW.

SOUTH ELEVATION (REAR):

NO WORK PROPOSED AT THIS AREA

WEST ELEVATION:

A. REPLACE (6) WOOD CASEMENT WINDOWS WITH CLAD WOOD CASEMENT WINDOWS AT BASEMENT.

B. REPLACE (12) EXISTING WOOD DOUBLE-HUNG WINDOWS WITH CLAD WOOD DOUBLE-HUNG INSERT WINDOWS.

C. REPLACE (2) EXISTING WOOD CASEMENT WINDOWS WITH (2) CLAD WOOD CASEMENT WINDOWS.

D. REPLACE (I) EXISTING WOOD CASEMENT WINDOW WITH (I) CLAD WOOD CASEMENT WINDOW.

PUSH Design 2



Corporate Office: 6477 West KL Avenue • Kalamazoo, MI 49009 • 269.353.8844 • 800.732.9400 • fax.269.353.8843

12/3/2020

Mr. Scott Lowell
Attn: Project Manager
Job Name: 701 W. Canfield
Job Location: Detroit, MI
630 Woodward Ave.

Detroit, MI. 48226 Phone: 313-610-8086

Email: scott@traffic-jam.com

HISTORIC WINDOW SITE REVIEW:

The following is the Historic Window Site Review as requested for the property at 701 W. Canfield in downtown Detroit, MI. This includes a review of all window openings on all elevations for this 3-story building. This review is based a site visit by Mike Shields of BlackBerry, and discussions with Mr. Scott Lowell. We also have reviewed the prepared plans by PUSH Design LLC, detailing the proposed renovation as well as window replacement. We have noted our review and confirmation of the window details as shown on pages H.19, H.20, and H.21. It is our understanding this property is in the historic district and must have HDC approval, as well as the Owner's possible interest in Federal Historic Tax Credits. Our review considers the National Park Service guidelines for restoration and replication as provided in the Wood Window Preservation NPS Brief #9. Likewise, in providing our recommendation for the restoration or replacement we are adhering to the guidelines that meet NPS and SHPO standards. Please note this review is our opinion based on over 30 years of historic window restoration and replication experience; however, you must have written approval from NPS to be assured of the project's approval; as well as approval by your local HDC prior to proceeding with construction.

Existing Conditions: The structure has (54) window openings including the basement, 1st Floor, 2nd Floor, and 3rd Floor levels. The original windows were wood double hung, picture, and casement configuration, with a wood exterior brick mould, sill, and blind stop. All windows were painted both on the interior and exterior surface. All windows were glazed with ¼" annealed float glass with an exterior putty glazing compound. In our interior and exterior inspection about 20 % of the windows had either interior or exterior board up which deterred full viewing of the condition. We did remove a sampling of the board up and in all cases found the window components to be in "poor "condition. The windows on the east half of the structure on the 1st, 2nd, and 3rd Floors have all been replace with vinyl replacement windows. The original wood sashes

including parting bead, and sash trim was removed and disposed of; the vinyl windows have a 3 ¼" frame depth and were set, screwed, and caulked into the old master frame. This was poorly done, and many of the main frames were damaged including being split and cracked making them unusable in a restoration application. The windows in this area of the structure account for approximately 40% of the openings in the building.

In the West half of the structure the windows are the original wood windows, except the casement windows on the east and west slope roof dormers. These appear to have been replaced in the last 30 years with a wood clad product, they are in poor working condition. The rest of the existing windows are in poor condition especially the exterior sills, and the corner joinery at the jamb and sill connection. The majority of the exterior sills are open grained, fissured, and need full replacement. Many sashes are missing, approximately 20%. Most have failed joinery at the meeting rail, or bottom rail and stile mortised joinery. The existing windows have not been maintained and have been allowed to be open to the weather that has warped and twisted sash and frame components.


Recommendation: Considering the fact the 40% of the windows were replaced with a very low-quality vinyl window; this alone should confirm the need to replace with a replica window product. Likewise, the remaining windows are in "very poor condition" and would not allow for a viable restoration. Water saturation, failed joinery, the need to fully replace over 30% of all exterior sills, all point to the need for a fully replication of the original product. I would suggest an aluminum clad wood or a thermally broken aluminum replica window. In this residential setting my opinion would the aluminum clad wood window would be fit this property. The new product would include AAMA 2604 finish, clear pine interior, insulated glass with low-e/argon, exterior brick mould casing, and a beveled exterior sash design. The estimated cost for replacement would be \$155,000.00

Please let me know if you need any additional information.

Sincerely,	
MKS	12/3/2020
Michael K. Shields	Date
President	
BlackBerry Systems, Inc.	

Note: See the following page for supporting photos

SUPPORTING PHOTOS



Front Elevation of 701 W. Canfield



Rear Elevation of 701 W. Canfield



1st Floor East Elevation, vinyl window replaced original sash



1st floor window, viewable sill condition - poor



Front Elevation, $\mathbf{1}^{st}$ Floor, Typical view vinyl replacement windows

Typical Condition of Existing Wood Windows on West side of structure



Failed Corner Joinery, Bottom Rail



Failed Sash Joinery



Rotted jamb behind board-up that was removed



Spilt Jamb Frame

		CONTACT US	FIND A DEALER	TECHNICAL SPECIFICATIONS	Q	SEARCH
MARVIN 🍥	Products	Solutions	Inspiration	Why Marvin		

MARVIN > SIGNATURE COLLECTION > MARVIN SIGNATURE™ ULTIMATE > ULTIMATE DOUBLE HUNG G2

ULTIMATE DOUBLE HUNG G2

Previously known as Clad Ultimate Double Hung-Next Generation



A contemporary classic, the Marvin Signature ™ Ultimate Double Hung G2 window blends traditional beauty with state-of-the-art window performance. Reliable and energy efficient, the Ultimate Double Hung G2 window offers an auto-lock feature for convenient security, durable hardware for smooth operation and Marvin's unique wash mode for easy cleaning. Customize your design with round top styles or single hung operation with optional Lift Lock - Marvin's exclusive bottom rail locking mechanism for easier operation in hard-to-reach areas.

> VIEW DESIGN OPTIONS

FOR THE PROS

Find technical documents for this product, including installation instructions, sizes and elevations, 3D drawings, architectural detail manuals and more.

☑ TECHNICAL SPECIFICATIONS



INTERIOR EXTERIOR

Features of the Ultimate Double Hung G2 Window

- Available in heights up to 10.5 feet or widths up to 5.5 feet
- Marvin's exclusive auto-lock activates when sashes are closed for convenient security
- Unique wash mode allows cleaning of both sides of glass from indoors
- Narrow checkrail maximizes view, while maintaining historical accuracy
- Retractable screen option is nearly invisible when the screen is not in use
- Available with the same features in a single hung style, with optional Lift
 Lock
- Additional configurations include round top, stationary transom or picture window
- Hidden Lock Status Sensor option connects with your smart home to indicate when windows are closed and locked
- Available with IZ3 coastal/hurricane certification
- Available with Commercial Windows Performance certification

CONTACT US FIND A DEALER TECHNICAL SPECIFICATIONS Q SEARCH

MARVIN © Products Solutions Inspiration Why Marvin

MARVIN > SIGNATURE COLLECTION > MARVIN SIGNATURE™ ULTIMATE > ULTIMATE CASEMENT NARROW FRAME

ULTIMATE CASEMENT NARROW FRAME

Previously Known as Clad Ultimate Replacement Casement/Contemporary Casement



The Marvin Signature [™] Ultimate Casement Narrow Frame window is a contemporary option with a flush exterior and narrow jamb ideal for frame-in-frame replacement, allowing quick and easy installation without disturbing the existing frame or interior wall. With its sleek design and square profiles, this window is a great fit for new construction or remodeling projects that call for slim lines and maximum views. With many design options, including round top shapes, the Ultimate Casement Narrow Frame window is a flexible option that can be sized to complement the most expansive views.

> VIEW DESIGN OPTIONS

FOR THE PROS

Find technical documents for this product, including installation instructions, sizes and elevations, 3D drawings, architectural detail manuals and more.

☑ TECHNICAL SPECIFICATIONS



Features of the Ultimate Casement Narrow Frame Window

- Available in heights up to 8 feet or widths up to 3.5 feet
- Contemporary-style window with sleek design and square profiles
- Narrow jamb for replacement applications that minimizes tear-down of existing frame and walls
- Unique wash mode allows access to both sides of glass from indoors
- Retractable screen option is nearly invisible when the screen is not in use
- Hidden Lock Status Sensor option connects with your smart home to indicate when windows are closed and locked
- CE certified

CONTACT US FIND A DEALER TECHNICAL SPECIFICATIONS Q SEARCH

MARVIN

Products Solutions Inspiration Why Marvin

ULITIMATE CASEMENT INSWING

Previously known as Marvin Inswing Casement





The Marvin Signature[™] Ultimate
Casement Inswing window
complements classic architectural
styles. Inswing casement windows can
open into a room, making them a
good choice when an outswing
window could block or take up
valuable space on patios, decks or
outdoor walkways. Available by special
order in single or French double-sash
styles.

> VIEW DESIGN OPTIONS

FOR THE PROS

Find technical documents for this product, including installation instructions, sizes and elevations, 3D drawings, architectural detail manuals and more.

☑ TECHNICAL SPECIFICATIONS



Features of the Ultimate Casement Inswing Window

- Available in heights up to 6 feet or widths up to 4 feet
- Choose from single-sash or French double-sash styles
- French Inswing Casement eliminates vertical center post for wide-open views
- Available in large sizes to maximize views and architectural impact
- Optional concealed pocket hinges provide clean look and smooth operation
- CE certified in clad material

INTERIOR

EXTERIOR