

From: [Doug Pattison](#)
To: [Dan Rieden](#)
Subject: [EXTERNAL] Fwd: East side double doors
Date: Wednesday, October 12, 2022 11:10:47 AM

This Message Is From an External Sender

ATTENTION: This email was sent from an external source. Please be extra cautious when opening attachments or clicking links.

Subject: East side double doors

Dan please note the opening for these doors is not original. There is no brick, stone or wood lintel. This has a steel L shaped lintel. You can also see that the opening was bricked back in to suit at the sides.

The mortar is slightly different. The concrete structure was likely done in the fifties or sixties. It is not stone but stacked rubble concrete. The footings here have been underpinned with ready mix concrete and the window that was infilled with the boiler would have been at original grade before this was excavated.

The concrete stairs and hobbit structure going into this bunker is not in anyway consistent with the original home.

My point that I will explore further is that this is not an original structure, was not safe, and was not even capable of repair.

Get [Outlook for iOS](#)