#### **Historic District Commission Submittal**

Date: November 4, 2022

Subject: Palms Apartments Building Interior & Exterior Alterations

HDC Submittal

Project No: 21023.00

Prepared By: Thomas Roberts, AIA

#### **PROJECT TEAM**

Owner – 81001 Jefferson LLC c/o – Great Water Opportunity Capital Architect – Thomas Roberts Architect Construction Manager – The Monahan Company

#### **DESCRIPTION OF EXISTING CONDITIONS**

The existing historic building was designed by George Mason and Albert Kahn in 1901 and is one of the first buildings in the country to have a poured in place concrete structure. The 60-unit, 45,000gsf apartment building is located in the East Jefferson Residential Historic District at the Local, State, and National levels.

The six-story load bearing brick with concrete frame interior structure is generally in good condition. The TPO roof was installed approximately 10 years ago and is in good condition. Copper flashings and trim are original and are in good condition. The exterior fire escape is in good condition. The exterior masonry and stone are in good condition. The stone window sills and door thresholds are in good condition. The original exterior wood windows and doors are in poor condition and require replacement. The existing wood cornice and freeze are in fair to good condition and require minimal repair. The existing wood bays on the west and north façade are in poor to fair condition and require restoration. The existing wood bay windows in the courtyard are in fair condition and require restoration. The existing stained glass window inserts in the courtyard bay windows are in fair condition and will be stabilized.

#### **DESCRIPTION OF PROJECT**

The exterior scope of the project includes replacement of the original wood windows and doors and frames; the (3) large multi-story wood bays on the west and north façades will be structurally stabilized and restored including missing and severely deteriorated elements will be replaced in-kind with details and profiles to match existing; new masonry openings in the courtyard for new egress doors; minimal masonry and stone restoration; and the existing fire escape and main entry gates will remain and will be primed and painted. New HVAC fresh air intake grilles and bathroom exhaust hoods will be added on the north elevation and within the courtyard. New grilles and hoods will be painted to match the stone and brick. No new mechanical equipment will be added to the roof. New light fixtures will be added at each floor landing of the fire escape. There will be no new exposed conduit on the exterior.

#### **DETAILED SCOPE OF WORK**

The following scope of work has been identified:

#### Site

1. There is no site work during this phase of the project.

#### Roofing

- 1. The existing TPO roofing membrane is in good condition and will not be replaced.
- 2. See roof plan sheet A107 for the limited scope of work. The limited scope of work will not be visible from the public right-of-way.

#### Metal Fascia, Gutters & Downspouts

- 1. Existing gutters and downspouts will remain. No work is anticipated.
- 2. Existing metal fascia will be scraped, primed, and painted.

#### Masonry

1. Patching and tuckpointing will be provided in areas of new masonry openings for new egress doors on the east and west elevations in the courtyard.

- 2. N Type mortar will be used and will match in color, texture, and tooling.
- 3. (2) 24x24 mockup areas will be provided to review joint preparation grinding methods, confirm mortar match, and confirm cleaning procedures.
- 4. Replacement brick will match, color, size, and texture. If possible, existing brick removed for new openings will be reused.
- 5. Stone window sill and door threshold replacement identified will be in-kind and match in size, color, texture, and profile. If possible, existing stone removed for new openings will be reused.
- 6. Masonry cleaning in areas of new work requires the gentlest means possible. Chemical, acid, abrasive, and blasting methods will not be allowed. Low pressure power wash with water and bristle brushes will be acceptable means of cleaning.

#### Windows & Doors

- 1. Existing wood windows and frames will be removed and replaced with historic aluminum windows. It is intended that the new windows match the existing in configuration, function, profile and color. Glazing will be 1" insulated with clear low-e finish. There will be no exterior screens.
- 2. Existing steel windows and frames will be removed and replaced with historic aluminum windows. It is intended that the new windows match the existing in configuration, function, profile and color. Glazing will be 1" insulated with clear low-e finish. There will be no exterior screens.
- 3. Existing wood doors and frames will be removed and replaced with insulated hollow metal doors and frames. It is intended that the new doors and frames are similar to the existing in configuration, function, profile and color. All new hollow metal doors and frames are located in the courtyard and are on non- primary elevations. Glazing will be 1" insulated with clear low-e finish. There will be no exterior screen doors.
- 4. Existing glass bock windows will be removed and replaced with historic aluminum windows. It is intended that the new windows match existing in configuration, function, profile and color. Glazing will be 1" insulated with clear low-e finish. Note: not all the glass block windows will be removed and replaced. See exterior elevations for locations. There will be no exterior screens.
- 5. Existing stained glass window inserts in the courtyard bay windows located on the north elevation at the stair landings will remain and be stabilized. Complete restoration of the stained glass is not included in the scope of work.
- 6. Existing wood windows and frames will remain in the basement commercial space at locations identified on the east elevations.
- 7. Existing storm window system will be removed at locations identified on the east elevation.

#### Carpentry

- 1. The (3) large multi-story bays on the west and north elevations will be structurally stabilized and restored. All missing and severely deteriorated wood elements will be repaired or replaced in-kind with details and profiles to match existing.
- 2. The small wood bay windows at the main stair landings on the north elevation in the courtyard will be restored. All missing and severely deteriorated wood elements will be repaired or replaced inkind with details and profiles to match existing.
- 3. All exterior wood will be primed and painted.

#### **Painting**

- 1. There is NO painting of masonry and stone on this project.
- 2. Existing wood window frames and sash scheduled to remain will be primed and painted. Paint color to match existing (SW2009 Sandstone).
- 3. The three (3) large multi-story wood bays on the west and north elevations will be primed and painted. Paint color to match existing (SW2009 Sandstone).
- 4. The small wood bay windows at the main stair landings on the north elevation in the courtyard will be primed and painted. Paint color to match existing (SW2009 Sandstone).
- 5. Existing steel fire escape and alcove support brackets will be primed and painted. Paint color to match existing (black).
- 6. Existing decorative security gates at the main entrance to be primed and painted. Paint color to match existing (black).
- 7. Existing metal fascia, gutters, and downspouts will be primed and painted. Paint color to match existing ( SW2009 Sandstone).

- 8. Existing storm windows scheduled to remain will be primed and painted. Paint color to match windows (SW2009 Sandstone).
- 9. Existing wood main entry doors will be restored and refinished. Finish to match existing (stain).
- 10. Existing grilles and louvers scheduled to remain will be primed and painted. Paint color to match windows (SW2009 Sandstone).

#### Lighting

- 1. Existing wall sconces and pendant light at the main entrance will remain.
- 2. Existing pendant light at tenant side entrance will remain.
- 3. New wall sconces will be added at each floor level at the exterior doors at the fire escape. See exterior elevations for locations.

#### **HVAC**

- 1. New bathroom exhaust vents and fresh air intake louvers will be added to the non-primary east and west elevations in the courtyard and the buildings north elevation.
- 2. New exhaust vents and intake louvers will be painted to match the brick or stone.
- 3. No new mechanical equipment will be added to the roof.
- 4. Existing grilles and louvers to remain will be primed and painted.

#### Miscellaneous

- Existing canvas entry canopies at the main entrance on the south elevation and the side entrance
  on the east elevation will be removed including the removal of all anchors and support members.
  Great care will be taken to not damage original material. Anchor holes will be filled with patching
  mortar and will match color and texture. No new canopies will be installed.
- 2. All existing exposed conduit will remain unless it is determined to be abandoned or obsolete. There will be no new conduit installed on the exterior of the building.
- 3. Existing signage to remain. No new signage will be installed.

#### The following documents have been included with this submission:

- 1. HDC Review Application
- 2. Detailed scope of work summary
- 3. Existing exterior building condition photo survey
- 4. Existing exterior window & door photo survey
- 5. Renovation building plans and exterior elevations
- 6. Existing window and door details
- 7. Proposed Quaker window detail drawings and specifications
- 8. Proposed exterior products and finishes including windows, light fixture, vents, and grills.



1. South Elevation



2. West Elevation



3. North Elevation.



4. East Elevation



5. Partial South Elevation looking at main entry and terrace.



6. Main entry looking north.



7. Main entry looking north at steel entry gate.



8. East elevation tenant entrance looking West.




9. Northeast corner looking south at commercial space rear entrance.




10. West Elevation in courtyard looking northeast.



11. East Elevation in courtyard looking northwest.



12. North Elevation in courtyard looking south at stair landing bay windows.



13. Northeast corner in courtyard looking northeast at fire escape.



14. Northwest corner of courtyard looking southwest at fire escape.



15. West Elevation looking east at bay windows (upper).



16. West Elevation looking east at bay windows (middle).




17. West Elevation looking east at bay windows (lower).




18. South bay window on West Elevation looking east at bay windows (lower).



19. North bay window on West Elevation looking east at bay windows (lower).



20. North Elevation looking south at bay window (upper).



21. North Elevation looking south at bay window (middle).



22. North Elevation looking south at bay window (lower).





2. Typical double hung wood window at stone.



3. Typical double hung window at stone.



4. Typical deteriorated window sill at stone.




5. East elevation basement level commercial space windows to remain.



6. East elevation, steel sash window to be removed and replaced.



Typical glass block infill to be removed and replaced (see exterior elevations for locations).



8. Courtyard north elevation, bay window at stair landing with stained glass to be restored (upper).




Courtyard north elevation, bay window at stair landing with stained and clear glass to be restored (lower).



 Courtyard north elevation, bay window at stair landing with clear glass to be restored (detail).



11. Typical courtyard double hung window with center mull.



12. Typical wood double hung window in courtyard.



13. Typical wood double hung window in courtyard.



14. Typical wood awning window in courtyard looking west.



15. Typical interior meeting rail condition.




16. Typical interior meeting rail condition.



17. Typical interior sill condition.



18. East elevation tenant entrance.



19. Existing door in southeast corner in courtyard.



20. Existing door in southwest corner in courtyard.



21. Typical existing fire escape door and screen in courtyard.

# PALMS APARTMENT BUILDING

Interior & Exterior Alterations

1001 E. Jefferson Avenue, Detroit, MI 48207



### Owner

### 81001 Jefferson LLC

c/o Great Water Opportunity Capital 6001 Cass Avenue Detroit, Michigan 48202

### Architect

### THOMAS ROBERTS ARCHITECT, LLC

2927 4th Street Wyandotte, Michigan 48192 734.250.4032 (t)

# Electrical Engineer

### ETS ENGINEERING

418-1/2 South Washington Blvd. Royal Oak, Michigan 48067 248.744.0360 (t)

### Mechanical Engineeer

POTAPA - VAN HOOSEAR ENGINEERING, INC. 48653 Van Dyke Avenue

Shelby Twp., Michigan 48317 586.997.0922 (t)

### Construction Manager

The Monahan Company 21321 Kelly Road Eastpointe, MI 48021 586.774.3800 (t)


# Drawing Index

Cover Sheet A002 Site Plan Proposed Basement Plan Proposed First Floor Plan Proposed Second Floor Plan Proposed Third Floor Plan Proposed Fourth Floor Plan Proposed Fifth Floor Plan Proposed Sixth Floor Plan Roof Plan North/South Elevations & Section East Elevation & Section A303 West Elevation & Section Window Schedules Window Details Window Details A611 Window Details Window Details Window Details Door Details Door Details Door Details Typical New Window Elevations **New Window Details** New Window Details New Window Details

# Scope of Work


- MASONF
- -- TUCKPOINTING @ NEW DOORS & WINDOW MODIFICATIONS
  -- NEW HOLES FOR NEW VENTS
- CARPENTRY (BAY WINDOW RESTORATION)
- WINDOW REPLACEMENT
- PAINTING

- EXTERIOR FIRE ESCAPE RESTORATION



November 04, 2022

21023 HDC Review



## SITE NOTES

- EXISTING TRANSFORMER
- 2) NEW UNDERGROUND ELECTRIC SERVICE
- 3 EXISTING BASEMENT EXTENDED UNDER PARKING LOT
- (4) EXISTING COVERED FIRE ESCAPE
- (5) EXISTING DRIVE APPROACH
- (6) EXISTING GATE
- (7) EXISTING BRICK PAVERS TO REMAIN
- 8 EXIST. PLANTS TO REMAIN UNLESS NOTED OTHERWISE
- 9 EXISTING PLANTER WITH TREE
- (10) EXIST. BRICK PAVER RETAINING WALL
- (11) EXIST. UPPER TERRACE
- 12) EXIST. LIMESTONE STEPS
- (13) EXIST. LAWNS TO REMAIN
- 14) SERVICE ENTRY
- 15) TENANT ENTRANCE
- 16 MAIN ENTRANCE
- (17) COMMERCIAL SPACE EGRESS
- (18) EXIST. FENCE & GATE TO REMAIN
- (19) EXIST. CANVAS CANOPIES TO BE REMOVED


Thomas Roberts Architects


Thomas Roberts Architects
Thomas Roberts Architects
Thomas Roberts Architects

2927 4th Street Wyandotte, MI 48192 thomasrobertsarchitect.com

734.250.4032









Palms Apartment Building Interior & Exterior Alterations 1001 E. Jefferson Ave. Detroit, MI, 48207

TR
principal in charge
TR
project manager
TR
project architect
SM
drawn
11.04.2022

21023.00 job number
A002







- A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON DRAWINGS.
- B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects

Wyandotte, MI 48192

734.250.4032

thomasrobertsarchitect.com

NOT FOR

CONSTRUCTION

- FACE OF FINISH AND FACE OF MASONRY U.N.O. C. ALL DIMENSIONS TO EXISTING CONSTRUCTION
- ARE TO FACE OF FINISH U.N.O. D. ALL INTERIOR PARTITIONS NOT TAGGED ARE
- EXISTING TO REMAIN. E. ALL DOORS AND FRAMES NOT TAGGED ARE EXISTING TO REMAIN. PROVIDE NEW FINISH AND MAKE SURE HARDWARE IS IN WORKING ORDER. SEE DOOR SCHEDULE FOR ADDITIONAL
- INFORMATION. F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS
- AND/OR OPENINGS IN EXISTING WALLS. G. PLUMBING FIXTURES TO REMAIN REQUIRE
- REMOVAL, REGLAZE, AND REINSTALL U.N.O. H. COORDINATE ALL WORK WITH MECHANICAL & ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

#### FLOOR PLAN KEYNOTES

1) NEW STACKED VENTLESS WASHER & DRYER

- (2) NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- (3) NEW RANGE
- 4) NEW KITCHEN SINK
- (5) NEW REFRIGERATOR
- (6) NEW TOILET
- 7) NEW VANITY AND SINK(S)
- (8) NEW BATHTUB/SHOWER
- (9) NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR SCHEDULE.
- (11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- (12) NEW WALL TO INFILL EXIST. OPENING
- (13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- (17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- 20) POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- (23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- (24) NEW/EXIST. WALL AT CABINET HEIGHT.
- (25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR
- ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- (27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW CASING & TRIM TO MATCH EXIST.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D FOLLOWING REMOVAL OF DOOR & PAINT.
- (31) EXIST. WD WAINSCOT TO BE REFINISHED
- (32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/ HARDWARE & PAINT
- (33) NEW WALL CONSTRUCTION
- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- (35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- (39) EXIST. MAIL SLOT
- (40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- (42) REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
- (44) EXIST. ELECTRICAL PANEL
- (45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O. (46) FIRE ESCAPE ABOVE
- (47) EXIST. WINDOWS TO REMAIN


Palms Apartment E Interior & Exterior A

1001 E. Jefferson Ave.
Detroit, MI, 48207 principal in charge project manager project architect

Building Alterations

11.04.2022

21023.00



# KITCHEN TYPES


- A NEW KITCHEN IN NEW LOCATION
- B NEW KITCHEN IN EXISTING LOCATION
- C REFRESH EXISTING KITCHEN

### BATHROOM TYPES

A NEW BATHROOM IN NEW LOCATION

B NEW BATHROOM IN EXISTING LOCATION

C REFRESH EXISTING BATHROOM



- A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON
- B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects

Wyandotte, MI 48192

734.250.4032

thomasrobertsarchitect.com

NOT FOR

CONSTRUCTION

- FACE OF FINISH AND FACE OF MASONRY U.N.O. C. ALL DIMENSIONS TO EXISTING CONSTRUCTION
- ARE TO FACE OF FINISH U.N.O. D. ALL INTERIOR PARTITIONS NOT TAGGED ARE
- EXISTING TO REMAIN. E. ALL DOORS AND FRAMES NOT TAGGED ARE EXISTING TO REMAIN. PROVIDE NEW FINISH AND MAKE SURE HARDWARE IS IN WORKING ORDER. SEE DOOR SCHEDULE FOR ADDITIONAL
- INFORMATION. F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS
- AND/OR OPENINGS IN EXISTING WALLS. G. PLUMBING FIXTURES TO REMAIN REQUIRE
- REMOVAL, REGLAZE, AND REINSTALL U.N.O. H. COORDINATE ALL WORK WITH MECHANICAL & ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

## FLOOR PLAN KEYNOTES

1) NEW STACKED VENTLESS WASHER & DRYER

- (2) NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- (3) NEW RANGE
- 4) NEW KITCHEN SINK
- (5) NEW REFRIGERATOR
- (6) NEW TOILET
- (7) NEW VANITY AND SINK(S)
- (8) NEW BATHTUB/SHOWER
- (9) NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR
- (11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- (12) NEW WALL TO INFILL EXIST. OPENING
- (13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- 17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- 20) POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- (23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- (24) NEW/EXIST. WALL AT CABINET HEIGHT.

LEGEND

020103 DOOR TAG

01 WALL TYPE TAG

KEY NOTE TAG

EXISTING DOOR

EXISTING WALL

A NEW KITCHEN IN NEW LOCATION

C REFRESH EXISTING KITCHEN

BATHROOM TYPES

B NEW KITCHEN IN EXISTING LOCATION

A NEW BATHROOM IN NEW LOCATION

C REFRESH EXISTING BATHROOM

B NEW BATHROOM IN EXISTING LOCATION

WORK AREA - LEVEL 2 ALTERATIONS

EXISTING PLUMBING FIXTURE TO REMAIN

**NEW DOOR** 

**NEW WALL** 

KITCHEN TYPES

- (25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR
- ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- (27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW
- CASING & TRIM TO MATCH EXIST.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D FOLLOWING REMOVAL OF DOOR & PAINT.
- (31) EXIST. WD WAINSCOT TO BE REFINISHED
- (32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/ HARDWARE & PAINT
- (33) NEW WALL CONSTRUCTION
- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- (35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- (39) EXIST. MAIL SLOT
- (40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- (42) REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
- (44) EXIST. ELECTRICAL PANEL
- (45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O. (46) FIRE ESCAPE ABOVE
- (47) EXIST. WINDOWS TO REMAIN

Building Alterations


Apartment I r & Exterior / Palms / Interior

11.04.2022

principal in charge

project manager

project architect





- A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON
- B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO
- FACE OF FINISH AND FACE OF MASONRY U.N.O. C. ALL DIMENSIONS TO EXISTING CONSTRUCTION
- ARE TO FACE OF FINISH U.N.O. D. ALL INTERIOR PARTITIONS NOT TAGGED ARE
- EXISTING TO REMAIN. E. ALL DOORS AND FRAMES NOT TAGGED ARE EXISTING TO REMAIN. PROVIDE NEW FINISH AND MAKE SURE HARDWARE IS IN WORKING ORDER. SEE DOOR SCHEDULE FOR ADDITIONAL INFORMATION.
- F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS AND/OR OPENINGS IN EXISTING WALLS.
- G. PLUMBING FIXTURES TO REMAIN REQUIRE REMOVAL, REGLAZE, AND REINSTALL U.N.O.
- H. COORDINATE ALL WORK WITH MECHANICAL & ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

# FLOOR PLAN KEYNOTES

1) NEW STACKED VENTLESS WASHER & DRYER

- (2) NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- (3) NEW RANGE
- 4) NEW KITCHEN SINK
- (5) NEW REFRIGERATOR
- (6) NEW TOILET
- 7) NEW VANITY AND SINK(S)
- (8) NEW BATHTUB/SHOWER
- (9) NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR SCHEDULE.
- (11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- (12) NEW WALL TO INFILL EXIST. OPENING
- (13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- 17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- (23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- (24) NEW/EXIST. WALL AT CABINET HEIGHT.
- (25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR
- ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- (27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW
- CASING & TRIM TO MATCH EXIST.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D
- FOLLOWING REMOVAL OF DOOR & PAINT.
- (31) EXIST. WD WAINSCOT TO BE REFINISHED (32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/
- HARDWARE & PAINT (33) NEW WALL CONSTRUCTION

KEY NOTE TAG

EXISTING DOOR

EXISTING WALL

C REFRESH EXISTING KITCHEN

BATHROOM TYPES

A NEW BATHROOM IN NEW LOCATION

C REFRESH EXISTING BATHROOM

B NEW BATHROOM IN EXISTING LOCATION

WORK AREA - LEVEL 2 ALTERATIONS

EXISTING PLUMBING FIXTURE TO REMAIN

NEW DOOR

**NEW WALL** 

- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- 35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- (39) EXIST. MAIL SLOT
- (40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- (42) REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
- (44) EXIST. ELECTRICAL PANEL
- (45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O.
- (46) FIRE ESCAPE ABOVE
- (47) EXIST. WINDOWS TO REMAIN

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects

Wyandotte, MI 48192

734.250.4032

thomasrobertsarchitect.com

NOT FOR

CONSTRUCTION


Building Alterations Palms Apartment E Interior & Exterior A Loo1 E. Jefferson Ave.

Detroit, MI, 48207 principal in charge

project manager

project architect

11.04.2022





020103 DOOR TAG 01 WALL TYPE TAG

KEY NOTE TAG

NEW DOOR

EXISTING DOOR **NEW WALL** 

EXISTING WALL

WORK AREA - LEVEL 2 ALTERATIONS EXISTING PLUMBING FIXTURE TO REMAIN

#### KITCHEN TYPES

NEW KITCHEN IN NEW LOCATION

B NEW KITCHEN IN EXISTING LOCATION

C REFRESH EXISTING KITCHEN

# BATHROOM TYPES

A NEW BATHROOM IN NEW LOCATION

B NEW BATHROOM IN EXISTING LOCATION

C REFRESH EXISTING BATHROOM

#### **GENERAL NOTES**

- A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON
- B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO FACE OF FINISH AND FACE OF MASONRY U.N.O.
- C. ALL DIMENSIONS TO EXISTING CONSTRUCTION ARE TO FACE OF FINISH U.N.O.
- D. ALL INTERIOR PARTITIONS NOT TAGGED ARE EXISTING TO REMAIN.
- E. ALL DOORS AND FRAMES NOT TAGGED ARE EXISTING TO REMAIN. PROVIDE NEW FINISH AND MAKE SURE HARDWARE IS IN WORKING ORDER. SEE DOOR SCHEDULE FOR ADDITIONAL
- INFORMATION. F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS
- AND/OR OPENINGS IN EXISTING WALLS. G. PLUMBING FIXTURES TO REMAIN REQUIRE REMOVAL, REGLAZE, AND REINSTALL U.N.O.
- H. COORDINATE ALL WORK WITH MECHANICAL & ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

#### FLOOR PLAN KEYNOTES

1) NEW STACKED VENTLESS WASHER & DRYER

- (2) NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- (3) NEW RANGE
- (4) NEW KITCHEN SINK
- (5) NEW REFRIGERATOR
- (6) NEW TOILET
- (7) NEW VANITY AND SINK(S)
- (8) NEW BATHTUB/SHOWER
- (9) NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR
- (11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- (12) NEW WALL TO INFILL EXIST. OPENING
- (13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- 17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- 20) POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- (23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- (24) NEW/EXIST. WALL AT CABINET HEIGHT.
- (25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR
- ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- (27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW
- CASING & TRIM TO MATCH EXIST.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D FOLLOWING REMOVAL OF DOOR & PAINT.
- (31) EXIST. WD WAINSCOT TO BE REFINISHED
- (32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/ HARDWARE & PAINT
- (33) NEW WALL CONSTRUCTION
- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- 35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- (39) EXIST. MAIL SLOT
- (40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- (42) REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
- (44) EXIST. ELECTRICAL PANEL
- (45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O.
- (46) FIRE ESCAPE ABOVE
- (47) EXIST. WINDOWS TO REMAIN

734.250.4032 NOT FOR CONSTRUCTION

Thomas Roberts Architects Thomas Roberts Architects


Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects


Wyandotte, MI 48192


thomasrobertsarchitect.com




Building Alterations Apartment I r & Exterior / Palms A Interior 1001 E. Jeffer Detroit, MI, 48

principal in charge project manager project architect 11.04.2022









- A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON DRAWINGS.
- B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO FACE OF FINISH AND FACE OF MASONRY U.N.O.
- C. ALL DIMENSIONS TO EXISTING CONSTRUCTION
  ARE TO FACE OF FINISH U.N.O.
- ARE TO FACE OF FINISH U.N.O.

  D. ALL INTERIOR PARTITIONS NOT TAGGED ARE
- EXISTING TO REMAIN.

  E. ALL DOORS AND FRAMES NOT TAGGED ARE
  EXISTING TO REMAIN. PROVIDE NEW FINISH AND
  MAKE SURE HARDWARE IS IN WORKING ORDER.
  SEE DOOR SCHEDULE FOR ADDITIONAL
- INFORMATION.

  F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS


  AND/OR OPENINGS IN EXISTING WALLS
- AND/OR OPENINGS IN EXISTING WALLS.
  G. PLUMBING FIXTURES TO REMAIN REQUIRE
- REMOVAL, REGLAZE, AND REINSTALL U.N.O.
  H. COORDINATE ALL WORK WITH MECHANICAL &
  ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF
  ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

# FLOOR PLAN KEYNOTES

NEW STACKED VENTLESS WASHER & DRYER

- (2) NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- (3) NEW RANGE
- 4 NEW KITCHEN SINK
- 5 NEW REFRIGERATOR
- 6 NEW TOILET
- 7 NEW VANITY AND SINK(S)
- 8 NEW BATHTUB/SHOWER
- 9 NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR SCHEDULE.
- 11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- (12) NEW WALL TO INFILL EXIST. OPENING
- (13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- (17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- 20) POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- 23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- (24) NEW/EXIST. WALL AT CABINET HEIGHT.
- (25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR
- ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- 27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW CASING & TRIM TO MATCH EXIST.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D
- FOLLOWING REMOVAL OF DOOR & PAINT.

  (31) EXIST. WD WAINSCOT TO BE REFINISHED
- 32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/ HARDWARE & PAINT
- (33) NEW WALL CONSTRUCTION
- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- 35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- (39) EXIST. MAIL SLOT
- (40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- (42) REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
  - EVIST ELECTRICAL DANIE
- 44) EXIST. ELECTRICAL PANEL
- (45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O.
- 46) FIRE ESCAPE ABOVE
- (47) EXIST. WINDOWS TO REMAIN



Thomas Roberts Architects
Thomas Roberts Architects

Thomas Roberts Architects
Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects

Wyandotte, MI 48192

734.250.4032

thomasrobertsarchitect.com

NOT FOR

CONSTRUCTION

Palms Apartment Building
Interior & Exterior Alterations
1001 E. Jefferson Ave.
Detroit, MI, 48207

21023.00 job number A 1 0 4

project manager

project architect

11.04.2022

BATHROOM TYPES

NEW BATHROOM IN NEW LOCATION

 NEW BATHROOM IN EXISTING LOCATION

LEGEND

020103 DOOR TAG

01 WALL TYPE TAG

KEY NOTE TAG

EXISTING DOOR

EXISTING WALL

NEW KITCHEN IN NEW LOCATION

C REFRESH EXISTING KITCHEN

B NEW KITCHEN IN EXISTING LOCATION

WORK AREA - LEVEL 2 ALTERATIONS


EXISTING PLUMBING FIXTURE TO REMAIN

NEW DOOR

**NEW WALL** 

KITCHEN TYPES

C REFRESH EXISTING BATHROOM





A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON

**GENERAL NOTES** 

B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO FACE OF FINISH AND FACE OF MASONRY LLN O

Thomas Roberts Architects
Thomas Roberts Architects

Thomas Roberts Architects
Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects

Wyandotte, MI 48192

734.250.4032

thomasrobertsarchitect.com

NOT FOR

CONSTRUCTION

- FACE OF FINISH AND FACE OF MASONRY U.N.O.

  C. ALL DIMENSIONS TO EXISTING CONSTRUCTION

  ARE TO FACE OF FINISH I I N.O.
- ARE TO FACE OF FINISH U.N.O.

  D. ALL INTERIOR PARTITIONS NOT TAGGED ARE
- EXISTING TO REMAIN.

  E. ALL DOORS AND FRAMES NOT TAGGED ARE EXISTING TO REMAIN. PROVIDE NEW FINISH AND MAKE SURE HARDWARE IS IN WORKING ORDER. SEE DOOR SCHEDULE FOR ADDITIONAL
- INFORMATION.

  F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS
  AND/OR OPENINGS IN EXISTING WALLS
- AND/OR OPENINGS IN EXISTING WALLS.
  G. PLUMBING FIXTURES TO REMAIN REQUIRE
- REMOVAL, REGLAZE, AND REINSTALL U.N.O.

  H. COORDINATE ALL WORK WITH MECHANICAL &
  ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF
  ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

# FLOOR PLAN KEYNOTES

(1) NEW STACKED VENTLESS WASHER & DRYER

- 2 NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- 3 NEW RANGE
- 4 NEW KITCHEN SINK
- 5 NEW REFRIGERATOR
- 6 NEW TOILET
- 7 NEW VANITY AND SINK(S)
- (8) NEW BATHTUB/SHOWER
- 9 NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR SCHEDULE.
- 11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- 12) NEW WALL TO INFILL EXIST. OPENING
- 13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- 17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- (23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- 24) NEW/EXIST. WALL AT CABINET HEIGHT.
- 25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- O NELOCATE, NEFAIN, & FAINT EXIST. NADIATON.
- (27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW CASING & TRIM TO MATCH EXIST.
- Chaire a Trilling to White Exist.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D
- FOLLOWING REMOVAL OF DOOR & PAINT.
- (31) EXIST. WD WAINSCOT TO BE REFINISHED
- 32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/ HARDWARE & PAINT
- (33) NEW WALL CONSTRUCTION
- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- (35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- EVICT MAIL BOVES TO DEMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- 39 EXIST. MAIL SLOT
- 40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
- EVIST ELECTRICAL DANIEL
- (44) EXIST. ELECTRICAL PANEL
- (45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O.(46) FIRE ESCAPE ABOVE
- 47) EXIST. WINDOWS TO REMAIN

21023.00 job number
A 105

Building Alterations

Palms Apartment E Interior & Exterior A Loo1 E. Jefferson Ave.


Detroit, MI, 48207

principal in charge

project manager

project architect

11.04.2022



#### KITCHEN TYPES


- NEW KITCHEN IN NEW LOCATION
- B NEW KITCHEN IN EXISTING LOCATION
- C REFRESH EXISTING KITCHEN

#### BATHROOM TYPES

A NEW BATHROOM IN NEW LOCATION

B NEW BATHROOM IN EXISTING LOCATION

C REFRESH EXISTING BATHROOM





- A. CONTRACTOR SHALL FIELD VERIFY ALL DIMENSIONS IN FIELD PRIOR TO CONSTRUCTION. NOTIFY ARCHITECT OF ANY DISCREPANCIES ON
- B. ALL DIMENSIONS TO NEW CONSTRUCTION ARE TO
- FACE OF FINISH AND FACE OF MASONRY U.N.O. C. ALL DIMENSIONS TO EXISTING CONSTRUCTION
- ARE TO FACE OF FINISH U.N.O. D. ALL INTERIOR PARTITIONS NOT TAGGED ARE
- EXISTING TO REMAIN. E. ALL DOORS AND FRAMES NOT TAGGED ARE EXISTING TO REMAIN. PROVIDE NEW FINISH AND MAKE SURE HARDWARE IS IN WORKING ORDER.
- INFORMATION. F. FLOORS TO BE PATCHED AT DEMOLISHED WALLS

SEE DOOR SCHEDULE FOR ADDITIONAL

- AND/OR OPENINGS IN EXISTING WALLS. G. PLUMBING FIXTURES TO REMAIN REQUIRE
- REMOVAL, REGLAZE, AND REINSTALL U.N.O. H. COORDINATE ALL WORK WITH MECHANICAL & ELECTRICAL CONTRACTOR. NOTIFY ARCHITECT OF ANY DISCREPANCIES BEFORE PROCEEDING WITH
- I. SEE ENLARGED PLAN SHEETS A111-A115 FOR SCOPE OR WORK IN LEVEL 2 ALTERATION AREAS

#### FLOOR PLAN KEYNOTES

1) NEW STACKED VENTLESS WASHER & DRYER

- (2) NEW KITCHEN CABINET(S)/MILLWORK (BY OTHERS)
- (3) NEW RANGE
- (4) NEW KITCHEN SINK
- (5) NEW REFRIGERATOR
- (6) NEW TOILET
- (7) NEW VANITY AND SINK(S)
- (8) NEW BATHTUB/SHOWER
- (9) NEW DOOR & FRAME AT EXIST. OPEN'G. SEE DOOR SCHEDULE.
- (10) NEW DOOR & FRAME IN NEW OPEN'G. SEE DOOR
- (11) NEW OPEN'G IN EXIST. WALL. PROVIDE CASING & TRIM TO MATCH EXIST. & PATCH FLOOR AT WALL REMOVAL.
- (12) NEW WALL TO INFILL EXIST. OPENING
- (13) NEW ELECTRIC PANEL SEE ELECTRICAL DRAWINGS.
- (14) EXISTING RADIATOR. PROVIDE MISC. REPAIRS & PAINT; TYP. U.N.O.
- (15) EXIST. WINDOW SEAT. PROVIDE MISC. REPAIRS & PAINT.
- (16) EXIST. MILLWORK TO BE RESTORED INCLUDING NEW HARDWARE & PAINT.
- 17) NEW UNIT ENTRY DOOR & FRAME IN NEW OPENING SEE DOOR SCHEDULE FOR ADDITIONAL INFO.
- (18) EXIST. SLIDING DOOR TO REMAIN.
- (19) EXIST. IN-ACTIVE FIREPLACE TO REMAIN.
- 20) POTENTIAL PLUMBING CHASE CONTRACTOR TO CONFIRM.
- (21) NEW WIRE SHELVING SYSTEM.
- (22) NEW WINDOW IN EXIST. DOOR OPENING. INFILL SILL W/ MASONRY & WOOD TRIM TO MATCH EXIST.
- (23) NEW MARBLE THRESHOLD TO MATCH EXIST.
- (24) NEW/EXIST. WALL AT CABINET HEIGHT.
- (25) NEW WINDOW IN EXIST. OPENING SEE EXTERIOR
- ELEVATIONS FOR WINDOW TYPE.
- (26) RELOCATE, REPAIR, & PAINT EXIST. RADIATOR.
- (27) DOOR FRAME, CASING, & TRIM TO REMAIN; PAINT.
- (28) EXIST. CLERESTORY WINDOWS TO REMAIN; PAINT.
- (29) NEW ENLARGED WALL OPEN'G. INSTALL SALVAGED/NEW
- CASING & TRIM TO MATCH EXIST.
- (30) MODIFY EXIST. WOOD CASING & TRIM AS REQ'D FOLLOWING REMOVAL OF DOOR & PAINT.
- (31) EXIST. WD WAINSCOT TO BE REFINISHED
- (32) EXIST. RECESSED MEDICINE CAB. TO BE REFRESHED W/ HARDWARE & PAINT
- (33) NEW WALL CONSTRUCTION

KEY NOTE TAG

EXISTING DOOR

EXISTING WALL

C REFRESH EXISTING KITCHEN

BATHROOM TYPES

A NEW BATHROOM IN NEW LOCATION

C REFRESH EXISTING BATHROOM

B NEW BATHROOM IN EXISTING LOCATION

WORK AREA - LEVEL 2 ALTERATIONS

EXISTING PLUMBING FIXTURE TO REMAIN

NEW DOOR

**NEW WALL** 

- (34) EXIST. DOOR & FRAME TO REMAIN; REMOVE HARDWARE & SECURE SHUT
- (35) EXIST. WALL; CUT DOWN TO BAR TOP HEIGHT W/ NEW CAP
- (36) NEW STL. OR MASONRY LINTEL AT NEW OPENING
- (37) EXIST. FIRE ALARM PANEL TO REMAIN
- (38) EXIST. MAILBOXES TO REMAIN
- (39) EXIST. MAIL SLOT
- (40) NEW MEDICINE CABINET
- (41) WATER WALL NEEDS WORK W/ NEW TILE
- (42) REPAIR OR REPLACE MISSING RADIATOR PANELS &
- (43) NEW RECESSED ELEC. HEATER
- (44) EXIST. ELECTRICAL PANEL
- (46) FIRE ESCAPE ABOVE
- (47) EXIST. WINDOWS TO REMAIN

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects Thomas Roberts Architects

Thomas Roberts Architects

Thomas Roberts Architects

Wyandotte, MI 48192

734.250.4032

thomasrobertsarchitect.com

NOT FOR

CONSTRUCTION

Apartment I r & Exterior A Palms / Interior principal in charge project manager project architect


Building Alterations

21023.00

11.04.2022

(45) EXIST. MARBLE THRESHOLD TO REMAIN; TYP. U.N.O.















4 HVAC Penthouse



3 Shaft Roof & Chimney





### **ROOF KEYNOTES**

- (1) EXIST. FIRE ESCAPE ROOF BELOW (NO WORK).
- (2) EXIST. CHIMNEY TO REMAIN (NO WORK).
- (3) EXIST. GUTTERS & DOWNSPOUTS TO REMAIN (NO WORK).
- 4 EXIST. MEMBRANE ROOF TO REMAIN.
- (5) EXIST. HVAC PENTHOUSE TO REMAIN.
- 6 CONFIRM EXIST CHIMNEY/INCINERATOR HAS BEEN ABANDONED; REMOVE TAR COATING AND MTL. CAP; INSTALL NEW MTL. CAP.
- 7 EXIST. ELEVATOR PENTHOUSE TO REMAIN (NO
- 8 EXIST. ROOF ACCESS STAIR PENTHOUSE TO REMAIN (NO WORK).
- 9 EXIST. PARAPET AND STONE COPING TO REMAIN (NO
- (10) EXIST. MEMBRANE ROOF ASSEMBLY TO REMAIN. ROOFING CONTRACTOR TO INSPECT ROOF AND PROVIDE RECOMMENDATIONS FOR REPAIR.
- (11) EXIST. WOOD CORNICE W/ COPPER CAP BELOW TO
- (12) EXIST. BAY WINDOW W/ COPPER ROOF BELOW. SEE EXTERIOR ELEVATIONS FOR SCOPE OF WORK.
- (13) EXIST. ALCOVE ROOF BELOW. ROOFING CONTRACTOR TO INSPECT ROOF AND PROVIDE RECOMMENDATIONS FOR REPAIR.
- (14) INSTALL NEW MEMBRANE ROOF & FLASHING.
- (15) NEW GUTTER & DOWNSPOUT.


Thomas Roberts Architects Thomas Roberts Architects Thomas Roberts Architects Thomas Roberts Architects

2927 4th Street Wyandotte, MI 48192

Thomas Roberts Architects Thomas Roberts Architects




734.250.4032




Palms Apartment Building Interior & Exterior Alterations 1001 E. Jefferson Ave. Detroit, MI, 48207

principal in charge project manager project architect 11.04.2022

21023.00 job number



A301 Scale: 1/8" = 1'-0"




\ North Section A301 Scale: 1/8" = 1'-0"

### **ELEV./SECTION KEYNOTES**

- (1) EXIST. LIMESTONE FACADE (NO WORK)
- (2) EXIST. LIMESTONE WALLS W/ SCUPPERS (NO WORK)
- (3) EXIST. WOOD CORNICE; SCRAPE, PRIME, & PAINT
- 4 EXIST. ASPHALT SHINGLE SIDING TO REMAIN. PATCH AS REQUIRED AT NEW WINDOW INSTALLATION
- (5) SCRAPE, PRIME, & PAINT EXIST. MTL. CORNICE
- 6 REMOVE MTL. SIDING & INSTALL WD. PANELS & TRIM TO MATCH ABOVE & PAINT
- (7) EXISTING BRICK: CLEAN & PATCH AT AREAS OF NEW
- 8 REMOVE & REPLACE EXIST. WD. WINDOW (TYP.) UNLESS NOTED OTHERWISE.
- (9) STAINED GLASS WINDOWS TO REMAIN
- (10) REHABILITATE EXIST. WD. BAY WINDOW & PAINT
- (11) EXIST. GLASS BLOCK TO REMAIN
- (12) REMOVE EXIST. GLASS BLOCK & PROVIDE NEW D.H. WINDOW TO MATCH EXISTING
- (13) REMOVE STORM WINDOW & FRAME
- 14) STL. SASH WINDOW TO BE REMOVED & REPLACED TO MATCH EXISTING
- (15) REPLACE EXIST. WD FRAME AND LOUVER W/ NEW MTL/ FRAME & LOUVER
- (16) REPLACE EXIST. VENT WITH NEW VENT
- 17) EXISTING STEEL FIRE ESCAPE TO REMAIN; CLEAN, REPAIR,
- (18) PAINT EXIST. STL. SUPPORTS
- (19) NEW MASONRY OPENING W/ NEW DOOR & FRAME W/ MASONRY ARCH LINTEL TO MATCH EXISTING
- (20) NEW ALUM. DOOR & FRAME IN EXISTING OPENING
- (21) EXIST. ALUM. DOOR TO REMAIN
- (22) EXIST. WD DOOR & FRAME TO BE REMOVED AND REPLACED W/ NEW H.M. DOOR & FRAME
- (23) EXIST. ACCESS HATCH TO BE PAINTED
- (24) EXIST. GUTTER & DOWNSPOUTS TO REMAIN
- (25) EXIST. SURFACE MNTD. CONDUIT TO REMAIN
- (26) EXIST. SIGNAGE TO REMAIN
- (27) EXIST. ADDRESS TO REMAIN
- 28) REMOVE EXIST. FABRIC CANOPY COMPLETE INCLUDING ANCHORS, SUPPORTS. ETC.
- (29) EXIST. VENT TO BE REMOVED
- (30) EXIST. CAMERA TO REMAIN
- (31) EXIST. LIGHT TO REMAIN
- (32) EXIST. WALL SCONCE TO REMAIN
- (33) NEW LIGHT IN EXIST. LOCATION
- (34) EXIST. CEMENT STEP TO REMAIN
- (35) EXIST. LIMESTONE STEPS (NO WORK)
- (36) NEW WINDOW IN EXISTING DOOR OPENING. REMOVE STONE THRESHOLD AND INFILL WITH BRICK & STONE WINDOW SILL TO MATCH EXISTING
- (37) NEW LIGHT FIXTURE
- 38) NEW MASONRY INFILL BENEATH WINDOW TO MATCH ADJACENT MASONRY
- (39) NEW EXHAUST VENT
- 40 RESTORE EXIST. DECORATIVE IRON SECURITY GATES & WOOD DOORS
- (41) EXIST. WINDOW TO REMAIN AND BE RESTORED


Thomas Roberts Architects Wyandotte, MI 48192

734.250.4032



Building Alterations Apartment I r & Exterior / Palms / Interior

principal in charge project manager project architect 11.04.2022



#### **ELEV./SECTION KEYNOTES**


- 1) EXIST. LIMESTONE FACADE (NO WORK)

(2) EXIST. LIMESTONE WALLS W/ SCUPPERS (NO WORK)

- (3) EXIST. WOOD CORNICE; SCRAPE, PRIME, & PAINT
- (4) EXIST. ASPHALT SHINGLE SIDING TO REMAIN. PATCH AS REQUIRED AT NEW WINDOW INSTALLATION
- (5) SCRAPE, PRIME, & PAINT EXIST. MTL. CORNICE
- 6 REMOVE MTL. SIDING & INSTALL WD. PANELS & TRIM TO MATCH ABOVE & PAINT
- (7) EXISTING BRICK: CLEAN & PATCH AT AREAS OF NEW
- 8 REMOVE & REPLACE EXIST. WD. WINDOW (TYP.) UNLESS NOTED OTHERWISE.
- (9) STAINED GLASS WINDOWS TO REMAIN
- (10) REHABILITATE EXIST. WD. BAY WINDOW & PAINT
- (11) EXIST. GLASS BLOCK TO REMAIN
- (12) REMOVE EXIST. GLASS BLOCK & PROVIDE NEW D.H. WINDOW TO MATCH EXISTING
- (13) REMOVE STORM WINDOW & FRAME
- (14) STL. SASH WINDOW TO BE REMOVED & REPLACED TO MATCH EXISTING
- (15) REPLACE EXIST. WD FRAME AND LOUVER W/ NEW MTL/ FRAME & LOUVER
- (16) REPLACE EXIST. VENT WITH NEW VENT
- 17) EXISTING STEEL FIRE ESCAPE TO REMAIN; CLEAN, REPAIR, & PAINT
- (18) PAINT EXIST. STL. SUPPORTS
- (19) NEW MASONRY OPENING W/ NEW DOOR & FRAME W/ MASONRY ARCH LINTEL TO MATCH EXISTING
- (20) NEW ALUM. DOOR & FRAME IN EXISTING OPENING
- (21) EXIST. ALUM. DOOR TO REMAIN
- (22) EXIST. WD DOOR & FRAME TO BE REMOVED AND REPLACED W/ NEW H.M. DOOR & FRAME
- 23) EXIST. ACCESS HATCH TO BE PAINTED
- (24) EXIST. GUTTER & DOWNSPOUTS TO REMAIN
- (25) EXIST. SURFACE MNTD. CONDUIT TO REMAIN
- (26) EXIST. SIGNAGE TO REMAIN
- (27) EXIST. ADDRESS TO REMAIN
- 28) REMOVE EXIST. FABRIC CANOPY COMPLETE INCLUDING
- ANCHORS, SUPPORTS. ETC.
- (29) EXIST. VENT TO BE REMOVED
- (30) EXIST. CAMERA TO REMAIN
- (31) EXIST. LIGHT TO REMAIN (32) EXIST. WALL SCONCE TO REMAIN
- (33) NEW LIGHT IN EXIST. LOCATION
- (34) EXIST. CEMENT STEP TO REMAIN
- (35) EXIST. LIMESTONE STEPS (NO WORK)
- (36) NEW WINDOW IN EXISTING DOOR OPENING.
  REMOVE STONE THRESHOLD AND INFILL WITH BRICK & STONE WINDOW SILL TO MATCH EXISTING
- (37) NEW LIGHT FIXTURE
- 38) NEW MASONRY INFILL BENEATH WINDOW TO MATCH ADJACENT MASONRY
- (39) NEW EXHAUST VENT
- 40 RESTORE EXIST. DECORATIVE IRON SECURITY GATES & WOOD DOORS
- (41) EXIST. WINDOW TO REMAIN AND BE RESTORED


Thomas Roberts Architects Wyandotte, MI 48192

734.250.4032



Building Alterations Apartment I r & Exterior / Palms / Interior

> principal in charge project manager project architect 11.04.2022




### ELEV./SECTION KEYNOTES

- 1) EXIST. LIMESTONE FACADE (NO WORK)
- (2) EXIST. LIMESTONE WALLS W/ SCUPPERS (NO WORK)
- 3 EXIST WOOD CORNICE: SCRAPE PRIME & PAIN
- ③ EXIST. WOOD CORNICE; SCRAPE, PRIME, & PAINT
- (4) EXIST. ASPHALT SHINGLE SIDING TO REMAIN. PATCH AS REQUIRED AT NEW WINDOW INSTALLATION
- 5 SCRAPE, PRIME, & PAINT EXIST. MTL. CORNICE
- (6) REMOVE MTL. SIDING & INSTALL WD. PANELS & TRIM TO MATCH ABOVE & PAINT
- 7 EXISTING BRICK: CLEAN & PATCH AT AREAS OF NEW WORK
- 8 REMOVE & REPLACE EXIST. WD. WINDOW (TYP.) UNLESS NOTED OTHERWISE.
- 9 STAINED GLASS WINDOWS TO REMAIN
- (10) REHABILITATE EXIST. WD. BAY WINDOW & PAINT
- 11) EXIST. GLASS BLOCK TO REMAIN
- (12) REMOVE EXIST. GLASS BLOCK & PROVIDE NEW D.H. WINDOW TO MATCH EXISTING
- (13) REMOVE STORM WINDOW & FRAME
- (14) STL. SASH WINDOW TO BE REMOVED & REPLACED TO MATCH EXISTING
- (15) REPLACE EXIST. WD FRAME AND LOUVER W/ NEW MTL/ FRAME & LOUVER
- (16) REPLACE EXIST. VENT WITH NEW VENT
- (17) EXISTING STEEL FIRE ESCAPE TO REMAIN; CLEAN, REPAIR, & PAINT
- (18) PAINT EXIST. STL. SUPPORTS
- (19) NEW MASONRY OPENING W/ NEW DOOR & FRAME W/ MASONRY ARCH LINTEL TO MATCH EXISTING
- 20) NEW ALUM. DOOR & FRAME IN EXISTING OPENING
- (21) EXIST. ALUM. DOOR TO REMAIN
- (22) EXIST. WD DOOR & FRAME TO BE REMOVED AND REPLACED W/ NEW H.M. DOOR & FRAME
- (23) EXIST. ACCESS HATCH TO BE PAINTED
- (24) EXIST. GUTTER & DOWNSPOUTS TO REMAIN
- (25) EXIST. SURFACE MNTD. CONDUIT TO REMAIN
- 26 EXIST. SIGNAGE TO REMAIN
- (27) EXIST. ADDRESS TO REMAIN
- (28) REMOVE EXIST. FABRIC CANOPY COMPLETE INCLUDING ANCHORS, SUPPORTS. ETC.
- (29) EXIST. VENT TO BE REMOVED
- 30 EXIST. CAMERA TO REMAIN
- (31) EXIST. LIGHT TO REMAIN
- (32) EXIST. WALL SCONCE TO REMAIN
- 33) NEW LIGHT IN EXIST. LOCATION
- 34) EXIST. CEMENT STEP TO REMAIN
- (35) EXIST. LIMESTONE STEPS (NO WORK)
- (36) NEW WINDOW IN EXISTING DOOR OPENING.
  REMOVE STONE THRESHOLD AND INFILL WITH BRICK &
  STONE WINDOW SILL TO MATCH EXISTING
- 37) NEW LIGHT FIXTURE
- (38) NEW MASONRY INFILL BENEATH WINDOW TO MATCH ADJACENT MASONRY
- (39) NEW EXHAUST VENT
- (40) RESTORE EXIST. DECORATIVE IRON SECURITY GATES & WOOD DOORS
- (41) EXIST. WINDOW TO REMAIN AND BE RESTORED

Thomas Roberts Architects

2927 4th Street
Wyandotte, MI 48192

734.250.4032




Palms Apartment Building Interior & Exterior Alterations


TR
principal in charge
TR
project manager
TR
project architect
SM
drawn
11.04.2022


print date


21023.00 job number A303

ТҮРЕ	QTY.	LOCATION		DOW IZE	MATERIAL	TYPE	DETAIL SHEET	NOTES	WINDOW ELEV	, , , ,
A1	36	E, S: 1-6	W 48	H 77	EX WD/ N ALUM.	EX DH/ N SH	A609			
A1 A2	12	EC, WC: 1-6	48	77	EX WD/ N ALUM.	EX DH/ N SH	A610		4'-0"	
А3	6	W: 1-6	48	77	EX WD/ N ALUM.	EX DH/ N SH	A609		 	
В	18	E: 1-6	38	77	EX WD/ N ALUM.	EX DH/ N SH	A609			
C1	18	E: 1-6 N, W: 1-6	30	51 51	EX WD/ N ALUM.  EX WD/ N ALUM.	EX DH/ N SH EX DH/ N SH	A609 A609			
D D	3	E: 2, 3, 5	14	42	EX STL/ N STL	CASEMENT	A613		- 6-5-	
E1	6	E: 1-6	48	77	EX WD/ N ALUM.	EX DH/ N SH	A609			
E2	12	E: 1-6	32	77	EX WD/ N ALUM.	EX DH/ N SH	A609			
F1 F2	66	N, E, S, W: 1-6 W: 1-6	42	77	EX WD/ N ALUM.  EX WD/ N ALUM.	EX DH/ N SH EX DH/ N SH	A609 A609			
G FZ	5	E: B	50	75	WD WD	CASEMENT	7007	EXISTING TO REMAIN		
Н	2	N, E: B	42	68	EX WD/ N ALUM.	EX DH/ N SH	A609		A1, A3	
J	1	E: B	32	49	EX WD/ N ALUM.	EX DH/ N SH	A609		,, ,	
K1	8	S: 2-5	32	77	EX WD/ N ALUM.  EX WD/ N ALUM.	EX DH/ N SH EX DH/ N SH	A611			
K2 K3	3	S: 2-5 S: 6	18 32	77 72	EX WD/ N ALUM.	EX DH/ N SH	A611			
L	13	N: 1-6	48	68	EX WD/ N ALUM.	EX DH/ N SH	A609			
М	1	N: 1	48	88	EX WD/ N ALUM.	EX DH/ N SH	A609			
N	1	N: B	48	51	EX WD/ N ALUM.  EX WD/ N ALUM.	EX DH/ N SH  EX CASEMENT/ N	A609		3'-6"	
Р	10	N: 1-5	20	48		FIXED			Ĭ 	
Q	2	WC: B EC, WC: 1-6	48 78	66 77	EX WD/ N ALUM.  EX WD/ N ALUM.	EX DH/ N SH EX DH/ N SH	A610 A610			
R S	23	EC, WC: 1-6 EC, WC: B	32	66	EX WD/ N ALUM.	EX DH/ N SH	A610		21.9	
T	5	WC: 1-5	36	69	EX WD/ N ALUM.	EX DH/ N SH	A610		\dot \big  \dot \dot \big	
U	4	WC: B-3, 6	40	66	EX WD/ N ALUM.	EX DH/ N SH	A610			
V	1	WC: B	24	51 77	EX WD/ N ALUM.  EX WD/ N ALUM.	EX DH/ N SH EX DH/ N SH	A610 A610		<u> </u>	
W Y	12	WC: 2 EC, WC: 1-6	30	51	EX WD/ N ALUM.	EX DH/ N SH	A610			
Z	7	NC, EC: B-6	24	41	EX WD/ N ALUM.	EX DH/ N SH	A610		1.1	
AA	3	EC: B	30	33	EX WD/ N ALUM.	AWNING	A610		Н	
BB	1	NC: 1	78	72	WD WD	CASE/HODDED		EXISTING TO REMAIN		
CC DD	5 18	NC: 2-6 N: 1-6	78 42	92	EX WD/ N ALUM.	CASE/HOPPER EX DH/ N SH	A612	EXISTING TO REMAIN		
EE1	12	W: 1-6	42	60	EX WD/ N ALUM.	EX DH/ N SH	A612			
EE2	24	W: 1-6	30	60	EX WD/ N ALUM.	EX DH/ N SH	A612			
FF1	1	WC: 5	26	77	EX WD/ N ALUM.	EX DH/ N SH	A612			
FF2 GG	2	WC: 5 S, W: B	16	77 55	EX WD/ N ALUM.  GB	EX DH/ N SH FIXED	A612	EXISTING TO REMAIN		+
HH	1	E: B	21	43	EX GB/ N ALUM	EX FIXED/ N SH	A609		<u> 1'-8"</u>	
JJ	3	S: B	45	41	GB	FIXED		EXISTING TO REMAIN		
KK	1	S: B	45	65	GB	FIXED FIXED		EXISTING TO REMAIN		
LL MM	1	N: B N: B	37 23	45 45	GB GB	FIXED		EXISTING TO REMAIN  EXISTING TO REMAIN	10-14	
NN	5	W: B	37	33	GB	FIXED		EXISTING TO REMAIN		
PP	2	W: B	37	27	GB	FIXED		EXISTING TO REMAIN		
QQ	4	E, S: B	43	55	EX GB/ N ALUM.	EX FIXED/ N SH	A609			
FI F\	VATIONS	LOCATION	ON INFO	OITAMS	N FLOC	290		WINDOW SCHEDULE	Р	
N E	NORTH EAST	E, S, W	V, EC, WC	2: 1-6	В	BASEMENT FLOORS 1-6		ABBREVIATIONS		
S W	SOUTH WEST			<u> </u>		FLOORS 2, 3, & 5		ALUM ALUMINUM  CASE CASEMENT		
NC EC	NORTH C	COURTYARD URTYARD						DH DOUBLE-HUNG		
WC		DURTYARD						GB GLASS BLOCK		
								N NEW SH SINGLE HUNG		
								WD WOOD		
									2'-0"	<b>.</b>
										Ĭ ſi
									3-5-	
									-	
									Z	












SM drawn 11.04.2022 print date 21023.

project manager

project architect

TR

21023.00 job number
A603



# $\mathsf{TRA}$

2927 4th Street Wyandotte, MI 48192 homasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207



TR
principal in charge
TR
project manager
TR
project architect
SM
drawn

11.04.2022 print date 21023

job number A609 sheet number






2927 4th Street Wyandotte, MI 48192 homasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207



TR
principal in charge
TR
project manager
TR
project architect
SM
drawn

11.04.2022 print date 21023

job number
A610
sheet number




# $\mathsf{TRA}$

2927 4th Street Wyandotte, MI 48192 nomasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207



TR principal in charge TR project manager TR project architect SM drawn

11.04.2022 print date 21023 job number

A611 sheet number



# TRA

2927 4th Street Wyandotte, MI 48192 nomasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207





TR principal in charge TR project manager TR project architect

11.04.2022 print date 21023

job number A612 sheet number











2927 4th Street Wyandotte, MI 48192 homasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations

1001 E. Jefferson Ave. Detroit, Mi 48207


HDC REVIEW	_	11-04-2022			
		HDC REVIEW			

TR
principal in charge
TR
project manager
TR
project architect

11.04.2022 print date

21023 job number

A613 sheet number





2927 4th Street Wyandotte, MI 48192 homasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207



TR
principal in charge
TR
project manager
TR
project architect
SM
drawn

11.04.2022 print date 21023

job number A614 sheet number






2927 4th Street Wyandotte, MI 48192 nomasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207



TR
principal in charge
TR
project manager
TR
project architect
SM
drawn

11.04.2022 print date 21023

job number A615 sheet number




# TRA

2927 4th Street Wyandotte, MI 48192 homasrobertsarchitect.com 734.250.4032

#### Palms Apt. Alterations


1001 E. Jefferson Ave. Detroit, Mi 48207




TR
principal in charge
TR
project manager
TR
project architect
SM
drawn

11.04.2022 print date 21023


job number A616 sheet number



TYPICAL NEW WINDOWS @ BRICK



TYPICAL NEW WINDOWS @ BRICK WITH MULL




TYPICAL NEW WINDOWS @ STONE


THE PALMS BUILDING DETROIT, **ELEVATIONS** PHONE (573)-744-528

PAX (573)-744-5586

COMMERCIAL

C Drawing Created 10/14/22





Drawing Created 10/14/22

