

2984 Iroquois Driveway Gate Application

Homeowner requests approval to install a 10-foot wide by 5-foot-tall chain link style driveway gate to the existing masonry fence at 2984 Iroquois, Indian Village HD. Fence is primarily to control two dogs.

The existing fence on the back of the house is brick and block with a pebbledash stucco covering (that has failed in some areas) on two sides, with a chain link fence on the south side of the property. These fences have been in place for many decades.

The proposed gate is also chain link in style, to harmonize with the one non masonry fence. Chain link gates and fences are common in the HD as well. Gate appearance and specification are included here. Lowes Model #58090322

The fence posts will be placed “behind” the masonry walls and towards the rear of the property to allow for opening as wide as possible to avoid possibility of striking cars backing out of the driveway.





Detail, driveway, and walls looking east.



Looking west to Iroquois.


Gate posts will be centered behind the masonry fence "pillars."



Existing old chain link fence, facing



<https://www.lowes.com/pd/Common-10-Actual-x-9-5-Powder-Coated-Steel-Driveway-Gate/1000802222>



Proposed gate. Model specifics in link.