


From: [sterling howard](#)
To: [Dan Rieden](#)
Subject: [EXTERNAL] Re: 3515 Sherbourne
Date: Thursday, September 7, 2023 10:25:15 AM
Attachments: [image001.png](#)

Please find pics attached.



LIVE







Sent from my iPhone

On Sep 7, 2023, at 10:21 AM, sterling howard <showard@silvercapitalgroupllc.com> wrote:

Dan – Thanks for taking time to chat with me yesterday. I can't readily find pictures of the 13 steel windows that were removed. The old windows were corroded, inoperable and contaminated with lead paint. The replacement windows match the 28 other windows that were replaced by a previous owner. I will forward pictures and location of the new windows under separate cover. Please review the manufacturer's website for more detailed product information <https://www.northstarwindows.com/windows/>.