September 29, 2017

CERTIFICATE OF APPROPRIATENESS

Sherrell Holmes 1427 Edison Detroit MI 48206

RE: Application Number 17-5375, 1427 Edison; Boston Edison Historic District

Dear Ms. Holmes:

Pursuant to Section 5(10) of the Michigan Local Historic District Act, as amended, being MCL 399.205(10), MSA 5-3407(5)(10); Section 25-2-57(b) of the 1984 Detroit City Code; Detroit Historic District Commission Resolution 97-01 (adopted August 13, 1997); Detroit Historic District Commission Resolution 98-01 (adopted February 11, 1998), the staff of the Detroit Historic District Commission has reviewed the above-referenced application for building permit and hereby issues a Certificate of Appropriateness (COA) which is effective as of September 29, 2017.

Staff finds the below-listed work appropriate:

- The existing concrete porch slab and steps will be retained. If their condition is too deteriorated, the pouring of a new concrete porch slab and new concrete steps shall be composed of exposed aggregate, tinted gray or finished with a clear clearing compound as not to be "bright white".
- Temporary supports shall be put in place during porch slab repair, demolition/construction so the pediment shall remain in place and not suffer structural damage.
- The remaining existing brick column to the right of the steps shall be retained. The damaged and incorrectly colored brick at the base of the column will be replaced with brick that matches the historic brick in dimension, color and profile.
- The column constructed of orange brick will be dismantled. The column will be rebuilt to match the historic column in location, dimension and design; brick that matches the historic brick in dimension, color and profile shall be used.
- Bricks surrounding the porch base and stepped wing walls shall also match the historic brick. The
 existing stone (or concrete) wing wall tops shall be reused.
- A historic mortar mix (as it must be softer than contemporary mortar) matching the composition, width, color and profile of the existing mortar joints shall be used.
- All construction shall not extend beyond the existing footprint of the porch and stairs.
- Should the building code require railings, the previous railings can be re-installed and painted black to match its previous condition. If new railings are required, the design shall be submitted for staff review.

as the project meets the "Secretary of the Interior's Standards for Rehabilitation" Standard Number #6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be

BUILDING PERMIT APPLICATION

CITY OF DETROIT

BUILDINGS, SAFETY ENGINEERING & ENVIRONMENTAL DEPARTMENT 2 WOODWARD AVENUE, ROOM 409, DETROIT, MICHIGAN 48226

Expedited Plan Review Re	equest (subject to additional fees)	Date:	9/18/17
Property Information			
Address: 1427 Fdis	501 Det MI 4820	Floor: Suite#:	Stories: 7
AKA:	Lot(s		vision: Boston - Bolisa
Parcel ID#(s):		Acres: 25 Lot Width:	Lot Depth:
Current Legal Use of Property:	Residential	Proposed Use:	
Are there any existing buildings	or structures on this parcel?	✓ Yes No	444 (40.1/4)
Project Information	THE RESERVE OF THE PARTY OF THE		
Permit Type			
New Alteration Add	ition Demolition Correct	Violations 🔲 Foundation Or	nly Temporary Use
Change of Use Oth			_
Revision to Original Permit #	:(0	original permit has been issued	and is active)
Description of Work (Describe in	detail proposed work and use of proposed	roperty, attach work list)	1
Rebuilding front	Berck WALL Of DU	ech, fixine Sta	it wall on
jest side atom	that to be	den crimin hen	E color
		MBC use change	No MBC use change
Included Improvements (Check	all applicable; these trade areas re	equire separate permit application	ons)
HVAC/Mechanical	Electrical Plumbing	Fire Sprinkler System	Fire Alarm
Structure Type			
	tructure 🔲 Tenant Space 🔲 🤆	Garage/Accessory Building	Other
Size of Structure to be Demolis			ubic feet
Construction involves changes	to the floor plan? (e.g. interior dem	nolition or constructing new walls)	Yes 🔲 No
Use Group:	Type of Construction (per curre	nt MI Bldg Code Table 601):	
Estimated Cost of Construction		\$	
Structure Use	By Contractor	By Departme	nt
Residential-Number of Units:	Office-Gross Floo	r Area: Industri	al-Gross Floor Area:
Commercial-Gross Floor Area:	Institutional-Gros	ss Floor Area: Othe	r-Gross Floor Area:
Proposed no. of employees:	List materials to b	be stored in the building:	(
PLOT PLAN SHALL BE submitte	ed on separate sheets and shall show all ea	sements and measurements (must be c	orrect and in detail).
SHOW ALL streets a	butting lot, indicate front of lot, show all bu (Building Permit Application Conti		s to lot lines.
	FOR BUILDING DEPARTM		
Intake by:	Date:	Fees Due:	DngBld? ☐ No
Permit Description			
Current Legal Land Use:	Proposed Use:		
Permit#:	Date Permit Issued:	Permit Cos	:t: \$
Zoning District:	Zoning Grant(s):	Lots Combined? Yes	No (attach zoning clearance)
Revised Cost (revised permit application	ons only) Old \$	New \$	
STRUCTURAL:	DATE:	NOTES:	3
ZONING:	DATE:	NOTES:	
OTHER:	DEPT:	DATE:	
			2/15/2015

PERMIT #

HD1, #17-5375 Slove 9129/17









Audra Dye - Re: 1427 Edison

From: sherrell Holmes <sherrellmorrisholmes@gmail.com>

To: Audra Dye <dyea@detroitmi.gov>

Date: 9/25/2017 11:44 AM **Subject:** Re: 1427 Edison

I found matching brick from a antique brick yard in highland park. Here are picks top is new bottom is one from the house.





On Wed, Sep 20, 2017 at 4:14 PM Audra Dye < dyea@detroitmi.gov > wrote:

Good Afternoon,

Upon seeing the true scope of work, as the project has already begun, there are a few issues to be addressed. HDC staff can't approve the brick that is being used. The new brick must match the existing brick not only in dimension and color, but also pattern. Painting it won't match the old brick. An equally important element is the mortar, that must also match the mortar on the house.

Other questions from reviewing the photographs:

- --Has one wing wall been rebuilt? It is a different color than the remaining original porch column and different than the orange brick.
- --Are the stairs remaining? Why do they look the way they do?
- --What happened to the side of the porch near the driveway? How will that be fixed?

In closing, what is being constructed won't be approved. Please submit a corrected scope of work, detailing each component of the project (including the new railings). I've copied one of the city's building inspector's on this email so she can offer guidance on what additional information needs to be provided to the city for review of the construction work related to the porch.

You can submit everything via email. Thank you.

I will be out of the office 9/21 - 9/25. I've copied my colleague Jennifer Ross, on this email should you have questions in my absence.

CITY OF DETROIT HISTORIC DISTRICT COMMISSION

65 CADILLAC SQ., SUITE 1300 DETROIT, MICHIGAN 48226 PHONE 313-224-6536 FAX 313-224-1310

July 13, 2006

CERTIFICATE OF APPROPRIATENESS

Marko Jovanovic 17117 W. Nine Mile #1319 Southfield MI, 48075

RE: Application Number 06-96; 1427 Edison; Boston Edison Historic District

Dear Jovanovic:

Pursuant to Section 5(10) of the Michigan Local Historic District Act, as amended, being MCL 399.205(10), MSA 5-3407(5)(10); Section 25-2-57(b) of the 1984 Detroit City Code; Detroit Historic District Commission Resolution 97-01 (adopted August 13, 1997); Detroit Historic District Commission Resolution 97-02 (adopted October 8, 1997); and Detroit Historic District Commission Resolution 98-01 (adopted February 11, 1998), the staff of the Detroit Historic District Commission has reviewed the above-referenced application for building permit and hereby issues a Certificate of Appropriateness, which is effective as of July 13, 2006.

The staff finds the work appropriate for the following reasons:

The replacement of the wood windows with new wood windows to match the existing in size, operation and muttin pattern meets "The Secretary of the Interior's Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings" standard number 6, "Deteriorated historic features shall be repaired than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence."

Please retain this Certificate of Appropriateness for your files. You should now proceed to obtain a building permit from the City of Detroit Buildings and Safety Approval by the Detroit Historic District Commission does not waive the applicant's responsibility to comply with any other applicable ordinance or statute. If you have any questions regarding the foregoing, please telephone the Detroit Historic District Commission at 224-6536.

For the Commission:

Susan M. McBride

Staff

Detroit Historic District Commission

Lall for

copy: Shanker Warrier, B&SE