### #DETROITDEMO

POWERE BY PROP

### **Detroit Construction & Demolition Newsletter** As of **September 30, 2024**

### **STABILIZATION**

The Construction & Demolition Department created the Vacant Property Unit. This unit will use Prop N funds to clear out & secure vacant homes.





# OUR PARTNERS

**1st Choice Hauling AW Preservation Bing Youth Institute Cleaning Up Detroit Detroit Grounds Crew** Gayanga **GTJ Consulting/MWV Huntman Transport J. Keith Construction Emerging Industries Training Institute Motor City Preservation Payne Landscaping Premier Group** P & P Group **Resourceful Vending RT Contracting Staffing Equipment Evolution** 

# **CLEAR BOARDS**

Our Securing Team uses Polycarbonate Clear Board, a superior material for boarding, offering strength, durability, and aesthetic appeal beyond traditional options like plywood or metal.



as of 9/30/2024

### **Demo Dashboard Overview**







HOMES CONTRACTED USING BOND FUNDING



PENDING ABATEMENT



HOMES DEMOLISHED

As of 9/30/2024



HOMES CURRENTLY OUT FOR BID

539

## READY FOR DEMOLITION

6,780

DEMOLITIONS THAT HAVE BEEN GRADED





DEMOLITIONS & STABILIZATIONS	DISTRICT 1	DISTRICT 2	DISTRICT 3	DISTRICT 4	DISTRICT 5	DISTRICT 6	DISTRICT 7
Completed Residential Demos	577	424	1,803	1,514	639	876	1,053
Remaining	76	42	238	257	129	56	168
Completed Stabilizations	199	120	<b>607</b>	515	388	284	<b>413</b>
Remaining	42	98	226	184	99	40	104
Completed Commercial Demos	13	24	<b>40</b>	33	76	61	48
Remaining	14	18	31	22	28	24	21

As Of September 2024

# September Metrics

## **Emergency Demolition Performance**

Demolition Contractor	EMG Count	Within EMG Timeline
Adamo	1	100%
Detroit Next	3	0%
DMC Consultants	3	67%
Homrich	1	100%
Inner City	1	100%
Salenbien	8	88%

## September 2024 Payments

Contractor	Sum	Sum of Amount Paid			
ADAMO DEMOLITION COMPANY	\$	323,343.50			
ATC GROUP SERVICES	\$	45,095.00			
Detroit Next Inc.	\$	39,500.00			
DLZ	\$	22,440.00			
DMC CONSULTANTS INC	\$	842,873.00			
GAYANGA CO	\$	1,075,988.00			
GTJ CONSULTING LLC	\$	302,114.00			
Inner City Contracting, LLC	\$	1,711,535.11			
LEADHEAD CONSTRUCTION LLC	\$	1,100.00			
LIMBACH COMPANY LLC	\$	50,735.48			
MacDermott Roofing, Inc	\$	6,127.79			
P & P Group Inc.	\$	16,900.00			
PREMIER GROUP ASSOCIATES LC	\$	3,787.50			
Salenbien Trucking and Excavating, Inc.	\$	394,544.65			
SC Environmental Services, LLC	\$	244,742.00			
Grand Total	\$5,080,826.03				

### 12 Month Discipline Report

account Name amo Group, Inc.	Date Issued	Infraction Type	Contractor Violation: Contractor Violation Name	Notes	Notice of Appeal Dat	le outcome of Hearing	Disqualification Start D	Disqualification
	10/11/2023	Warning	VIO-000788	Missed Commercial Benchmarks-Bond Groups-203 & 207. Letter rescinded due to missing permits.				
	4/5/2024	Warning	VIO-000789	Missed Commercial Benchmarks.				
Blue Star								
	11/7/2023	Warning	VIO-000745	Over 14 Days since OH approved no FG Grade request-4 properties.				
Detroit Next								
	12/8/2023	Warning	VIO-000753	Warning-Missed Term of Performance for Emergency Property-19608 Coventry.				
	8/26/2024	Warning	VIO-000814	Warning-Missed Term of Performance for Emergency Property-18635 Albany and 6219 Stahelin.				
IC Consultants								
	10/25/2023	Warning	VIO-000743	Properties (19) Over 14 Days since Open Hole Approved-no Final Grade requested.				
	11/7/2023	Warning	VIO-000746	Properties (22) Over 14 Days since Open Hole Approved-no Final Grade requested. Over 14 Days since OH				
	44/20/2022	LOD New Collectores	1//0 000350	approved-no FG request-18 properties. Due to a history of this type of violation it resulted in an automatic LOD.		Colorentiated		
	11/29/2023 2/12/2024	LOD - Non-Salesforce Warning	VIO-000759 VIO-000769	Warning-missing Water Pipe Material information-12 properties.		Substantiated Other		
	2/12/2024	warning	10-000789	warning-missing water Pipe Material mornation-12 properties.		other		
	4/29/2024	Warning	VIO-000792	Missed an Demo Performance Benchmark-2 (50%) for Bond Groups Q1&2.See attached Salesforce report.				
	5/13/2024	Warning	VIO-000796	Missed EMG timeline on a property located at 17144 Harlow.				
				A section of asphalt near 5968 Seminole, between Lambert and Medbury, was damaged. See attached				
	6/17/2024	LOD - Non-Salesforce	VIO-000806	pictures. DMC has acknowledged responsibility for this damage. Paid for damage-Invoice attached.	6/17/2024	UnSubstantiated		
				Missed a Demo Performance Benchmark-3 (75%) for Bond Groups Q1 (64%), & Q2 (64%). See attached				
	7/1/2024	Warning	VIO-000807	Salesforce report.				
yanga Co. LLC		<u> </u>						
	10/23/2023	Warning	VIO-000741	Failure to wait for verification on the PASV Smartsheet before starting abatement work-7123 Chatfield.		Other		
	2/13/2024	Warning	VIO-000775	Missed Abatement Performance Milestones-1 (25%) for Bond Groups Q10 and Q11.		Other		
	2/21/2024	Warning	VIO-000776	Missed Demolition Performance Milestones-1 (25%) for Bond Groups Q10, Q11 & Q12.		Other		
				Health and Safety Violation: Failure to Remove or Report asbestos containing waste material-floor tile to				
	2/29/2024	HSV-3D	VIO-000779	Demolition Department. Deputy Director unsubstantiated violation. Over 7 days since knock-no OH	2/29/2024	UnSubstantiated		
	3/27/2024	Warning	VIO-000786	request.		Other		
				Missed Abatement Performance Milestones-1 (50%) for Bond Groups Q10 and Q11. They had abatement				
	5/3/2024	Warning	VIO-000791	issues in Jan and Feb 2024.		Other		
	0/4/000		100 000000	Palling to fallen and a state of fallen state in the second state of the second state of the	0/40/2000	Coloring and the		
	9/4/2024	LOD - Non-Salesforce	VIO-000815	Failure to follow proper protocol for a fallen electric line-19245 Albany. Upheld by Deputy on 10/3/24.	9/12/2024	Substantiated		
	0/10/2027	IOD New Colorford	1/10.000010	Missed Demolition Performance Benchmark-4 (100%) for Bond Groups: Q10, Q11, and Q12.Appealed. Also,	0/20/2024	Cubetani		
Homrich	9/19/2024	LOD - Non-Salesforce	VIO-000818	requested extension on above groups. Upheld by deputy.	9/26/2024	Substantiated		
Homrich								
	6/12/2024	Warning	VIO-000804	Warning: damage of fencing at 7575 Palmetto due to the collanse of the property's exterior rear wall				
ty Contracting, LLC	6/12/2024	Warning	VIO-000804	Warning: damage of fencing at 7575 Palmetto due to the collapse of the property's exterior rear wall.				
ty Contracting, LLC								
ty Contracting, LLC	10/20/2023	Warning	VIO-000740	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.				
ty Contracting, LLC								
ity Contracting, LLC	10/20/2023 12/8/2023	Warning	VIO-000740 VIO-000755	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke.				
ty Contracting, LLC	10/20/2023	Warning Warning	VIO-000740	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023	Warning Warning Warning	VIO-000740 VIO-000755 VIO-000757	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024	Warning Warning Warning Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000757	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024	Warning Warning Warning Warning Warning	VIC-000740 VIC-000755 VIC-000757 VIC-000761 VIC-000763	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties Missing abatement details for 55 properties.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024	Warning Warning Warning Warning Warning	VIC-000740 VIC-000755 VIC-000757 VIC-000761 VIC-000763	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties Missing abatement details for 55 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/12/2024	Warning Warning Warning Warning Warning Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000781 VIO-000781 VIO-000768	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties Missing abatement details for 55 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/12/2024 2/12/2024	Warning Warning Warning Warning Warning Other	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000763 VIO-000781 VIO-000768 VIO-000799	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missing abatement details for 55 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/12/2024	Warning Warning Warning Warning Warning Other Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000781 VIO-000781 VIO-000768	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missing abatement details for 55 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days Missed Demolition Benchmark-1 (25%) Bond Group Q20.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/12/2024 2/12/2024	Warning Warning Warning Warning Warning Other Warning Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000763 VIO-000781 VIO-000768 VIO-000799	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark: (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/31/2024 2/9/2024 2/12/2024 2/15/2024 2/21/2024	Warning Warning Warning Warning Warning Other Warning Warning Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000781 VIO-000781 VIO-000781 VIO-000799 VIO-000799 VIO-000777	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Laison, the wrong property would have been knocked. See attached conference record				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/12/2024 2/12/2024	Warning Warning Warning Warning Warning Other Warning Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000763 VIO-000781 VIO-000768 VIO-000799	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missing abatement details for 55 properties.   Missed entering the Kniestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liason, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/12/2024 2/12/2024 2/15/2024 2/15/2024 2/29/2024	Warning Warning Warning Warning Warning Other Warning Warning Warning Warning Other	VIC-000740 VIC-000755 VIC-000757 VIC-000761 VIC-000763 VIC-000781 VIC-000781 VIC-000768 VIC-000799 VIC-000777	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/31/2024 2/9/2024 2/12/2024 2/15/2024 2/21/2024	Warning Warning Warning Warning Warning Other Warning Warning Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000781 VIO-000781 VIO-000781 VIO-000799 VIO-000799 VIO-000777	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days Missed Demolition Benchmark-1 (25%) Bond Group Q20. Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024	Warning Warning Warning Warning Warning Other Warning Warning Warning Other Other	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000768     VIO-000799     VIO-000777     VIO-000780     VIO-000784	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 2/29/2024 3/22/2024	Warning Warning Warning Warning Warning Warning Warning Warning Other Other Other Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000768 VIO-000781 VIO-000768 VIO-000777 VIO-000777 VIO-000780 VIO-000784 VIO-000785	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone Sond Group A3/AB Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Lision, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024	Warning Warning Warning Warning Warning Other Warning Warning Warning Other Other	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000768     VIO-000799     VIO-000777     VIO-000780     VIO-000784	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days Missed entering the Planned knock-down date for 4 properties. Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event. Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete- 43. Abatement rolling pct-44%. Don't count. Timeline revised. Over 14 Days since Open Hole-No FG request-36 properties.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Warning Warning	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000768     VIO-000777     VIO-000780     VIO-000786     VIO-000780     VIO-000785     VIO-000785	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liason, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Poling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 1/31/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 2/29/2024 3/22/2024	Warning Warning Warning Warning Warning Warning Warning Warning Other Other Other Warning	VIO-000740 VIO-000755 VIO-000757 VIO-000761 VIO-000763 VIO-000768 VIO-000781 VIO-000768 VIO-000777 VIO-000777 VIO-000780 VIO-000784 VIO-000785	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missed invoice cut-off date Milestone-Bond Group AJ/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days Missed Demolition Benchmark-1 (25%) Bond Group Q20. Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from LDDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event. Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete- 43. Abatement rolling pct-44%. Don't count. Timeline revised. Over 14 Days since Open Hole-No FG request-36 properties. Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.	5/9/2024	Substantiated	8/26/2024	9/25/20
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/12/2024 2/12/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000788     VIO-000799     VIO-000780     VIO-000781     VIO-000780     VIO-000780     VIO-000785     VIO-000799	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Direct Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCD Field Laison, the wrong property would have been knocked. See attached conference card from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Wrongful demolition. Di56 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 4/18/2024 7/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000768     VIO-000768     VIO-000799     VIO-000780     VIO-000784     VIO-000785     VIO-000780	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised. Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. a65 days suspension. <td>5/9/2024 7/12/2024</td> <td>Substantiated</td> <td>8/26/2024 8/26/2024</td> <td>9/25/20</td>	5/9/2024 7/12/2024	Substantiated	8/26/2024 8/26/2024	9/25/20
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/12/2024 2/12/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000788     VIO-000799     VIO-000780     VIO-000781     VIO-000780     VIO-000780     VIO-000785     VIO-000799	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days Missed Demolition Benchmark-1 (25%) Bond Group Q20. Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event. Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete- 43. Abatement rolling pct-44%. Don't count. Timeline revised. Over 14 Days since Open Hole-No FG request-36 properties. Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dr. needed time to review with EDD team. Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. Joil 46 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 365 days suspension. Over 14 Days since Open Hole-No FG request-36 properties.				
ty Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other LOD - Non-Salesforce	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000788     VIO-000799     VIO-000780     VIO-000784     VIO-000785     VIO-000790     VIO-000790	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their   fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately we		Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 4/18/2024 7/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000768     VIO-000768     VIO-000799     VIO-000780     VIO-000784     VIO-000785     VIO-000780     VIO-000780	Failed to timely enter the Start and Finish dates on the PASV Smartsheet. Missed an emergency timeline for a property at 11850 Van Dyke. Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock. Over 14 Days since Open Hole-No FG request-20 properties. Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion. Missed entering the Planned knock-down date for 4 properties. Properties over 30 days Missed Demolition Benchmark-1 (25%) Bond Group Q20. Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event. Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete- 43. Abatement rolling pct-44%. Don't count. Timeline revised. Over 14 Days since Open Hole-No FG request-36 properties. Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dr. needed time to review with EDD team. Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. Joil 46 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 365 days suspension. Over 14 Days since Open Hole-No FG request-36 properties.		Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other LOD - Non-Salesforce	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000788     VIO-000799     VIO-000780     VIO-000784     VIO-000790     VIO-000790	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (25%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q2. Abateme		Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024 7/11/2024 8/29/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other LOD - Non-Salesforce Warning	VIO-000740   VIO-000755   VIO-000751   VIO-000761   VIO-000763   VIO-000781   VIO-000786   VIO-000799   VIO-000780   VIO-000784   VIO-000790   VIO-000790   VIO-000808   VIO-000810   VIO-000816	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 363 days suspension.   Over 14 Days since Open Hole-No F		Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other LOD - Non-Salesforce	VIO-000740     VIO-000755     VIO-000757     VIO-000761     VIO-000763     VIO-000781     VIO-000788     VIO-000799     VIO-000780     VIO-000784     VIO-000790     VIO-000790	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bood Group A3/AS Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed invoice cut-off date Milestone-Bood Group A3/AS Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatements rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont. 1. Failure to nervoe all RACN. Z. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Wrongful dem		Substantiated		
ity Contracting, LLC	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024 3/25/2024 4/11/2024 4/11/2024 8/29/2024 10/16/2023	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other Warning EGLE Other LOD - Non-Salesforce Warning	VIO-000740     VIO-000755     VIO-000751     VIO-000761     VIO-000763     VIO-000768     VIO-000768     VIO-000780     VIO-000780     VIO-000784     VIO-000799     VIO-000780     VIO-000781     VIO-000780     VIO-000781     VIO-000780     VIO-000781     VIO-000780     VIO-000808     VIO-000808     VIO-000810     VIO-000816	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missing abatement details for 55 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 363 days suspension.   Over 14 Days since Open Hole-No F	7/12/2024	Substantiated Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/21/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024 7/11/2024 8/29/2024	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other EGLE Other LOD - Non-Salesforce Warning	VIO-000740   VIO-000755   VIO-000751   VIO-000761   VIO-000763   VIO-000781   VIO-000786   VIO-000799   VIO-000780   VIO-000784   VIO-000790   VIO-000790   VIO-000808   VIO-000810   VIO-000816	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their   fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Wrongful demolition. D156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 36 days suspension.		Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/25/2024 3/25/2024 4/11/2024 4/11/2024 8/29/2024 10/16/2023	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other Warning EGLE Other LOD - Non-Salesforce Warning	VIO-000740     VIO-000755     VIO-000751     VIO-000761     VIO-000763     VIO-000768     VIO-000768     VIO-000780     VIO-000780     VIO-000784     VIO-000799     VIO-000780     VIO-000781     VIO-000780     VIO-000781     VIO-000780     VIO-000781     VIO-000780     VIO-000808     VIO-000808     VIO-000810     VIO-000816	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure   to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Contractor Gailed to reall were the max the scheduged their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 757 Rosemont-1. Failure to meve all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dr. needed time to review with EDD team.   Wrongful demolition. 10156 Elmira was the scheduled property be knocked. Jul 46 Sey suspension.   Over 14 Days since Open Hole-No FG request-36 properties.	7/12/2024	Substantiated Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 4/11/2024 7/11/2024 8/29/2024 10/16/2023 10/16/2023	Warning Warning Warning Warning Warning Warning Warning Warning Other Other Other Other Other EGLE Other LOD - Non-Salesforce Warning Warning	VI0-000740   VI0-000755   VI0-000751   VI0-000761   VI0-000763   VI0-000781   VI0-000788   VI0-000780   VI0-000781   VI0-000780   VI0-000785   VI0-000799   VI0-000781   VI0-000781   VI0-000780   VI0-000781   VI0-000780   VI0-000781   VI0-000782   VI0-000808   VI0-000810   VI0-000810   VI0-000737   VI0-000739	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Conference Call Record: Contractor failed to Failure   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their   fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmarks 2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement Performance Benchmarks 2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement Performance Benchmarks 2 (50%) for Bond Group Cal. Abatements rolling complete-43. Abatement Performance Benchmarks 2 (50%) for Bond Group Cal. Distended their set were with EDD team.   Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 365 days suspension.   Over 14 Days since Open Hole-No FG req	7/12/2024	Substantiated Substantiated		
	10/20/2023 12/8/2023 12/8/2023 1/10/2024 1/29/2024 2/9/2024 2/9/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024 7/11/2024 8/29/2024 10/16/2023 10/17/2023	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other Other Other UD - Non-Salesforce LOD - Non-Salesforce	VIC-000740 VIC-000755 VIC-000751 VIC-000761 VIC-000763 VIC-000781 VIC-000780 VIC-000799 VIC-000780 VIC-000780 VIC-000780 VIC-000785 VIC-000785 VIC-000785 VIC-000808 VIC-000810 VIC-000810 VIC-000737 VIC-000737 VIC-000739	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Woregful demolition. 10156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 365 days suspension.   Over 14 Days since Open Hole-No FG request-36 properties.   V	7/12/2024	Substantiated Substantiated		
	10/20/2023 12/8/2023 12/12/2023 1/10/2024 1/29/2024 2/9/2024 2/15/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 4/11/2024 7/11/2024 8/29/2024 10/16/2023 10/16/2023	Warning Warning Warning Warning Warning Warning Warning Warning Other Other Other Other Other EGLE Other LOD - Non-Salesforce Warning Warning	VI0-000740   VI0-000755   VI0-000751   VI0-000761   VI0-000763   VI0-000781   VI0-000788   VI0-000780   VI0-000781   VI0-000780   VI0-000785   VI0-000799   VI0-000781   VI0-000781   VI0-000780   VI0-000781   VI0-000780   VI0-000781   VI0-000782   VI0-000808   VI0-000810   VI0-000810   VI0-000737   VI0-000739	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure   to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Demolition Benchmark-1 (25%) Bond Group Q20.   Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCDD Field Liaison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their   fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 groperties.   Violations: 757 Rosemont-1. Failure to meve all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Din needed time to review with EDD team.   Wrongful demolition. 10156 Elmira was the scheduled property to be knocked. Jul 46 Elmira was knocked on 10/4/23. Entered to 102. Substantiated. 36 days sus	7/12/2024	Substantiated Substantiated		
	10/20/2023 12/8/2023 12/8/2023 1/10/2024 1/29/2024 2/9/2024 2/9/2024 2/15/2024 2/21/2024 3/22/2024 3/22/2024 3/22/2024 3/22/2024 3/25/2024 4/11/2024 7/11/2024 7/11/2024 8/29/2024 10/16/2023 10/17/2023	Warning Warning Warning Warning Warning Other Warning Warning Other Other Other Other Other Other UD - Non-Salesforce LOD - Non-Salesforce	VIC-000740 VIC-000755 VIC-000751 VIC-000761 VIC-000763 VIC-000781 VIC-000780 VIC-000799 VIC-000780 VIC-000780 VIC-000780 VIC-000785 VIC-000785 VIC-000785 VIC-000808 VIC-000810 VIC-000810 VIC-000737 VIC-000737 VIC-000739	Failed to timely enter the Start and Finish dates on the PASV Smartsheet.   Missed an emergency timeline for a property at 11850 Van Dyke.   Missed entering the knock-down date for 11850 Van Dyke into Salesforce within one business after knock.   Over 14 Days since Open Hole-No FG request-20 properties.   Missed invoice cut-off date Milestone-Bond Group A3/A8 Conference Call Record: Contractor failed to Failure to submit Emergency Demolition Fence Plans in a timely fashion.   Missed entering the Planned knock-down date for 4 properties.   Properties over 30 days   Missed Conference Call Record: Contractor failed to verify location of scheduled demolition. Without intervention from DCD Field Laison, the wrong property would have been knocked. See attached conference record from Linda Montgomery. Conference Call Record: Subject: Miscommunication between ICC and demo team. They changed their fencing plan without informing demo team. Not a recurring event.   Missed an Abatement Performance Benchmark-2 (50%) for Bond Group Q3. Abatements rolling complete-43. Abatement rolling pct-44%. Don't count. Timeline revised.   Over 14 Days since Open Hole-No FG request-36 properties.   Violations: 7757 Rosemont-1. Failure to remove all RACM. 2. Failure to adequately wet RACM. Violation substantiated on 8/22/24. Dir. needed time to review with EDD team.   Woregful demolition. 10156 Elmira was the scheduled property to be knocked. 10146 Elmira was knocked instead. Both are contracted to ICC. Substantiated. 365 days suspension.   Over 14 Days since Open Hole-No FG request-36 properties.   V	7/12/2024	Substantiated Substantiated		

### 12 Month Discipline Report

				Missed Demolition Benchmark-4 (100%).Demo rolling completed-56% of 100%. Only 45 out of 81 properties				
	2/28/2024	LOD - Non-Salesforce	VIO-000778	completed. Deputy Dir. substantiated on 3/15/24. On 3/28/24, suspended by Director for 6 months. Failure to	3/5/2024	Substantiated	3/28/2024	9/27/2024
	4/9/2024	Warning	VIO-000787	update Planned Knock Down dates for a property.				
	4/30/2024	LOD - Non-Salesforce	VIO-000794	Missed Demolition Benchmark-4 (100%).Demo rolling completed-79% of 100%. Demo'd 63 out of 81 properties completed. Sixth LOD issued on 4/30/24. Did not appeal. 365 days susp. Ends 5/8/25.		Substantiated	5/8/2024	5/8/2025
	6/6/2024	Stop Work	VIO-000803	A number of sites that have exceeded their time frames as stipulated in the Scope of Services. 8163				
	9/3/2024	EGLE	VIO-000813	Mandalay. Failure to update notification-the demolition end date, Failure to keep ACWM adequately wet, Failure to deposit ACWM as soon as practical at a Type II facility. Did not appeal.			9/11/2024	11/10/2024
Leadhead Construction								
				Missed a Final Grade Performance Milestone 3 (75%). Attained only 44.44%. Benchmark date was				
	11/17/2023	LOD - Non-Salesforce	VIO-000747	11/10/2023. Substantiated by deputy-11/30. Did not appeal-due on 12/8/23. Sixteen (16) properties that are		Substantiated		
				over 14 Days Since Open Hole-no Final Grade Request. As of 1/4/2024, none				
		LOD - Non-Salesforce	VIO-000756	of the previous properties were on the Salesforce report.	12/15/2023	UnSubstantiated		
	12/13/2023	Warning	VIO-000758	Missing Water Hydrant addresses in Salesforce-12 properties.				
	2/2/2024	Warning	VIO-000765	Request for affidavit due to altered Asbestos Waste Manifest submitted to Livegistics.				
	5/7/2024	LOD - Non-Salesforce	VIO-000802	Improper Disposal of Debris in Alleyway-6886 Parkwood. Work plan for adjacent emergency properties is	5/13/2024	UnSubstantiated		
	5/29/2024	Warning	VIO-000797	unacceptable. Reason are attached. If this issue occurs in the future it will incur a substantiated LOD.				
	6/12/2024	LOD - Non-Salesforce	VIO-000805	It was discovered that an emergency demo notification with an incorrect address was submitted to EGLE to demolish property. Correct was 14607 Northlawn not 14707. Failure to revise an EGLE Notification Start Date	6/19/2024	Substantiated		
	8/19/2024	LOD - Non-Salesforce	VIO-000811	for 9300 Wildemere. Did not appeal.		Substantiated		
	8/26/2024	LOD - Non-Salesforce	VIO-000812	Unapproved Backfill Material Source prior to backfill-1932 Devonshire. Appeal request was requested 4 days late.		Substantiated	9/3/2024	3/5/2025
				During backfill activities at 2011 Pasadena, LHC operated with an expired Miss Dig Ticket when a gas line was				
	9/16/2024	LOD - Non-Salesforce	VIO-000817	struck. In addition, LHC failed to immediately notify CDD of a gas leak at the site. Appealed.	9/16/2024			
Moss Company LLC								
	10/9/2023	Warning	VIO-000736	Over 14 Days since Open Hole approval-No Final Grade request-5 properties. Over 14 Days since Open				
	10/25/2023	LOD - Non-Salesforce	VIO-000742	Hole approval-No Final Grade request-1 property-17195 Arlington. Appealed. Substantiated by deputy-11/30/2023.Did not final appeal by 12/8/2023.	11/1/2023	Substantiated		
SC Environmental Services, LLC								
	11/21/2023	Other	VIO-000748	Wrongful Knock-19636 Albany.19652 Albany was the contracted property. Both properties are DLBA owned. Will not appeal.60 Day Suspension starts 11/30/2023 and ends 1/29/24		Substantiated	11/30/2023	1/29/2024
	4/29/2024	Warning	VIO-000793	Over 14 Days since Open Hole approval-No Final Grade request-17 properties. Company is currently working on a restructure of their team.				
				Wrongful Knock-654 E Savannah. 645 E Savannah was the contracted property. This is the third violation within a 365 day period. Director substantiated on July 18th. Received EGLE violation. Will review progress in October				
	5/31/2024	EGLE	VIO-000798	2024.		Substantiated	7/18/2024	7/18/2025

# Detroit Block X Block

Powered by the Construction & Demolition Department

We've launched Detroit Block by Block, an online archive of stories from Detroiters about some of the city's now-closed commercial buildings.

As our department aggressively addresses commercial blight for the overall safety and wellbeing of our residents, Block by Block will maintain memories of the past by highlighting the experiences of Detroiters and the buildings that played impactful roles in their lives.

Join the experience at https://detroitmi.gov/blockbyblock





@DetroitBlockByBlock

# **Sherrill Elementary School**

7300 Garden Detroit Block X Block

"If these spaces stay up in the state that they are, they attract an element that you don't want in the community." said RuShann Long, a longtime community activist who attended Sherrill Elementary in the early 1960s.

**CLICK HERE** or scan the QR code below to watch the full interview with RuShann Long as she reflects on fond memories of Sherrill and what led her to community activism as a longtime Detroiter.





# Glossary of Terms, Abbreviations, and Acronyms

- **3D** -- Detroit Demolition Department
- **COD -- City of Detroit**
- **CRIO -- Civil Rights, Inclusion & Opportunity Department**
- **DESC -- Detroit Employment Solutions Corporation**
- **DLBA -- Detroit Land Bank Authority**
- **DON -- Department of Neighborhoods**
- **EMG -- Emergency Demolition**
- **HRD** -- Housing and Revitalization Department
- **HSV** -- Health and Safety Violation
- LOD -- Letter of Discipline
- **NIB -- Neighborhood Improvement Bond**
- NIP -- Neighborhood Improvement Plan
- **OCFO -- Office of the Chief Financial Officer**
- **OCP** -- Office of Contracting and Procurement
- **ODFS -- Office of Departmental Financial Services**
- **ODM -- Ordered Demolition**







# DETROIT CONSTRUCTION and Demolition



J)



Construction & Demolition Department

### **CONTACT INFORMATION TO KNOW**



**Detroit Construction and Demolition Department** 

313-224-4737 demo-info@detroitmi.gov



### **Report abandoned and/or Dangerous Building**

313-224-3215 BSEDDemo@detroitmi.gov



### **Department of Neighborhoods**

Locate your District Manager at: www.detroitmi.gov/neighborhoods





#### NEW HIRE SPOTLIGHT

NAME: Heather Zeigler

JOB TITLE: GIS/ Data Analyst

#### INTERESTING FACT ABOUT YOURSELF:

I'm a hobby stained-glass artist, which means I create colorful glass art pieces for fun. I've also traveled to over 12 countries so far!





# **EMPLOYEE** SPOTLIGHT

Heather joins us as a GIS (Geographic Information Systems) and Data Analyst, where she will handle data analysis, management, and reporting for residential and commercial demolitions across the city.

We're excited to have you on board, Heather!