

HISTORIC DISTRICT COMMISSION NOTICE OF DENIAL

City of Detroit - Planning & Development Department 2 Woodward Avenue, Suite 808 Detroit, Michigan 48226

Notification Date: 05/23/25 Application Number: HDC2025-00114

APPLICANT & PROPERTY INFORMATION

NAME: Steven Flum

COMPANY NAME: Steven Flum Inc

ADDRESS: 3105 Holbrook

CITY: HAMTRAMCK

STATE: MI

ZIP: 48212

PROJECT ADDRESS: 2233 Park Avenue

HISTORIC DISTRICT: Park Avenue Local

SCOPE:

Replacement of wood French-style windows with aluminum-clad cottage-style windows on floors three through eight.

At the Regular Meeting that was held on 05/14/25 , the Detroit Historic District Commission ("DHDC") reviewed the above-referenced application. Pursuant to Section 5(1) and 9(1) of the Michigan Local Historic District Act, as amended, being MCL 399.205 (1), MCL 399.209 (9) and Sections 21-2-78 and 21-2-80 of the 2019 Detroit City Code; the DHDC hereby issues a Denial for the following work, effective on 05/23/25 , as it will be inappropriate according to the Secretary of Interior's Standards for Rehabilitation and the district's Elements of Design:

REASON FOR DENIAL: The circa 1920s photo of the building confirms the existing windows at the third through eight floors are similar to the historic windows; unique in design, proportion and operation, they are a distinctive character-defining feature of the building. Replacement windows that were installed likely occurred prior to designation of the local historic district and were designed to be compatible with the historic window opening pattern and French window function.
windows; unique in design, proportion and operation, they are a distinctive character-defining feature of the building. □ Replacement windows that were installed likely occurred prior to designation of the local historic district and were designed to be
☐ The submitted exterior visual analysis by staff shows that there is no clear understanding of what, if any, original historic material remains, beyond the brick mould. Before the Commission can consider any level of a window replacement project, a window survey documenting the details of each and every window that is suggested to be replaced must be completed.
□ The application proposes to install "cottage-style" windows from the third through eighth floors on three sides of the building. o The installation of this new window type would obliterate the distinctive, character-defining feature of the existing windows and would alter the features that characterize this building. o Additionally, the proposal is to remove or cover all remaining details, including the profiled wood brick mould. The brick mould is
one of the most visible components of a window opening due to its proximity to the masonry wall. Aluminum trim cannot be bent in such a way as to match the highly profiled wood brick mould. The flatter surface and sheen of aluminum is not compatible with a building erected in the early 20th century.

FAILURE TO MEET STANDARDS:

The Standards for Rehabilitation (codified in 36 CFR 67 for use in the Federal Historic Preservation Tax Incentives program) address the most prevalent treatment. "Rehabilitation" is defined as "the process of returning a property to a state of utility, through repair or alteration, which makes possible an efficient contemporary use while preserving those portions and features of the property which are significant to its historic, architectural, and cultural values."

As stated in the definition, the treatment "rehabilitation" assumes that at least some repair or alteration of the historic building will be needed in order to provide for an efficient contemporary use; however, these repairs and alterations must not damage or destroy materials, features or finishes that are important in defining the building's historic character.

The Standards are to be applied to specific rehabilitation projects in a reasonable manner, taking into consideration economic and technical feasibility.

Failure to meet standards: 2, 5, 6
Corresponding Standard numbered below:

- 1. A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment
- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.
- 4. Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.
- 5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a property shall be preserved.
- 6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
- 7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
- 8. Significant archeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

FAILURE TO MEET ELEMENTS OF DESIGN: Failure to meet Elements of Design: N/A

Corresponding design element numbered below:

Corresponding design element numbered below:	
1. Height.	12. Walls of continuity.
2. Proportion of building's front façades.	13. Relationship of significant landscape features and surface treatments.
3. Proportion of openings within the façade.	14. Relationship of open space to structures.
4. Rhythm of solids to voids in front façade.	15. Scale of façade and façade elements.
5. Rhythm of spacing of buildings on streets.	16. Directional expression of front elevations.
6. Rhythm of entrance and/or porch projections.	17. Rhythm of building setbacks.
7. Relationship of materials.	18. Relationship of lot coverages.
8. Relationship of textures.	19. Degree of complexity within the façade.
9. Relationship of colors.	20. Orientation, vistas, overviews.
10. Relationship of architectural details.	21. Symmetric or asymmetric appearance.
11. Relationship of roof shapes.	22. General environmental character.

If you have any questions regarding the above, please contact staff at 313-224-1762 or hdc@detroitmi.gov.

For the Commission:

Daniel Rieden

Senior Clerk to the Historic District Commission

APPEALS PROCESS

The application may be resubmitted for the Historic District Commission's review when suggested changes have been made that address the cited reasons for denial, if applicable. Please be advised that, in accordance with MCL 399. 211 and Section 21-2-81 of the 2019 Detroit City Code, an applicant aggrieved by a decision of the DHDC may file an appeal with the State Historic Preservation Review Board. Within sixty (60) days of your receipt of this notice, an appeal may be filed with:

PSR: 250523AD

Jon Stuckey, Michigan Department of Attorney General

2nd Floor, G. Mennen Williams Building

525 West Ottawa Street, P.O. Box 30754, Lansing, MI 48909

Phone: 517-335-0665 E-mail: stuckeyj@michigan.gov



HISTORIC DISTRICT COMMISSION APPLICATION FOR WORK APPROVAL

City of Detroit - Planning & Development Department 2 Woodward Avenue, Suite 808 Detroit, Michigan 48226

APPLICATION ID

HDC2025-00114

PR	OPERTY INFO	ORMATION						
ADD	RESS(ES): 2233	Park Avenue						
HIST	ORIC DISTRICT:	Park Avenue Lo	ocal					
sco	PE OF WORK: (C	Check ALL that appl	ly)					
x	Windows/ Doors	Walls/ Siding	Painting	Roof/Gutters/ Chimney	Po	orch/Deck/Balcony	Other	
	Demolition	Signage	New Building	Addition	(la	te Improvements ndscape, trees, fence tios, etc.)	es,	
Repl	BRIEF PROJECT DESCRIPTION: Replace windows in 112 openings on the south, east and north elevations, third floor through eighth floor.							
APPLICANT IDENTIFICATION								
	E OF APPLICAN							
	E OF APPLICAN			COMPANY NAME:	Steven F	lum Inc		
TYP	E OF APPLICAN	Γ: Architect/Engin		COMPANY NAME: CITY: HAMTRAMCK	Steven F	lum Inc	ZIP: 48212	
TYP NAM ADD	E OF APPLICANT	F: Architect/Engin		CITY: HAMTRAMCK			ZIP: 48212	
NAM ADD PHO	E OF APPLICANT IE: Steven Flum RESS: 3105 Holbr NE: +1 (313) 407-	F: Architect/Engin		CITY: HAMTRAMCK EMAIL: SFLUM@S		STATE: MI	ZIP: 48212	
NAM ADD PHO	E OF APPLICANT Steven Flum RESS: 3105 Holbr NE: +1 (313) 407-	T: Architect/Engin	HE FOLLOW	CITY: HAMTRAMCK EMAIL: SFLUM@S	BTEVENC	STATE: MI		
TYP NAM ADD PHO	E OF APPLICANT IE: Steven Flum RESS: 3105 Holbr NE: +1 (313) 407-2 CREE TO AN I understand that project and/or a I understand that responsibility to	T: Architect/Engine Took 1318 D AFFIRM T It the failure to up denied application to the review of the comply with any	HE FOLLOW pload all required con.	CITY: HAMTRAMCK EMAIL: SFLUM@S ING:	STEVENCE STE	STATE: MI FLUM.COM Extended review In does not waik	times for my	
NAM ADD PHO	E OF APPLICANT BE: Steven Flum RESS: 3105 Holbr NE: +1 (313) 407- CREE TO AN I understand that project and/or a I understand that responsibility to sign, etc.) or oth I hereby certify that	T: Architect/Engine Took 1318 D AFFIRM T It the failure to up denied application It the review of the comply with any er department application at the information of	HE FOLLOW bload all required con. his application by tother applicable copprovals prior to both this application is	CITY: HAMTRAMCK EMAIL: SFLUM@S ING: documentation may re the Historic District Coordinances including o	esult in exmmission btaining	STATE: MI FLUM.COM Extended review In does not wain appropriate per proposed work is	times for my ve my rmits (building,	
NAM ADD PHO	E OF APPLICANT IE: Steven Flum IRESS: 3105 Holbr INE: +1 (313) 407- I understand tha project and/or a I understand tha responsibility to sign, etc.) or oth I hereby certify the owner of record and	T: Architect/Engine Took 1318 D AFFIRM T It the failure to up denied application It the review of the comply with any er department application at the information of	HE FOLLOW bload all required con. his application by tother applicable copprovals prior to both this application is	CITY: HAMTRAMCK EMAIL: SFLUM@S ING: documentation may re the Historic District Coordinances including of the work. true and correct. I certify	esult in exmmission btaining	STATE: MI FLUM.COM Extended review In does not wain appropriate per proposed work is	times for my ve my rmits (building,	
NAM ADD PHO	E OF APPLICANT BE: Steven Flum RESS: 3105 Holbr NE: +1 (313) 407- CREE TO AN I understand that project and/or a I understand that responsibility to sign, etc.) or oth I hereby certify that	T: Architect/Engine Took 1318 D AFFIRM T It the failure to up denied application It the review of the comply with any er department application at the information of	HE FOLLOW bload all required con. his application by tother applicable copprovals prior to both this application is	CITY: HAMTRAMCK EMAIL: SFLUM@S ING: documentation may re the Historic District Coordinances including of the work. true and correct. I certify	esult in examples of the state	STATE: MI FLUM.COM Extended review In does not wain appropriate per proposed work is	times for my ve my rmits (building,	

NOTE: Based on the scope of work, additional documentation may be required. See www/detroitmi.gov/hdc

for scope-specific requirements.

PROJECT DETAILS - TELL US ABOUT YOUR PROJECT

Instructions: Add project details using the text box in each section. If your details exceed the space provided, attach the details via the attachment icon for that section.

ePLANS PERMIT NUMBER:

(only applicable if you've already applied for permits through ePLANS)

N/A

GENERAL

1. DESCRIPTION OF EXISTING CONDITION

Please tell us about the current appearance and conditions of the areas you want to change. You may use a few sentences or attach a separate prepared document on the right. (For example, "existing roof on my garage is covered in gray asphalt shingles in poor condition.")

Description of Existing Condition

The existing wood windows are deteriorating, lacking weatherization and unsafe. The window consists of French windows (with no center post) and a fixed transom above.

No original window sashes are present. Approximately 50% of the original wood head, jambs, sills and brickmould are present but are cracked and deteriorated. The window sashes were replaced in 2006, poor workmanship and usi



2. PHOTOGRAPHS

Help us understand your project. Please attach photographs of all areas where work is proposed.



3. DESCRIPTION OF PROJECT

In this box, tell us about what you want to do at the areas described above in box #1. (For example, Install new asphalt shingle roofing at garage.)

Description of Project

Replacement of the windows with a Pella Reserve aluminum clad wood cottage style single hung window. The new window provides a superior performance with air and water infiltration, structural integrity and is a safer solution. The windows will have insulated dual pane glass. The aluminum window sash, frame and trim will be black.

Install 112 single hung windows. New windows will be located on the second thru eighth floor, on the north, east and



4. DETAILED SCOPE OF WORK

In this box, please describe all steps necessary to complete the work described in box #3. (For example, "remove existing shingles, replace wood deck as necessary, replace wood eaves, install roof vents, replace rotted fascia boards, paint, clean worksite.")

Detail Scope of Work

- 1. Remove existing windows sashes, jambs, head and sill
- 2. Install new wood blocking at the jamb, head and sill to the masonry
- 3. Install new window and trim
- 4. Install sealant between exterior aluminum trim and masonry
- 5. Install new interior wood window sill, caulk and paint


5. BROCHURES/CUT SHEETS


Please provide information on the products or materials you are proposing to install. For example, a brochure on the brand and color of the shingles proposed.





ADDITIONAL DETAILS

6. WINDOWS/DOORS Detailed photographs of window(s) and/or door(s) proposed for replacement showing the condition of the interior and exterior of the window(s) and/or door(s)	











North East Corner Park Ave. and W. Montcalm St.



South view of building at alley



Exterior close up view of existing windows




Interior view of existing window closed position



Interior view of existing window open position



Window frame wood sill and exterior stone will



Close up view of window frame sill



Window frame head and transom above



View of existing widow jamb and sash




View of existing window jamb and sash



View of existing window sash

Docusign Envelope ID: 32B5BBD7-11E6-40B7-9D6F-C334B7E3EC4D



SOUTH ELEVATION

EAST AND NORTH ELEVATION


2233 Park Avenue

Iodent Building

Park Ave. Historic District 4/15/2025


Scope of Work


- Remove windows in 112 openings on floors three thru eight, on the north, east and south facades.
- Install new single hung windows
- Repair or replace wood bucks at the sill, jamb and head.
- Insulated and caulk perimeter.
- Install aluminum trim to cover perimeter wood buck.
- Replace wood sill with marble sill.




Viewed From Exterior


Pella Reserve, Traditional
Cottage Style Single Hung Window
Exterior aluminum clad black
Interior painted white










PRELIMINARY DRAWING FOR IODENT BUILDING RENOVATION DETROIT, MICHIGAN



PRELIMINARY DRAWINGS
NOT FOR CONSTRUCTION







TM03.17 SEALANT

3 SILL

FC01.06 SCREW

TM03.16 SEALANT

BC03.05

WOOD BLOCKING

SEE ARCHITECTURAL DRAWINGS FOR

INTERIOR FINISH REQUIREMENTS.

CONFIRM EXISTING

CONSTRUCTION

DETAIL KEYNOTES

AC: ATTACHMENT COMPONENTS

AC08.02 VINYL RECEPTOR GASKET. INSTALL INTO ACCESSORY GROOVE AS NOTED PRIOR TO INSTALLING UNIT. NOTCH BARB TO CONTINUE BULB GASKET OVER MULLION ENDS.

BC: BUILDING COMPONENTS (BY OTHERS)

BC03.05 CONTINUOUS WOOD BLOCKING. SEAL AND ANCHOR SECURELY TO WALL CONSTRUCTION.

FC: FASTENING COMPONENTS

SCREWS OR SIMILAR SUBSTRATE COMPATIBLE ANCHOR

RR: RENOVATION AND REPLACEMENT ACCESSORIES

RR05.01 ALUMINUM T-SUBFRAME SYSTEM. HEAD. REFER TO PELLA SUBFRAME INSTALLATION INSTRUCTIONS ASSEMBLY AND INSTALLATION REQUIREMENTS

RR06.01 ALUMINUM T-SUBFRAME SYSTEM JAMB. REFER TO PELLA SUBFRAME INSTALLATION INSTRUCTIONS FOR THE PROPERTY OF THE PROPERT

FC01.06 ANCHOR UNIT TO OPENING WITHIN 4" OF ENDS AND 16" ON CENTER (MAXIMUM) WITH #8 X 3" WOOD

ASSEMBLY AND INSTALLATION REQUIREMENTS

RR07.01 ALUMINUM T-SUBFRAME SYSTEM SILL. REFER TO PELLA SUBFRAME INSTALLATION INSTRUCTIONS FOR ASSEMBLY AND INSTALLATION REQUIREMENTS

RR08.01 SUBFRAME CLIP. SEE TYPICAL DETAIL CC1. ANCHOR TO OPENING WITH:
TREATED WOOD OR EXISTING WOOD WINDOW: #8 x 1-1/2" STAINLESS STEEL PAN HEAD SCREW.
CONCRETE, BLOCK/BRICK: 3/16" x 1-3/4" STAINLESS STEEL HEX WASHER HEAD MASONRY SCREW.
STEEL STUD: #8 x 1-1/2" STAINLESS STEEL SELF-DRILLING PAN HEAD SCREW.

RR08.02 *CAUTION!! SHIM CLIP AS REQUIRED. TO MAINTAIN 5/8" DIM. BETWEEN SUBFRAME AND OPENING.
RR10.01 WINDOW CLIP. SEE TYPICAL DETAIL CC1. USE #8 X 5/8" STAINLESS STEEL SCREW. AVOID INTERFERENCE

TM: THERMAL AND MOISTURE PROTECTION

TM03.16 CONTINUOUS SEALANT. ENSURE FIELD APPLIED PERIMETER SEALANT CONNECTS WITH SEALANT ENDS TM03.17 CONTINUOUS SEALANT. PROVIDE WEEPS AS REQUIRED.
TM03.18 CONTINUOUS SEALANT.

TM04.01 APPLY CONTINUOUS 1" BEAD OF LOW EXPANSION, POLYURETHANE, INSULATING FOAM SEALANT MEET THE REQUIREMENTS OF AAMA812 - DO NOT USE HIGH PRESSURE OR LATEX FOAMS TO CREATE FULL

FOR OR W

| KeV: DATE: REV: DATE: | Colored |

DING RENOVATION

DENT BUILDING R

ORIGINAL: 3-17-2025

DRAWN BY: BMB

CHECKED BY: RCH

Project No.:

223688.01

01 of 01



PELLA® RESERVE™ - TRADITIONAL Wood Double-Hung Window

3.78 ★★★☆ 357 Reviews

Create the traditional look your historic renovation, new construction or replacement project requires with a traditional wood or aluminum-clad wood double-hung window. This Pella Reserve window proves our uncompromised attention to detail with historic putty profiles, through-stile construction, innovative grilles and authentic spoon-lock hardware.

- Winner of 2019 Most Innovative Window from Window and Door Magazine with optional Integrated Rolscreen® retractable screen that appears when you open the window and rolls away when you close it.
- Pella Reserve products have been reviewed and approved on a case-by-case basis by the National Park Service for use on projects with historic tax credits.
- Innovative sash lugs can be added to the exterior to create the authentic look, while maintaining modern tilting functionality for easy cleaning.



Pella® Reserve™ Traditional Hung Window

Size and Performance Data

Air/Water/Structural Performance ₁	
Meets or Exceeds AAMA/WDMA Ratings	H-CW30 - CW50 Hallmark Certified
Air Infiltration (cfm/ft² of frame @ 1.57 psf wind pressure) ₂	0.11
Water Resistance	4.6 – 7.5 psf
Design Pressure	30-50 psf

Other Performance Criteria	
Forced Entry Resistance Level (Minimum Security Grade) 3	10
Operating Force (lb) Initiate Motion / Maintain Motion (of Hallmark tested size and glazing) 4	40/45

Sound Transmission Class / Outdoor-Indoor Transmission Class

		Glazing System						
Product	Frame Size Tested 5	Overall Glazing Thickness	Exterior Glass Thickness	Interior Glass Thickness	Third Pane Thickness	STC Rating	OITC Rating	
Clad Double-Hung	WITHOUT GRILLES							
Window	45" x 65"	11/16"	2.5mm	2.5mm	-	28	24	
	45" x 65"	11/16"	5mm	3mm	_	31	27	
Wood Double-Hung	WITHOUT GRIL	LES						
Window	45" x 65"	11/16"	2.5mm	2.5mm	_	26	22	
	45" x 65"	11/16"	3mm	3mm	-	29	24	

^{(—) =} Not Available

⁽¹⁾ Maximum performance for single unit when glazed with the appropriate glass thickness. See Design Data pages in this section for specific product performance class and grade values.

⁽²⁾ Published performance data for air infiltration is determined by testing a minimum of four (4) products of NFRC model size. Testing is conducted in accordance with ASTM E283. Air infiltration ratings for products will differ by size. The performance data does not apply to combination assemblies unless noted. Actual product performance may vary for a number of reasons including installation and product care.

⁽³⁾ The higher the level, the greater the product's ability to resist forced entry.

⁽⁴⁾ Glazing configurations may result in higher operational forces

⁽⁵⁾ ASTM E 1425 defines standard sizes for acoustical testing. Ratings achieved at that size are representative of all sizes of the same configuration.



Pella® Reserve™ Traditional Hung Window

Features and Options

Standard	Options / Upgrades
Glazing	
Glazing Type	
Dual-Pane Insulating Glass	_
Insulated Glass Options/Low-E Type	es
	SunDefense [™] Low-E
	SunDefense+ Low-E
Advised 5	AdvancedComfort Low-E
Advanced Low-E	NaturalSun Low-E
	NaturalSun+ Low-E
	Clear (no Low-E coating)
Additional Glass Options	
	Tempered Glass
A manada di Clara	Obscure Glass ₁
Annealed Glass	Low-E Tinted Glass (Bronze, Gray and Green)
	Non-Impact Laminated Dual-Pane Insulating Glass
Gas Fill/High Altitude	
Argon	High altitude
Exterior	
Exterior Sash Profile	
Ogee	Putty Glaze
Exterior Finish	
EnduraClad® aluminum-clad exterior	EnduraClad Plus protective finish, Factory Primed Pine wood exterior, Unfinished Mahogany wood exterior
Cladding Colors	
Standard colors 1	Feature Colors, Custom Colors₁
Interior	
	Factory primed
Unfinished wood	Factory prefinished paint₁
	Factory prefinished stain₁
Wood Types	
Pine	Mahogany, Douglas Fir
Hardware	
Hardware Types	
	Simulated lock
Sash lifts, Cam-action lock	Air conditioner lock
	Historical spoon-style lock (surface mounted)
Hardware Finishes	
Champagne, White, Brown or Matte Black	Satin Brass, Satin Nickel, Oil-Rubbed Bronze, Distressed Bronze, Distressed Nickel 4
Tilt-Wash Cleaning	
Tilt to interior on both sashes	_
Grilles	
Integral Light Technology® Grilles	
_	Traditional, Prairie, Top Row, Cross, New England, Victorian, Diamond, Custom
Grilles-Between-the-Glass	
	Traditional, Prairie, Top Row ₁ , Cross, Custom-Equally Divided
Screens	
-	Integrated Rolscreen® - retractable screen, InView™ screens, in standard roll-form or premium extruded aluminum frame

(-) = Not Available

- (1) Contact your local Pella sales representative for current designs and color options.
- (2) Only available for Pella Reserve products with triple glazing. Not available with high altitude glazing.
- (3) Available with Low-E argon-insulated glass only.
- $(4) \ {\tt Antique\ Brass}, \ {\tt Distressed\ Nickel}, \ {\tt Distressed\ Bronze\ finishes\ available\ for\ Historical\ spoon-style\ lock\ only}.$

Pella® Reserve™ Traditional Hung Window

Size Tables - Cottage Sash

VENT UNITS

			(552) (533)	(654) (635)	(756) (737)	(857) (838)	(959) (940)	(1 060) (1 041)	(1 162) (1 143)	(1 238) (1 219)
	Op	ening	1' 93/4"	2' 13/4"	2' 53/4"	2' 93/4"	3' 13/4"	3' 53/4"	3' 93/4"	4' 03/4"
		Frame	1' 9"	2' 1"	2' 5"	2' 9"	3' 1"	3' 5"	3' 9"	4' 0"
(1 060) (1 041)	3' 53/4"	3'5"	VG2141	VG2541	VG2941	VG3341	VG3741	VG4141	VG4541	VG4841
(1 213) (1 194)	3' 113/4"	3'11"	VG2147	VG2547	VG2947	VG3347	VG3747	VG4147	VG4547	VG4847
(1 365) (1 346)	4' 53/4"	4'5"	VG2153	VG2553	VG2953	VG3353	VG3753	VG4153	VG4553	VG4853
(1 467) (1 448)	4' 93/4"	4' 9"	VG2157	VG2557	VG2957	VG3357	VG3757	VG4157	VG4557	VG4857
(1 518) (1 499)	4' 113/4"	4'11"	VG2159	VG2559	VG2959	VG3359	VG3759	VG4159	VG4559	VG4859
(1 670) (1 651)	5' 53/4"	5' 5"	VG2165	VG2565	VG2965	VG3365	VG3765	VG4165	VG4565	VG4865
(1 822) (1 803)	5' 113/4"	5'11"	VG2171	VG2571	VG2971	VG3371	VG3771 E	VG4171	VG4571	VG4871
(1 822) (1 803)	5' 113/4"	6'5"	VG2177	VG2577	VG297	VG3377	VG3777	VG4177	VG457	VG4877

Egress Notes:

Check all applicable local codes for emergency egress requirements.

- E = Window meets minimum clear opening of 24" height, 20" width, and 5.7 ft².
- E1 = Window meets minimum clear opening of 24" height, 20" width, and 5.0 ft².

See Design Data pages in this section for clear opening dimensions.

Clear opening (egress) information does not take into consideration the addition of a Rolscreen (or any other accessory) to the product. Consult your local building code to ensure products with Rolscreens meet egress requirements.

Opening Dimensions

Clad Exterior Units:

Dimensions shown in standard size tables are rough opening dimensions.

Wood Exterior Units:

Use frame dimension plus dimensions below. This dimension includes the use of standard 1-1/8" wood subsill.

Frame	Roi	ugh	Masonry		
Brickmould	Width	Height	Width	Height	
STD	+ 3/4"	+1-7/8"	+ 3-1/8"	+ 3-1/8"	
3-1/2"	+ 3/4"	+1-7/8"	+ 6-3/8"	+ 4-3/4"	

For clad and wood units with impact-resistant glass, see the product installation instructions or refer to local building code requirements.

Not to scale.

Traditional grille patterns shown. Refer to Grille Types section for additional patterns and profiles.

Cottage units have unequal sash split. Sash glass ratio is 40% upper sash to 60% Lower sash.

Vent variable units have unequal sash split. Sash glass ratio is determined by checkrail heights. See unit sections for dimension requirements.



North East Corner Park Ave. and W. Montcalm St.



South view of building at alley



Exterior close up view of existing windows




Interior view of existing window closed position



Interior view of existing window open position



Window frame wood sill and exterior stone will



Close up view of window frame sill



Window frame head and transom above



View of existing widow jamb and sash



View of existing window jamb and sash



View of existing window sash