STAFF REPORT: 5/12/2021 MEETING P APPLICATION NUMBER: #21-7178 ADDRESS: 2061 LONGFELLOW HISTORIC DISTRICT: BOSTON EDISON APPLICANT: WILLIAM WROBLEWSKI/ CANDY CONSTRUCTION PROPERTY OWNER: ASM REALTY HOLDINGS LLC DATE OF PROVISIONALLY COMPLETE APPLICATION: 04/19/2021 DATE OF STAFF SITE VISIT: 4/27/2021

### SCOPE: CONSTRUCT NEW GARAGE AND DRIVEWAY

### **EXISTING CONDITIONS**

Built in 1921, this 2 1/2-story single-family colonial faces northwest. The moderate-pitched, side-gabled roof is punctured by 3 arched-topped dormers setting the division of the front elevation fenestration in threes: three sets of double-hung windows each with stone sills and shutters on the second floor, over the main door flanked on each side with two sets of double hung windows on either side. The main floor windows feature keystone lintels with masonry sills. The centerpiece of this façade is the curvilinear porch roof topped with an ornate metal railing and supported by a pair of classical columns on either side of the front door. The house is composed mostly of dark red brick that wraps around all elevation of the home. The house sits elevated on the property where a central walkway and steps leads to the front porch. A concrete driveway was recently removed and the remaining path leads to the backyard site of the proposed garage location, where trenches await the first pour of footings on the property's southeast corner. Landscape is mostly lawn, barren soil, and two large evergreens on either side of the front porch.



Site Photo 1, by Staff April 27, 2021: (Northwest) front side

Site Photo 2 by Staff April 27, 2021: Garage site (Southeast) side/rear.

The owner purchased the property in July 2017. As staff currently does not have access to some of the previous paper applications and approval letters, the Detroit Property Index is the only available information on the property. This property has no previous HDC approved work. However, an outstanding violation is effect for work done without approval that includes the following scope: foundation work, front porch, windows, soffit, gutter, doors and new foundation for proposed garage. The City's BSEED is also monitoring this case.






2061 Longfellow Designation Photo, 1974



Aerial, May 2020

### PROPOSAL

The applicant provided an incomplete application initially for a broader range of work that included windows and a general rehab of the house. However, a complete application was received for the proposed new construction of a garage. Staff received a narrative, site photos, construction documents and material details for the following proposed work: construct a 18' x 18' two-car garage, with a 10" x 42" deep concrete trench footing foundation, 4" concrete slab set back 2 feet 6 inches from the side (east) property line and no setback from the rear (south) property line. This proposal also includes a 9 feet 7 inch wide driveway from the front property line to the rear of the house, flairing out to 18' at approximately 18' from the front of the proposed garage. See also attached documents provided by the applicant.



Site plan and elevations, by Applicant

### STAFF OBSERVATIONS AND RESEARCH

- At the time of this report, Staff has not yet received a response to additional information requested from the applicant with regards to the following:
  - Color of garage shingles, Hardie cladding, soffit/trim, side and main garage doors.
  - Spec sheets for the windows, doors, with material make-up, dimensions, color and finish.
- Staff visited the site on April 27, 2021. Staff photographed the property from the public right-of-way and observed the front (north) and rear (south) sides of the house. (See staff photos enclosed)
- Staff observed that trenchwork for foundation work has already started.
- Staff found no record of a previous garage at this property.
- Staff observes that the proposed hipped pyramid roof shape is different than the house's side-gabled form, but the pitch for the roof at 12:5 appears close to the moderate pitch of the house, and there are many examples of hipped roof garages accompanying variously gabled houses.
- Because of this location and the garage being less than the maximum height allowed (15 ft) at approximately 11 ½ feet, it would not be hardly visible to the public.
- Staff received confirmation that all poured concrete surfaces shall be 4" thick with a 4" compacted base.
- It is staff's opinion with Hardie cladding, the materials, and size are appropriate for the existing context of the Boston Edison Historic District.

### **ISSUES**

• Details regarding color, material, and finish of the garage have not been presented.

### RECOMMENDATION

Section 21-2-78, Determination of Historic District Commission

HDC staff recommends the Commission issue a Certificate of Appropriateness for the below work items because they meet the Secretary of the Interior's Standards for Rehabilitation and conform to the Elements of Design for the Boston Edison Historic District:

- Construct a new 18' x 18' garage, with a 4" concrete pad
- Construct a new cement driveway from front property line to garage.

However, staff recommends the Commission issue a COA with the following conditions:

- The applicant will provide manufacturer specifications on the following for HDC staff review and approval prior to an issued permit:
  - Color of garage shingles, Hardie cladding, soffit/trim, side and main garage doors.
  - Spec sheets for the windows, doors, with material make-up, dimensions, color and finish.

















### HISTORIC DISTRICT COMMISSION PROJECT REVIEW REQUEST

3-21-21

DATE: 2-14-21

Based on the scope of work, additional i documentation may be required.

See www.detroitmi.gov/hdc for scope-specific requirements.

CITY OF DETROIT PLANNING & DEVELOPMENT DEPARTMENT 2 WOODWARD AVENUE, ROOM 808, DETROIT, MI 48226

P	RC	)P	Ξ	R	Ì	Y	7		ſ	2		P.	L	Ţ	ľ	ľ		J	Z	
					-					-										ľ

ADDRESS: 2061 LONG FELLOW AKA:

HISTORIC DISTRICT:

APPLICANT IDENTIF	ICATION		
Property Owner/ Homeowner	Contractor	Tenant or Business Occupant	Architect/ Engineer/ Consultant
NAME: WILLIAM KA	20BLEKKLI COM	IPANY NAME: CANDY	CONSTRUCTION.
ADDRESS: 11415 B	POOKFIELDCITY:	LIVONA. STATE: N	15 ZIP: 48150
PHONE:	MOBILE: 313-4	10-0680 EMAIL: B	GHAIL COM.

### **PROJECT REVIEW REQUEST CHECKLIST**

Please attach the following documentation to your request:

**Detailed photographs** of location of proposed work (photographs to show existing condition(s), design, color, & material)

**Description of existing conditions** (including materials and design)

**Description of project** (if replacing any existing material(s), include an explanation as to why replacement--rather than repair--of existing and/or construction of new is required)



Detailed scope of work (formatted as bulleted list)

Brochure/cut sheets for proposed replacement material(s) and/or product(s), as applicable

Upon receipt of this documentation, staff will review and inform you of the next steps toward obtaining your building permit from the Buildings, Safety Engineering and Environmental Department (BSEED) to perform the work.

### SUBMIT COMPLETED REQUESTS TO HDC@DETROITMI.GOV

### **CANDY CONSTRUCTION L.L.C.**

### 11415 BROOKFIELD LIVONIA, MICHIGAN 48150

### 313-410-0680

April 18, 2021

Historic Preservation Staff Detroit Planning and Development Dept. Coleman A. Young Municipal Center. 2 Woodward Avenue , Suite 808 Detroit , Michigan 48226 Phone : 313-224-4803

Atten: Garrick B. Landsberg Director Historic Preservation Phone : 313-224-3521 E-mail : <u>landsbergg@detroitmi.gov</u>

Atten: Daniel P. Rieden, PLA Lead Landscape Architect Phone : 313-224-1762 E-Mail : <u>hdc@detroitmi.gov</u>

Re: 2061 Longfellow Detroit , Michigan 48206 U.S.A.

Candy Construction inspected the historic property at 2061 Longfellow Detroit , Michigan 48206 and presenting the following report.

EXISTING CONDITIONS : The house needs a lot of work. It's the most deteriorated house on the street. The exterior brick and stonework is in good condition. The exterior wood trim , shutters , and decorative porch cover (portico) need repair and paint . The front porch portico needs new support posts. The roof needs replacement. New gutters and downspouts are needed. The porch with excavated area below needs to be rebuilt. Windows need repair and some glass replacement. Dormers on front roof need repair. House needs driveway and concrete to the rear entry door. House has no driveway or walkways. The porch at one rear door needs replacement. A second rear first floor dining room door needs a new deck. Three of the four rear doors are gone and need replacement.

DESCRIPTION OF PROJECT : Remove and replace existing shingles. The shingles are damaged beyond repair and leaking. Replace missing gutters and downspouts. Repair exterior wood trim and repaint . Repair existing windows and replace glass as needed. Repair front porch and excavated area below and provide new supported concrete cap. Repair and paint front porch portico and provide new approved structural support posts. Provide new driveway and concrete to rear entry doors. Replace 3 missing rear doors with approved doors. Make stationary , repair and paint existing second floor door. Provide new garage with matching shingles and approved James Hardi smooth siding and new approved garage door

and service door. Repair interior drywall throughout, renovate cabinetry, replace interior trim and light fixtures.

### DETAILED SCOPE OF WORK :

Existing shingles removed and disposed of properly. Provide new matching shingles. Replace damaged roof sheeting as needed.

Repair deteriorated roof dormers .

Repair and paint exterior wood trim.

Remove and replace front porch and rebuild excavated wine cellar area under front porch and replace with properly supported concrete cap and steps to code.

Repair front porch roof portico and provide proper support columns.

Replace missing exterior entry doors

Make stationary existing second floor entry door.

Reuse existing front window shutters. (repair and paint).

Repair existing windows and replace glass as needed throughout.

Provide new galvanized steel gutters and downspouts.

Provide new 18' x 18' 2 car garage with new matching roof, approved garage door and approved James Hardie siding with 8" x 42" concrete trench footing foundation.

Rebuild rear porch at dining room on existing footing and provide new steps


Provide new deck at right side rear entry door.

Provide new concrete driveway and walkways.

Thank You for your time.


William T. Wroblewski State of Michigan Builders License Number 2101160504

5/TE PLAN 96465: 1=201-0" LENCIEST ALLET) 50'-0" 9 18'-0" • NEW • 2-6-29-6" GATAGE-18-0" PROVIDE NEW GIAPAGE NEW: LONC PRIVE 13610 REBUILTE COLLAPSED NEW STAIPS) BRICK PORCH. Papecon NEWCON 8-0° 72-1 5-07 9-7° EXIT. HOUSE EXIGT 2/2 EXAMPT HOUSE STORY HOUSE 8.5 2 onafellow NEH R 34-8" PORCH E 01 REPUILD COLLAPSED FRONT BROTH NEW NEW CONC WALK 50-0-EXAMPT 6 CONC WALK 6420 206 LONGFELION DEPENT REPARED BY RODERTY OWNER CANDY CONSTRUCTION ASM REALTY HOLDINGS LL INIMANA WEDBLENDER 26636 MICHIGAN. SHITE 339 11415 BROOKFIELD DEARBOPH ME 48124 LIVONIA MIE +\$150 313-410-0680 DATE: 3-17-2021




RECONSTRUCTION OF EXISTING FRONT PORCH / PLAN VIEW


SCALE 1/ 4'' =1'-0''




RECONSTRUCTION OF NEW FRONT PORCH SIDE ELEVATION



SCALE | / 4'' = |'-0''



### FRONT PORCH FOUNDATION PLAN ( REBUILT )



SCALE |/ 4'' =|'-0''

8" X 16" CONCRETE BLOCK PORCH FOUNDATION , EXCAVATED AREA USED AS WINE CELLAR

, REBUILD FRONT STAIRS - TOP OF NEW SLAB "-10" , EXIST. GRADE


SCALE |/ 4'' =|'-0''




4  $\langle \rangle$ 481.  $\leq$ \_  $\mathbb{N}$  $\frac{1}{1}$ XX TIONS RB(  $\sum_{i=1}^{n}$ SUNG 777 $\overline{}$ ATION  $\mathcal{L}$ Sulte  $\underline{t}$ AVE  $\checkmark$ D 11 1 ASM  $\left\langle \right\rangle$  $H_{C_{I}}$ VIEW MC  $\mathbb{A}$ 636  $\frac{1}{2}$ 20


PREPARED BY: CANDY CONSTRUCTION WILLIAM WROBLEWSKI 11415 BROOKFIELD LIVONIA , MICHIGAN 48150

313-410-0680





### NEW GARAGE PLAN VIEW SCALE 1/4"=1'-0"





### NEW GARAGE FOUNDATION PLAN SCALE 1/4"=1'-0"








PREPARED BY:

CANDY CONSTRUCTION



BUILDING SECTION

SCALE ; 1/2'' = 1'-0''






























Cookie Preterences


Accept Cookies

9:43 AM

Ne use cookies to operate our website, enhance site navigation, analyze site usage, and assist in our marketing efforts. By clicking "Accept Cookies," you agree to this use. For more information please visit our Cookie Notice.












The siding youll see below is available on special order in Dream Collection<sup>TM</sup> products and


### Fined for Fantony.


# 

# 











# home's exterior. It's primed. It's ready for field painting. It's a durable, high-performance canvas.

## AVAILABLE SIZES

### 






# MUDTHS: 9.25" 6.25" EXPOSURES: 8" 5"


5.25" 7.25" 4" 6"

8.25"

Request a Quote >

Request a Sample >







C Type here to search

results



# https://www.amazon.com/EA0808ANFSATUTU-Endura-Aluminum-Load-Bearing-Non-Tapered-Capital/dp/B000KKM000/ref...

Column, Round Shaft (Load-Bearing 21,000 lbs); & Base Brande Afrece Sizz Remained Round Related Height 6 Round x 9 Total Height 8<sup>th</sup> Round x 8<sup>th</sup> Total Height Egad Eleanng Application Encaloss Mante s//www.amazon.com/o?node=10158976011&pd\_rd\_w=1uXSV&pf\_rd\_p=64178df4-e708-422d-b882-fde00dad3d46&pf\_rd\_r=ZCT83PMCTVD592BT839J&pd\_rd\_r=878ba688-15a4-46b1-be8f-0a371b793acb&pd\_rd\_wg=oZwRt 

# AFCO EA0808ANFSATUTU 8' x 8' Endura-Aluminum Non-Tapered, Fluted, Gloss White Finish w/ Capital

annels - nnezon wy are publice

## 

\$199.48 & FREE Returns FREE delivery O select delivery

To

## Usually ships 2 months.

Quy: 1 w




Secure transec Ships from Amazon.c Amazon Sold by

# prime

Enjoy fast, FREE exclusive deals ar winning movies 8 shows with Prime Try Prime and star today with Fact FA


A D & 40




GUTTETS

# 

# K Style Galvanized Steel Gutters









Guiters

Are jui a Contractor? Get exclusive priving à discutto






### 









### 

