# **CLARKSTON WINDOW & DOOR**



Quotation: 248-338-6781 Phone:

1-248-338-8167 Fax:

SQGXG000600\_1 Quote Name: Lewand Bldg. Seward Ave full replacement Quote #: User Name: Jeff Weaver Cutoff Order Day - Thursday 12 P.M. CST

151 CESAR E. CHAVEZ AVE.


PONTIAC,MI 48342

**Quoted For:** CLARKSTON WINDOW & DOOR CLARKSTON WINDOW & DOOR Ship-To:

	151 CESAR E. CHAVEZ AVE. PONTIAC, MI 48342 US						
Prepared By:	Jeff Weaver jeff@clarkstonwindow.com		Created On: Available To:		9/26/2021 10/26/2021		
Quote Information							
Total Value:		\$15,954.67	Status:		Open		
Header:							
Terms:							
Pricing:							
All terms and conditions of this quote, including units, quantities, and accessories, are verified and accepted by the undersigned for purchase.							
Accepted By		Date		Po#			

Printed On: 9/29/2021 9:12 AM Page **1** of **9** 

Line	Label	Quantity	UOM	Part Number	Unit	Extended
1	FF front bay	2	EA	Quaker Unit	\$737.66	\$1,475.31



\*\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 28 1/4 X 71 1/4 Outer Perimeter: 31 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. CasingBrckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 28 1/4 X 71 1/4, NOT Egress,


NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Overall Rating: DP-50





Series: Brighton

**Exact Size:** 34 1/4 X 71 1/4 **Outer Perimeter:** 37 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass: EnergyNorth (180+4th Surface), Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc:No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. Casing Brckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 1/4 X 71 1/4, Meets Egress

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43

Rating: R-50


Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Bottom Glass: Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB, Strength: Annealed Glass

Overall Rating: DP-50

3 FF front left 1 EA Quaker Unit \$781.13 \$781.13



Series: Brighton

Exact Size: 34 1/4 X 71 1/4 Outer Perimeter: 37 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass: EnergyNorth (180+4th Surface), Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Printed On: 9/29/2021 9:12 AM Page **2** of **9** 

Install Acc:No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. CasingBrckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext. SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 1/4 X 71 1/4, Meets Egress

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Overall Rating: DP-50

4 FF left front 1 EA Quaker Unit \$781.13 \$781.13



\*\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 34 1/4 X 71 1/4 Outer Perimeter: 37 1/4 X 73 3/8

Color:Black, Paint Type: 2604, Interior Finish: Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. Casing Brckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 1/4 X 71 1/4, Meets Egress

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

**Overall Rating: DP-50** 

5 FF left bay 2 EA Quaker Unit \$712.15 \$1,424.29



\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 24 3/4 X 71 1/4 Outer Perimeter: 27 3/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass: EnergyNorth (180+4th Surface), Argon Filled,

Hardware:Gold,Sash:Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. CasingBrckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 24 3/4 X 71 1/4, NOT Egress,

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 

Rating: R-50


Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

Top Glass:Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,Strength:Annealed Glass
Bottom Glass:Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,Strength:Annealed Glass

Overall Rating: DP-50

Printed On: 9/29/2021 9:12 AM Page **3** of **9** 

6 FF left bay 1 EA Quaker Unit \$744.76 \$744.76



Series: Brighton

Exact Size: 29 1/4 X 71 1/4 Outer Perimeter: 32 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass: EnergyNorth (180+4th Surface), Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior: Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc:No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. Casing Brckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 29 1/4 X 71 1/4, NOT Egress,

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Overall Rating: DP-50

7 FF rear left 1 EA Quaker Unit \$851.95 \$851.95



\*\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 42 1/4 X 71 1/4 Outer Perimeter: 45 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. Casing Brckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 42 1/4 X 71 1/4, Meets Egress

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43


Rating: DP-30 \*

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Overall Rating: DP-30

8 FF rear entrance 1 EA Quaker Unit \$603.22 \$603.22



Series: Brighton

Exact Size: 24 3/8 X 47 1/4 Outer Perimeter: 27 3/8 X 49 3/8

Color:Black, Paint Type: 2604, Interior Finish: Natural Finish, Glass: Energy North (180+4th Surface), Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior: Yes,

Printed On: 9/29/2021 9:12 AM Page **4** of **9** 

## \*\* Viewed From Exterior \*\*

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc:No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. CasingBrckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 24 3/8 X 47 1/4, NOT Egress,

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 

Rating: R-50


Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

Top Glass: Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB, Strength: Annealed Glass

Bottom Glass: Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB, Strength: Annealed Glass

Overall Rating: DP-50

9 FF rear porch 1 EA Quaker Unit \$782.02 \$782.02



\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 34 3/8 X 71 1/4 Outer Perimeter: 37 3/8 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass: EnergyNorth (180+4th Surface), Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior: Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. CasingBrckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 3/8 X 71 1/4, Meets Egress

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 


Rating: R-50

Energy Star: Yes, Climate Zone:North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Overall Rating: DP-50

10 FF right rear 1 EA Quaker Unit \$782.02 \$782.02



\*\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 34 3/8 X 71 1/4 Outer Perimeter: 37 3/8 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. CasingBrckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 3/8 X 71 1/4, Meets Egress

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43

Rating: R-50


Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Printed On: 9/29/2021 9:12 AM Page **5** of **9** 

## Overall Rating: DP-50

11 FF right stairs 1 EA Quaker Unit \$823.15 \$823.15



Series: Brighton

Exact Size: 34 3/8 X 71 1/4 Outer Perimeter: 37 3/8 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish, Glass:EnergyNorth (180+4th Surface),Tempered,Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior: Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. CasingBrckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 3/8 X 71 1/4, Meets Egress

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Tempered Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Tempered Glass

Overall Rating: DP-50

12 2 flr ftr. bay 1 EA Quaker Unit \$781.13 \$781.13



\*\* Viewed From Exterior \*\*

Series: Brighton

**Exact Size:** 34 1/4 X 71 1/4 **Outer Perimeter:** 37 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. CasingBrckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609,Factory Apply Ext Subsill: Yes, Perimeter Acc Color:Black,

Unit:1-Double Hung No Plough Exact Size: 34 1/4 X 71 1/4, Meets Egress

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43

Rating: R-50


Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

**Overall Rating: DP-50** 

13 2 flr frt bay 2 EA Quaker Unit \$737.66 \$1,475.31

Printed On: 9/29/2021 9:12 AM Page **6** of **9** 



\*\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 28 1/4 X 71 1/4 Outer Perimeter: 31 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass: EnergyNorth (180+4th Surface), Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 49/16" Jamb Depth, Ext. CasingBrckmld 15/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 28 1/4 X 71 1/4, NOT Egress,

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

Overall Rating: DP-50

14 2 fir front 1 EA Quaker Unit \$781.13 \$781.13



\* Viewed From Exterior \*\*

Series: Brighton

Exact Size: 34 1/4 X 71 1/4 Outer Perimeter: 37 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc: No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. Casing Brckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 1/4 X 71 1/4, Meets Egress

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 

Rating: R-50


Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

Top Glass: Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB, Strength: Annealed Glass

Bottom Glass: Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB, Strength: Annealed Glass

Overall Rating: DP-50

15 2 flr left bath 1 EA Quaker Unit \$621.62 \$621.62



Series: Brighton

Exact Size: 24 1/4 X 47 1/4 Outer Perimeter: 27 1/4 X 49 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish, Glass:EnergyNorth (180+4th Surface),Tempered,Argon Filled,

Hardware:Gold,Sash:Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior:Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc:No Nailing Fin, Depth:4 9/16" Jamb Depth, Ext. CasingBrckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Printed On: 9/29/2021 9:12 AM Page **7** of **9** 

Unit:1-Double Hung No Plough Exact Size: 24 1/4 X 47 1/4, NOT Egress,

NFRC - U-Factor:0.28SHGC:0.43VT:0.53AL:≤0.3CR:43


Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Tempered Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Tempered Glass

Overall Rating: DP-50

16 2 flr rear bedr 2 EA Quaker Unit \$781.13 \$1,562.26



Series: Brighton

**Exact Size:** 34 1/4 X 71 1/4 **Outer Perimeter:** 37 1/4 X 73 3/8

Color:Black,Paint Type:2604,Interior Finish:Natural Finish,

Glass:EnergyNorth (180+4th Surface),Argon Filled,

Hardware: Gold, Sash: Sweep Lock,

Jamb Liner:Beige, Jamb Liner Cover Exterior: Yes,

Screen:Full Screen, Material: Better Vue (TM), Ship: Screen With Product,

Install Acc:No Nailing Fin, Depth: 4 9/16" Jamb Depth, Ext. CasingBrckmld 1 5/8" No Fin, Factory Apply Ext Casing: Yes, Ext.

SubsillSillnose 5/8" 17609, Factory Apply Ext Subsill: Yes, Perimeter Acc Color: Black,

Unit:1-Double Hung No Plough Exact Size: 34 1/4 X 71 1/4, Meets Egress

 $\textbf{NFRC-U-Factor:} 0.28 \textbf{SHGC:} 0.43 \textbf{VT:} 0.53 \textbf{AL:} \leq 0.3 \textbf{CR:} 43$ 

Rating: R-50

Energy Star: Yes, Climate Zone: North, Zip Code: 48342,

**Top Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass **Bottom Glass:**Cardinal LowE 180 - DSB / Cardinal LowE i89 - DSB,**Strength:**Annealed Glass

**Overall Rating: DP-50** 

All Prices in USD	Quote Subtotal	\$15,051.57	
	Тах	6.000 %	\$903.09
	Total Quote Value		\$15,954.67

Quote Grand Total

(may be subject to sales tax)

\$15,954.67

**Quote Name:** 

#### Quote #:

#### Terms:

- This quote is based on the products as listed. Customer must review quote and verify quantities, sizes, types, finishes, glazing, and adherence to specifications and job requirements and any relevant local or national codes.
- All prices are subject to change at any time if quantities, product, or other terms and conditions that are not part of the original quotation change or if the buyer requests extended delivery dates.
- This quote is an offer by Quaker Window Products Co. ("Quaker"), a Missouri corporation, to sell to the Customer the products described herein at the prices indicated, subject to the terms and conditions stated in this document, including the referenced Quaker warranty and the limitations of liability described therein. Unless otherwise agreed, this offer shall expire after the quote availability date listed on the quote. In order to accept such offer, and before Quaker begins to fabricate such products, Customer must:
  - Review and approve this quote;
  - Provide any additional details or information Quaker requires regarding the job or the Customer;
  - 3. If applicable, complete and submit a credit application subject to approval by Quaker's credit department; and
  - If applicable, submit approved Shop Drawings which are incorporated into the order.
- Quaker's entry of a sales order will serve to acknowledge completion of these steps. Any purchase order or other document that Customer may use to indicate acceptance of this quote, shall be considered for Customer's internal purposes only, and notwithstanding any language to the contrary in any such document, any resulting order shall remain subject to the governing terms and conditions stated in this quote. Quaker expressly objects to, and does not accept, any conflicting, modified, or additional terms or conditions proposed by Customer unless such proposed terms and conditions are specifically approved in writing by Quaker's credit department, legal counsel, or an appropriate officer of the company.
- TAXES: Unless otherwise indicated, sales or use taxes are not included in this quote. It shall be Customer's responsibility to ensure payment of any applicable state or local sales or use or other taxes, and Customer shall indemnify Quaker against any claimed failure to pay such taxes when due.
- Any lead times provided are estimates only. An estimated delivery date will be established by Quaker and communicated to Customer once the sales order is entered.
- If you request any change to your order after placing your order, then you will be responsible for any actual or reasonably estimated costs incurred by Quaker in processing such change, and Quaker may require submittal of a change order documenting the requested changes.
- WARRANTY: The sale of the quoted products is subject to Quaker's Limited Warranty for Single-Family Dwellings dated 4/1/2019, which contains the relevant manufacturer's warranty and various limitations of liability, is hereby incorporated by reference, and is available at www.quakerwindows.com/ warranty-information/. Customer will provide this warranty to the end user as appropriate.
- Undeliverable Product Storage Fee: If Customer is not willing or able to accept delivery of an order that is ready for shipment, then for any delivery delayed by more than 14 calendar days from the estimated delivery date, an undeliverable product storage fee of \$350 per trailer per week will be added to the order, which may be invoiced at that time.
- Delivery & Detainage Fee: Customer is responsible for inspecting and unloading products associated with this order upon delivery. If offloading time is excessive, then Customer will be responsible for payment of detention fees in the amount of \$150 per hour. If Customer's inspection reveals products damaged during shipment, such damage should be photographed at the time of delivery, and must be documented on the delivery ticket.
- Product rating information: Individual units greater than gateway size may have a reduced rating per Quaker's calculations based on AAMA 2502-07 Comparative Analysis Procedure for Window and Door Products. Overall Design Pressure of mulls/assemblies may be less than the computed values of individual units per Quaker's calculations based on AAMA 450-10 Voluntary Performance Rating Method for Mulled Fenestration Assemblies. Thermal ratings are based on NFRC test size.
- Any vertical or horizontal mulling system is designed for lateral wind loading only and does not provide structural down loading. Headers must be sized to allow for a maximum deflection of 1/8 of an inch. Please consult an architect or engineer for design requirements and building code compliance when combining multiple units together.
- FIELD TESTING: In order to be warranted for performance by Quaker, any field testing of QUAKER products must be conducted as specified in the abovedescribed warranty.
- PRICE ADJUSTMENT: Quaker reserves the right to adjust the pricing described in this quote, or impose an additional surcharge, in the event of any extraordinary increase in any of its costs associated with manufacturing, supplying, or distributing the quoted products after the date of this quote, whether or not such increase arises out of an event of force majeure or a failure of presupposed conditions, upon notice to the Customer at any time prior to Quaker's entry of Customer's order regarding the adjustment or surcharge necessary to defray such increases.
- FORCE MAJEURE: Quaker will not be liable for any nonperformance, delay in performance, or damage that results from any cause beyond Quaker's reasonable control, including, without limitation, any: Act of God; act of the Customer; restraint of government, such as embargo or other trade restrictions or governmental regulations or demands (whether or not later proven to be invalid); fire; flood; accident; strike or other labor disturbance; machinery or equipment breakdown; plant shutdown or slowdown; war; riot; terrorist act; delay in transportation; delays of suppliers or carriers; or inability to obtain necessary labor, materials or manufacturing facilities at customary prices ("Force Majeure Events").

Printed On: 9/29/2021 9:12 AM Page 9 of 9