

**DETROIT HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH & SAFETY
FIELD INVESTIGATION REPORT**

RESIDENT/BUSINESS NAME: Osborn High School

ADDRESS: 11600 East Seven Mile Rd, Detroit, MI 48205

COMPLAINANT: Follow-up Review

TYPE OF INVESTIGATION:

Air Quality	_____	Hazardous Waste	_____
Environmental	_____	Solid Waste	_____

OTHER:

NATURE OF COMPLAINT: Detroit Public Schools-potential health-related violations observed by BSEED inspectors.

Date of follow-up review: 04/26/2016

INVESTIGATION SUMMARY: The Detroit Health Department, Office of Environmental Health and Safety has completed a review of violations for Osborn High School.

Summary:

All initial violations cited on January 12th 2016 for this location have been remediated with **one exception.**

1. Repair/replace roof areas cited in the 3rd party roof inspection report.

DHD has been notified that "*Roof repairs are on-going in areas not replaced*". An extended deadline of **June 30th 2016** has been granted to DPS in regards to the completion of the above remaining repair/modification required at Osborn High School.

CONDUCTED BY: Detroit Health Department – Environmental Team **DATE:** 04/26/2016

ROUTINE	Phone COMPLAINT	REFERRAL √
---------	-----------------	---------------