
## Rotted Exterior of Windows







## Window Damage

(Note: Structural damage. Vertical stabilizers were added to keep the windows from collapsing into the building because of rotted wood collapsing on itself)

