

Request/Reason: Replace rear window on 1504 Longfellow St. to allow more light into kitchen, better view of backyard (for safety of kids playing), and to match the rest of the house

Images of 1504 Longfellow:



Window to be replaced:



Existing Condition:

- 26"x36" double hung wood window with vinyl clad exterior
- Vinyl exterior painted to match house trim

Scope of work:

- Replace with two, side-by-side Anderson 400 series window
- Window will be wood with vinyl clad exterior
- Interior will be white. Exterior (including grilles) will be brown
- Each window will be 32"x57", total will be 70"x57" (6" space between windows mimicking front upper left window)
- Upper pane on each window will have colonial style grilles
- Image of replacement window:

