

Description of Existing Conditions @ 3546 Burns St
Parcel # 17006202

Over the summer, on two separate occasions, cars smashed through 3 sections of our 6' high cedar fence. Further, large sections of the fence have seen a lot of wear and tear since it was erected years prior to our purchasing the lot.

Description of Project @ 3546 Burns St

Since large sections of the fence were destroyed by hit and run events car crashes, and other sections face wear and tear from use over time, we want to replace the existing fence with a new fence of the same size and material (6', cedar)

Detailed Scope of work @ 3546 Burns St

- Replace wood
- Cut old poles at or below grade
- Replace with approximately 374' of 6' high treated dog eared flat board style fence on posts.