Description of Window Installment 12142 Broadstreet Ave, Detroit, MI 48204

- Property current does not have any windows to repair.
- Window coverings will be removed area prepped and cleaned for pocket installation of windows current window frames in good usable condition
- Install 7 total windows in front (west side facing Broadstreet) of property 3 lower level 4 upper level all front windows will be double hung, white, aluminum clad wood windows with a colonial grid pattern on top sash, no grid pattern on bottom sash in front upstairs and downstairs windows of home.
- Install 11 side and rear windows with white double hung, vinyl windows
- Intall 3 vinyl casement windows 2 on the North side of property next to the fireplace and 1 on the East side of the property at the threshold of the first floor stairwell.