





VIEW LOOKING NORTH




VIEW LOOKING NORTH



VIEW LOOKING SOUTHWEST PROPOSED BUMP OUT PATIOS



VIEW LOOKING SOUTHWEST




INTERIOR VIEW OF DINING ROOM



INTERIOR VIEW OF BAR



INTERIOR VIEW OF BAR ROOM



INTERIOR VIEW OF DINING



INTERIOR VIEW OF KITCHEN BAR



INTERIOR VIEW OF DINING ROOM




INTERIOR VIEW OF DINING ROOM




INTERIOR VIEW OF BASEMENT LOBBY



INTERIOR VIEW OF BASEMENT BAR ROOM



INTERIOR VIEW OF BASEMENT BAR ROOM



Issue Date:	
PERMIT	1/12/202

Sheet Title:

EXISTING CONDITIONS PHOTOS

Sheet Number:

G103