

A photograph of a roof with a missing slate. A yellow hand-drawn circle highlights a section of the roof. A blue rounded rectangle contains the text "missing slate". Three red arrows point to specific areas on the roof: one points to a gap in the shingles, another points to a white vent pipe, and a third points to a dark stain on the roof surface.

missing slate