
FRONT/EAST ELEVATION

NOTE DECORATIVE STONE TRIM/DETAILING AT ALL ELEVATIONS





ORIGINAL VERTICAL
PLANK WOOD DOORS,
EACH WITH LEADED
GLASS VISION PANEL



SIDE/SOUTH ELEVATION (SIMILAR CONDITIONS AT SIDE/NORTH ELEVATION)






ORIGINAL STEEL CASEMENT AND TRANSOM WITH STAINED GLASS PANES (W/LEAD CAMING)

ORIGINAL FIXED STEEL WINDOWS AND TRANSOMS WITH STAINED GLASS PANES (WAYEAD CAMING)



ORIGINAL STEEL CASEMENT AND TRANSOM WITH POST-1981, COLORED GLASS PANES ORIGINAL FIXED STEEL WINDOWS AND TRANSOMS WITH STAINED GLASS PANES (W/LEAD CAMING)



POST- 1981, COLORED GLASS PANES

SIDE/SOUTHWEST ELEVATION (ONE STORY, FLAT-ROOF WING)



GLASS BLOCK WINDOW INSTALLED IN 2023 W/OUT HDC APPROVAL


REAR/WEST ELEVATION



SIDE/NORTH ELEVATION (REAR)



SIDE/NORTH ELEVATION (SIMILAR TO CONDITIONS AT SIDE/SOUTH ELEVATION)



ORIGINAL STEEL CASEMENT WITH STEEL FIXED WINDOWS AND TRANSOM, WITH ORIGINAL STAINTED GLASS PANES AND POST- 1981, COLORED GLASS

ORIGINAL STEEL CASEMENT WITH STEEL TRANSOM, WITH ORIGINAL STAINTED GLASS PANES. WINDOW TO RIGHT IS MISSING

ROOF



GABLED AND HIPPED ROOF WITH ASPHALT SHINGES (INSTALLED IN 2023)

SITE CONDITIONS (REAR YARD)



SITE CONDITIONS (NORTH/SIDE AND FRONT YARDS)



SITE CONDITIONS (SOUTH/SIDE YARD)



SITE CONDITIONS (SOUTH/SIDE YARD)

