



A: The wing wall is leaning to the left due to improper footing.



B: Column and wing wall are separating and shifting due to improper footing.



C: The porch wall has dropped down due to footing movement.



Step Crack



D: The brick column twisted and moved due to footing shifting. Step Crack



E: The porch deck needs to be replaced due to all of the movement that took place with the footing.