
Project Review Request Checklist (2066 ATK)

Address: 2066 Atkinson Detroit Michigan

Photographs (1 and 2):





Description of Existing Condition (3):

- Exterior house painting (trim and siding only)

Scope of Work (4): All work has been Completed

- Repair rotted wood
- Prep for paint
- Caulk
- Install paint on siding
- Install paint on trim

Description of Project (5):

- Replacement of water damaged wood
- Exterior paint

Brochure/cut sheets:

- NA new materials (work completed)
- SW Salty Dog 9177 (used)
- Sw Urban Putty 7532 (used)