



1. Exterior, West Elevation, Looking East. c. 2022.

Merchants Building



2. Exterior, North elevation, Looking southwest. c. 2022.

Merchants Building




3. Exterior, South elevation, Looking northeast. c. 2022.

Merchants Building



4. Exterior, East elevation, Looking northwest. c. 2022.

Merchants Building



5. Exterior, East elevation, Detail of Existing Fire Escape, Looking northwest. 4/17/23.

Merchants Building



6. Exterior, Detail of Existing Fire Escape, Looking west. 4/17/23.



7. Exterior, North Elevation, Typical spandrel panel condition. 4/5/23.

Merchants Building