


# Proposed Design for the **SEYBURN INN**

7810 Kercheval Avenue Detroit Michigan


HISTORICAL DISTRICT COMMISSION PROJECT REVIEW





## HOUSE DETAILED PHOTOS

INDICATES AREA OF WORK/CONSTRUCTION



MASONRY CHIMNEY

Fascia ,soffit, and trim board — -DETERIORATING WOOD -CHIPPING PAINT

SOLIDER COURSE -

BOARDED UP CURVED WINDOWS -

LIMESTONE SILL -

BRICK VENEER -

MISSING SIDE ENTRY PORCH -



EXISTING PERSPECTIVE SOUTH



EXISTING PERSPECTIVE EAST




EXISTING PERSPECTIVE SOUTHEAST



## EXISTING PERSPECTIVE NORTHEAST

- HIPPED DORMER WITH COMPROMISED FRAMING
- HIPPED ROOF WITH COMPROMISED FRAMING
- OUTDATED SATELLITE DISH
- BOARDED UP WINDOW
- FASCIA ,SOFFIT, AND TRIM BOARD -DETERIORATING WOOD -CHIPPING PAINT
- INFILLED SCREEN PANELS
- MASONRY COLUMNS
- MASONRY PORCH
- CONCRETE PORCH STEPS



OWNER, CONTRACTOR AND ARCHITECT

DRAWN BY: MML CHECKED BY: *TJM* 

- SHEET NO. -





# ACCESSORY STRUCTURE DETAILED PHOTOS

INDICATES AREA OF WORK/CONSTRUCTION



EXISTING PERSPECTIVE EAST

STEEL BRACKETS -SOILDER COURSE TRIM -LIMESTONE VENEER boarded up storefront —


BILLBOARD —



# EXISTING PERSPECTIVE SOUTHEAST

LOACTION OF NEW MASONRY OPENING -

# EXISTING PERSPECTIVE SOUTHEAST




#### DESCRIPTION OF EXISTING CONDITIONS:

-THE EXISTING CONDITIONS OF THE ORIGINAL BRICK HOUSE INDICATE SIGNIFICANT DETERIORATION BOTH INSIDE AND OUT, WITH THE MASONRY SHOWING SIGNS OF CRACKING AND DETERIORATION IN MANY AREAS. IN ADDITION TO MISSING A SIDE ENTRYWAY, ALL OF THE WINDOWS ARE DETERIORATING OR BOARDED UP, WHICH LIMITS NATURAL LIGHT AND CREATES AN UNATTRACTIVE APPEARANCE.

-THE COMMERCIAL SPACE BEHIND THE HOUSE IS ALSO IN A STATE OF DISREPAIR, WITH BOARDED UP STOREFRONTS AND CRACKING MASONRY. DEBRIS ON THE ROOF FURTHER COMPROMISES ITS STRUCTURAL INTEGRITY AND CREATES SAFETY HAZARDS.

EXISTING STEEL SIGN BRACKETS EXISTING STEEL SIGN BRACKETS MASONRY VENEER

EXISTING STOREFRONT WALLS



# EXISITING PERSPECTIVE SOUTHWEST





# EXISITING PERSPECTIVE SOUTH

HIPPED ROOF DORMER WITH - COMPROMISED FRAMING - DETERIORATING SHINGLE SHAKE HIPPED ROOF WITH -COMPROMISED FRAMING MISMATCHING WINDOW OUTDATED SATELLITE DISH

FASCIA ,SOFFIT, AND TRIM BOARD -DETERIORATING WOOD -CHIPPING PAINT

NON HISTORICAL SCREENED PORCH

CONCRETE STEPS WITH METAL GUARD RAIL

FASCIA ,SOFFIT, AND TRIM BOARD -DETERIORATING WOOD -CHIPPING PAINT

WINDOWS INFILLED WITH WOOD PANELS

DETERIORATING ADDITION

TELEPHONE 313.571.3385 PROJECT SEYBURN-INN 7810 KERCHEVAL AVE DETROIT, MI, 48214 ISSUED DATE FOR


OWNER, CONTRACTOR AND ARCHITECT


H


HOLCOMB

DEVELOPMENT

656 ST. CLAIR STREET GROSSE POINTE, MI 48230







EXISTING DORMER FRONT ELEVATION

	OWNER, CONTRACTOR AND ARCHITECT
	H
	656 ST. CLAIR STREET GROSSE POINTE, MI 48230 TELEPHONE 313.571.3385
	PROJECT
	SEYBURN-INN
	7810 KERCHEVAL AVE DETROIT, MI, 48214
	ISSUED DATE FOR
	SCHEMATIC DESIGN         01/27/2023           HDC PRE-REVIEW         03/30/2023           HDC SUBMISSION         11/20/2023
٥	
2 <sup>3</sup> / <sub>2</sub>	
	DRAWING TITLE
2'-10"	EXISTING CONDITIONS DORMER
	PROJECT NO: DRAWN BY: <i>MML</i> CHECKED BY: <i>TJM</i> - SHEET NO
_	A104



周新

a series of the second s

ENTRY DOOR AND CAGE TO BE \_\_\_\_

HISTORICAL SIDE LIGHT TO BE REPAIRED -REMOVE METAL CAGE





ENTRY DOOR TO BE REMOVED -

REPAIR HISTORICAL SIDE LIGHT — -REPAIR SIDE LIGHT JAMB, SILL, AND PANEL




























A105



**TRANSOM TRIM DETAIL** 






STOREFRONT EXISTING SECTION



INTERIROR VIEW OF TRANSOM

**EXISTING BOARDED UP STORE FRONT** 











#### RENDERING WEST ON KERCHEVAL AVENUE


OWNER, CONTRACTOR AND ARCHITECT
HOLCOMB
development 656 ST. CLAIR STREET
GROSSE POINTE, MI 48230 TELEPHONE 313.571.3385
PROJECT
SEYBURN-INN
7810 KERCHEVAL AVE DETROIT, MI, 48214
ISSUED DATE FOR
SCHEMATIC DESIGN         01/27/2023           HDC PRE-REVIEW         03/30/2023           HDC SUBMISSION         11/20/2023
DRAWING TITLE
PROPOSED RENDERING
PROJECT NO: DRAWN BY: <i>MML</i>
CHECKED BY: TJM - SHEET NO
A201



# BASEMENT FLOOR PLAN SCALE: 1/4"=1'-0"



FIRST FLOOR PLAN SCALE: 1/4"=1'-0"



#### SYMBOL LEGEND

INDICATES NEW WOOD FRAMED WALL CONSTRUCTION TO REMAIN INDICATES EXISTING WOOD FRAMED WALL CONSTRUCTION TO REMAIN INDICATES EXISTING EXTERIOR WALL CONSTRUCTION TO REMAIN

INDICATES EXISTING BRICK VENEER TO REMAIN INDICATES NEW BRICK VENEER

/////////// INDICATES EXISTING WALLS TO BE REMOVED

INDICATES EXISTING DOORS TO BE REMOVED

INDICATES EXISTING WINDOWS TO BE REMOVED

#### INDICATES EXISTING COMPONENT TO BE REMOVED



INDICATES EXISTING AREA TO BE REMOVED

PROJECT

OWNER, CONTRACTOR AND ARCHITECT

Н

HOLCOMB

DEVELOPMENT

656 ST. CLAIR STREET GROSSE POINTE, MI 48230

TELEPHONE 313.571.3385

#### SEYBURN-INN

7810 KERCHEVAL AVE DETROIT, MI, 48214

DATE ISSUED FOR

SCHEMATIC DESIGN 01/27/2023 HDC PRE-REVIEW 03/30/2023 11/20/2023 HDC SUBMISSION

DRAWING TITLE

FLOOR PLANS

PROJECT NO: DRAWN BY: MML CHECKED BY: TJM


- SHEET NO. -




# SECOND FLOOR PLAN

SCALE: 1/4"=1'-0"

#### THIRD FLOOR PLAN SCALE: 1/4"=1'-0"





#### PROJECT

owner, contractor AND Architect

H

HOLCOMB DEVELOPMENT

656 ST. CLAIR STREET GROSSE POINTE, MI 48230 TELEPHONE 313.571.3385

#### SEYBURN-INN

#### SYMBOL LEGEND

	INDICATES
	INDICATES
	INDICATES
[]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]	INDICATES
	INDICATES
7//////////////////////////////////////	INDICATES
	INDICATES

S NEW WOOD FRAMED WALL CONSTRUCTION TO REMAIN S EXISTING WOOD FRAMED WALL CONSTRUCTION TO REMAIN S EXISTING EXTERIOR WALL CONSTRUCTION TO REMAIN S EXISTING BRICK VENEER TO REMAIN S NEW BRICK VENEER

S EXISTING WALLS TO BE REMOVED

S EXISTING DOORS TO BE REMOVED

INDICATES EXISTING WINDOWS TO BE REMOVED

Í

#### INDICATES EXISTING COMPONENT TO BE REMOVED



INDICATES EXISTING AREA TO BE REMOVED

7810 KERCHEVAL AVE DETROIT, MI, 48214 ISSUED DATE FOR SCHEMATIC DESIGN 01/27/2023 HDC PRE-REVIEW 03/30/2023 HDC SUBMISSION 11/20/2023 DRAWING TITLE FLOOR PLANS

PROJECT NO: DRAWN BY: MML

CHECKED BY: TJM


- SHEET NO. -

A301

#### ROOF PLAN SCALE: 1/4"=1'-0"

ENLARGED DORMER -DEMO EXISTING FRAMING AND RE-FRAME LARGER DORMER -FASCIA, TRIM , SOFFIT BOARD TO MATCH EXISTING DORMERS -REFRENCE SECTION (B/A500)

ROOF PERSPECTIVE





	OWNER, CONTRACTOR AND ARCHITECT
	H
	656 ST. CLAIR STREET GROSSE POINTE, MI 48230 TELEPHONE 313.571.3385
SYMBOL LEGEND	
INDICATES NEW WOOD FRAMED WALL CONSTRUCTION TO REMAIN	
INDICATES EXISTING EXTERIOR WALL CONSTRUCTION TO REMAIN	
INDICATES EXISTING BRICK VENEER TO REMAIN	
INDICATES NEW BRICK VENEER	
INDICATES EXISTING WALLS TO BE REMOVED	
INDICATES EXISTING DOORS TO BE REMOVED	
INDICATES EXISTING WINDOWS TO BE REMOVED	
INDICATES EXISTING COMPONENT TO BE REMOVED	PROJECT
INDICATES EXISTING AREA TO BE REMOVED	
	SEYBURN-INN
<ul> <li>NEW DORMER</li> <li>-WINDOWS,CORNICE,PANELS TO MATCH EXISTIN DORMERS</li> <li>-REFRENCE SECTION (A/A500)</li> </ul>	7810 KERCHEVAL AVE DETROIT, MI, 48214
	ISSUED DATE FOR
	SCHEMATIC DESIGN 01/27/2023

SCHEMATIC DESIGN	01/27/2023								
HDC PRE-REVIEW	03/30/2023								
HDC SUBMISSION	11/20/2023								
DRAWING TITLE									
FLOOR PLANS									
PROJECT NO:									
DRAWN BY: <i>MML</i>									
CHECKED BY: TJM									

- Sheet NO. -







#### **RIGHT ELEVATION**

-CONCRETE TOP		

#### WINDOW SCHEDULE - BASEMENT

MARK	OPERATION	BRAND	SIZE (WIDTH X HEIGHT)	QTY.	ROUGH OPENING	MASONRY OPENING	MATERIALS	EXTERIOR COLOR	INTERIOR COLOR	HARDWARE FINISH	REMARKS
$\bigcirc$	AWNING	-	36" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
B	AWNING	-	42" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
Ô	AWNING	-	42" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
0	AWNING	-	42" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
E	AWNING	-	38" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
F	AWNING	-	38" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
G	AWNING	-	38" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
θ	AWNING	-	38" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
						MASONRY INF	ILL			•	
$\bigcirc$						MASONRY INF					

#### 

IARK	OPERATION	BRAND	SIZE (WIDTH X HEIGHT)	QTY.	ROUGH OPENING	MASONRY OPENING	MATERIALS	EXTERIOR COLOR	INTERIOR COLOR	HARDWARE FINISH	REMARKS
K		Į				MASONRY INF	ILL	<u> </u>		II	
	DOUBLE HUNG	-	22" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
M	DOUBLE HUNG	-	34" x 68"	2	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\mathbb{N}$	DOUBLE HUNG	-	22" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
0	DOUBLE HUNG	-	46" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
P	DOUBLE HUNG	-	42" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
0	DOUBLE HUNG	-	42" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
R	DOUBLE HUNG	-	42" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
S	FIXED	-	42" x 28"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\bigcirc$	DOUBLE HUNG	-	22" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\bigcirc$	DOUBLE HUNG	-	38" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\heartsuit$	DOUBLE HUNG	-	22" x 68"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\odot$	PUSH-OUT CASEMENT	-	26" x 34"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\otimes$	PUSH-OUT CASEMENT	-	26" x 34"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
$\odot$	DOUBLE HUNG	-	26" x 54"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
Ż	DOUBLE HUNG	-	32" x 54"	1	FIELD VERIFY	FIELD VERIFY	STEEL EXTERIOR/ STEEL INTERIOR	WHITE	WHITE	MATCH EXISTING	
AA	DOUBLE HUNG	-	32" x 54"	1	FIELD VERIFY	FIELD VERIFY	STEEL EXTERIOR/ STEEL INTERIOR	WHITE	WHITE	MATCH EXISTING	
BB		*	-	•		MASONRY INF	= FILL	*	-	• • •	

MARK	OPERATION	BRAND	SIZE (WIDTH X HEIGHT)	QTY.	ROUGH OPENING	MASONRY OPENING	MATERIALS	EXTERIOR COLOR	INTERIOR COLOR	HARDWARE FINISH	REMARKS
Ô	DOUBLE HUNG	-	32" x 62"	1	FIELD VERIFY	FIELD VERIFY	FIELD VERIFY WOOD EXTERIOR/ WOOD INTERIOR		WHITE	MATCH EXISTING	
Ō	SINGLE HUNG	-	32" x 32"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR/	WHITE	WHITE	MATCH EXISTING	
Ē	DOUBLE HUNG	-	36" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
(FF)	DOUBLE HUNG	-	36" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
G	DOUBLE HUNG	-	36" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
	CASEMENT	-	24" x 48"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
	DOUBLE HUNG	-	44" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
IJ	DOUBLE HUNG	-	32" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
(KK)	DOUBLE HUNG	-	32" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
	DOUBLE HUNG	-	32" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
MM	DOUBLE HUNG	-	32" x 62"	1	FIELD VERIFY	FIELD VERIFY	WOOD EXTERIOR/ WOOD INTERIOR	WHITE	WHITE	MATCH EXISTING	
WIND	OW SCHEDULE -	THIRD F					•				
MARK	OPERATION	BRAND	SIZE (WIDTH X HEIGHT)	QTY.	ROUGH OPENING	MASONRY OPENING	MATERIALS	EXTERIOR COLOR	INTERIOR COLOR	HARDWARE FINISH	REMARKS
ND	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	
	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD INTERIOR WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	
P	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD INTERIOR WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	
	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD INTERIOR WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	
R	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD INTERIOR WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	
<u>S</u>	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD INTERIOR WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	
	PUSH-IN CASEMENT		34 x 34"	1	FIELD VERIFY		WOOD INTERIOR WOOD EXTERIOR/	WHITE	WHITE	MATCH EXISTING	NEW SEE PAGE A601
			01201	· ·			WOOD INTERIOR				

WHITE WHITE MATCH EXISTING

NEW SEE PAGE A601

WIND	WINDOW SCHEDULE - THIRD FLOOR											
MARK	OPERATION	BRAND	SIZE (WIDTH X HEIGHT)	MASONRY OPENING	MATERIALS							
$\mathbb{N}$	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
$\odot$	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
PP	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
0	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
RR	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
S	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					
	PUSH-IN CASEMENT	-	34 x 34"	1	FIELD VERIFY	-	WOOD EXTERIOR/ WOOD INTERIOR					

# -REFER TO DORMER "B" ON A500

-NEW DORMER

- REPAIR EXISTING ROOF AS NEEDED


— 6" ALUMINUM K STYLE GUTTER -REPLACE IF NEEDED -MATCH EXISTING

- REPAIR CORNICE AS NEEDED -MILLWORK TO MATCH EXISTING SIZE AND FINISH

- EXISTING BRICK. REPAIRED AND/OR REPLACED - EXISTING PORCH ROOF REPAIR AS NEEEDED — 6" ALUMINUM K STYLE GUTTER -REPLACE IF NEEDED -MATCH EXISTING


- REPAIR CORNICE AS NEEDED -PAINTED WHITE TO MATCH EXISTING

-NEW CUSTOM FRONT DOOR TO MATCH EXISTING SIDE LITES (REFER TO PAGE (A601) 





#### LEFT ELEVATION



#### **RIGHT ELEVATION**





#### - Existing Dormer -Repair as Needed -REFER TO A104


- REPAIR CORNICE AS NEEDED


- EXISTING DOOR TO BE FULL RESTORED

# 









PARTING STOP SASH AREA


11/2'


SASH AREA


1" INNER STOP 1<sup>3</sup>⁄16"

BLIND STOP INNER STOP


(PLAN VIEW)






















NEW WOOD CASEMENT WINDOW CONSTRUCTION TO USE EXISTING MULTI-LITE SASH PROFILE

NEW WOOD MULI-LITE SASH CASEMENT WINDOW







# ARCHITECTURAL SITE PLAN

