

Condition of Window 1-6: Interior and Exterior





Window 1-6 are in deteriorated condition and boarded up.

Propose the replacement of the windows:

Window \$1-6 with Andersen (Wood /aluminum) suitable for historical property.

Proposed trim color:

A:2 Light Olive Gray (MS: 10Y/1)



A:2 Light Olive Gray
MS: 10Y 6/1