

Property Address: 4750 Cortland St, Detroit, MI

Scope of work:

- Replace windows with **Anderson** aluminium windows.
- **Front side: Window #1-6**

Window #7-8

WINDOW LOCATION	WINDOW SIZES	Clad	Operation
Window 1	28" x 46"	Aluminium	Single hung
Window 2	60" x 48"	Aluminium	Single hung
Window 3	28" x 46"	Aluminium	Single hung
Window 4	28" x 46"	Aluminium	Single hung
Window 5	60" x 48"	Aluminium	Single hung
Window 6	28" x 46"	Aluminium	Single hung
Window 7	24" x 24"	Aluminium	Single hung
Window 8	24" x 24"	Aluminium	Single hung

- **North East Window #9-12**

WINDOW LOCATION	WINDOW SIZES	Clad	Operation
Window 9	3@ 32" x 45"	Aluminium	Single hung
Window 10	2@ 32" x 45"	Aluminium	Single hung
Window 11	3 @32" x 45"	Aluminium	Single hung
Window 12	3@ 32" x 45"	Aluminium	Single hung

- All windows are to be manufactured with simulated divided light.

FRONT SIDE:



NORTHEAST SIDE:



Window 1-8







Window 1-8 are in deteriorated condition, broken glass, and boarded up.

Proposed installation of new windows:

Window 1-8 with Andersen (Wood /aluminum) suitable for historical property.

Proposed trim color:

A:2 Light Olive Gray (MS: 10Y/1)



A:2 Light Olive Gray
MS:10Y 6/1

Window 9 & 10



Window #9 and Window #10 are in boarded up. No windows.

Proposed installation of new windows:

Installation of new window installation with Andersen (Wood /aluminum) suitable for historical property.

Proposed trim color:

A:2 Light Olive Gray (MS: 10Y/1)



A:2 Light Olive Gray
MS: 10Y 6/1

Window 13

Retain as is – no window replacement.

Proposed changing of existing trim color: WHITE (to match the rest of the home)
to trim color **A:2 Light Olive Gray (MS: 10Y/1)**



A:2 Light Olive Gray
MS: 10Y 6/1

Window 14-25

Retain as is – no window replacement.

Proposed changing of existing trim color: WHITE
(to match the rest of the home)
to trim color **A:2 Light Olive Gray (MS: 10Y/1)**



A:2 Light Olive Gray
MS: 10Y6/1

