


Exterior Photos:

Homeowner: Gracie Brown	Project: 14686	Appointment Date: 3/24/25
Address: 1101 Chicago Boulevard Detroit, MI 48202 Technician: Jacob Lucius, repair and warranty manager		
tiles (stress/age cracks, exposed na	deteriorated flashings with ails, or severely chipped),	wet tiles. However, the inspection heavy tar patching, numerous failing and eroded mortar sealing the hip/ridge es, including direct sightlines into the
•	spots, including complete re to be viable; the entire r	,
Recommendations: Full roof replacement.		
Photos (If Applicable)		








































































































































































































































Interior Damage:



















