

## HISTORIC DISTRICT COMMISSION ADDITIONAL INFORMATION REQUEST

City of Detroit - Planning & Development Department 2 Woodward Avenue, Suite 808 Detroit, Michigan 48226

Date: 04/25/2025 Application Number: HDC2025-00208

# APPLICANT & PROPERTY INFORMATION NAME: Niall Berkery COMPANY NAME: Neumo ADDRESS: 1497 Pilgrim Avenue CITY: Birmingham STATE: MI ZIP: 48009 PROJECT ADDRESS: 8325 E Jefferson Ave HISTORIC DISTRICT: Indian Village

#### REQUESTED INFORMATION

We have received your application, but it is not yet complete for review. Please provide additional details based on the comments and questions listed below. Should you need to attach additional files per this request, use the paperclip icons at the end of this form. You may attach up to (5) files per icon up to 25MB:

This application is not completed. Please provide the following:

- Window schedule, which describes the existing windows material and operation & shows the proposed new windows, their material, operation, dimensions, and color
- Photos of the exterior elevations of the house with labels that show which windows on the window schedule are being placed where
- · Clarify if the window's frames, trim, sills, lintels, mullions, and/or brick mould will be kept in place, removed, or covered, and how
- Product information with the specific material, design, and colorway of the exterior light fixtures (screenshot of product information is OK, but website links are not)

Thank you!

PSR: 250425LS


APPLICANT RESPONSE	
Response Date: 05/06/2025	
All historic windows will be restored. None will be replaced.  See attached window schedule and plans.	

# Window Schedule


8325 E Jefferson Detroit MI 48214 All historic windows will be restored.

Windows #28 and #36 are not historic and will be left as-is


## **Front Side**




## **Left Side**



## **Right Side**



## **Rear Side**



## Front - Outside View



Kitchen		1st Floor Room 4	
2 <sup>nd</sup> Staircase	Hallway	Main	1st Floor
Bathroom		Staircase	Room 3
1st Floor		1# Floor	1st Floor
Room 1		Foyer	Room 2



### Rear – Outside View







## 6 Left - Outside View








## Right – Outside View






Kitchen		1st Floor Room 4	
2 <sup>nd</sup> Staircase	Hallway	Main	1st Floor
Bathroom		Staircase	Room 3
1st Floor		1 <sup>st</sup> Floor	1st Floor
Room 1		Foyer	Room 2

















































[14]





**(14**)





**(16**)















(18)












































Not historic window




































Not historic window